



Crow-Applegate-Lorane School District No. 66  
Educational Facility Master Plan & Facility  
Assessment  
June, 2016



**gLas**  
Architects, LLC

# Contents:

## Applegate Elementary:

- Master Plan
- Priority Options
- Assessment Cost Analysis

## Crow Middle School & High School:

- Master Plan
- Priority Options
- Assessment Cost Analysis

## Mechanical, Plumbing and Electrical Assessment:

# PLANNING FOR THE FUTURE

## SETTING PRIORITIES

### PRIORITY 1


1. SAFETY AND SECURITY UPGRADES, INCLUDING:
  - RELOCATE SCHOOL OFFICE TO PROVIDE A DIRECT VISUAL CONNECTION TO EVERYONE ENTERING THE FACILITY
  - CENTRALIZED MAGNETIC DOOR CONTROLS AND NEW EXTERIOR DOORS FOR LOCKDOWNS
  - ATTRACTIVE BUT SECURE FENCING TO IMPROVE PERIMETER SECURITY
  - UPDATED FIRE ALARM SYSTEM
  - NEW, MORE SECURE AND ADA COMPLIANT CLASSROOM DOOR HARDWARE
  - ADA IMPROVEMENTS FOR SAFE ACCESS FOR ALL STUDENTS

### PRIORITY 2

2. IMPROVEMENTS FOR ADEQUATE LEARNING SPACES INCLUDE:
  - CEILING MOUNTED INTEGRATED AV SYSTEMS TO FREE UP CLASSROOM SPACE
  - ADD DATA OUTLETS FOR BETTER COMPUTER ACCESS AT EACH CLASSROOM
3. RENEWAL AND REPLACEMENT OF VITAL BUILDING SYSTEMS, INCLUDING:
  - REMODEL STAFF AND STUDENT TOILET ROOMS
  - REMODEL EXISTING LOCKER ROOMS TO CREATE SEPARATE STORAGE, TEAM ROOMS AND TOILET ROOMS.
  - NEW HIGH EFFICIENCY HEATING AND VENTILATION EQUIPMENT IN CLASSROOMS AT THE GYMNASIUM
  - IMPROVED DRAINAGE AT BUS LOOP EXIT
  - RETROFIT EXISTING LIGHTING FOR IMPROVED ENERGY EFFICIENCY

### PRIORITY 2

1. PROVIDE WHEELCHAIR ACCESS FROM THE LOWER LEVEL TO THE UPPER LEVEL.
2. PROVIDE WHEEL CHAIR ACCESS TO THE CAFETERIA




## APPLEGATE ELEMENTARY SCHOOL MASTER SITE PLAN

CROW APPLEGATE LORANE SCHOOL DISTRICT


MAY 26, 2016







APPLEGATE ELEMENTARY SCHOOL  
**EXISTING SITE PLAN**

SCALE: 1" = 120'-0"






APPLEGATE ELEMENTARY SCHOOL  
EXISTING FLOOR PLAN



SCALE: 1" = 60'-0"

**PRIORITY I - ADDITIONAL IMPROVEMENTS**

1. PROVIDE LEVER HARDWARE
2. REROUTE DRAINAGE AT EAST DRIVE END
3. REPLACE CLASSROOM HVAC UNITS
4. INSTALL NEW TOILET ROOM EXHAUST FANS
5. INSTALL VENTILATION UNIT FOR GYM WITH HEAT RECOVERY
6. INSTALL AN ELECTRONIC HVAC CONTROL SYSTEM
7. SEISMICALLY BRACE BASEMENT WATER HEATER
8. REPLACE OLDER FIXTURES WITH NEW LOW FLOW TYPE
9. REPLACE OLDER INEFFICIENT FLUORESCENT FIXTURES
10. PROVIDE LOCAL OCCUPANCY SENSOR CONTROL TO OCCUPIED ROOMS AND SUPPORT SPACES
11. PROVIDE NEW DATA - 1 DROP PER CLASSROOM
12. INSTALL NEW MAGNETIC DOOR LOCKS FOR EXTERIOR DOORS
13. INSTALL NEW MANUAL FIRE ALARM/SPRINKLER MONITORING SYSTEM
14. INSTALL CEILING MOUNTED INTEGRATED AV SYSTEMS AT EACH CLASSROOM




**APPLEGATE ELEMENTARY SCHOOL  
FLOOR PLAN - PRIORITY I**

1  
A3

SCALE: 1" = 60'-0"





NEW ADA STAGE  
LIFT

NEW RAMP ACCESS  
AT MAIN HALL STAIR



NORTH

APPLEGATE ELEMENTARY SCHOOL  
FLOOR PLAN - PRIORITY 2


1  
A4

SCALE: 1" = 60'-0"

**gLas**  
Architects,  
LLC

PRIORITY 3 - ADDITIONAL IMPROVEMENTS

- 1. REPLACE DRINKING FOUNTAINS
- 2. MODIFY CLASSROOM SINK FAUCETS FOR ADA
- 3. SEISMIC RETROFIT (SCOPE TBD)



APPLEGATE ELEMENTARY SCHOOL  
FLOOR PLAN - PRIORITY 3



1  
A5

SCALE: 1" = 60'-0"



PRIORITY 5 - ADDITIONAL IMPROVEMENTS


1. NEW AUTOMATIC FIRE SUPPRESSION SYSTEM
2. INSULATE DOMESTIC WATER PIPING WHERE NEEDED
3. ABATE AND REPLACE ASBESTOS FLOOR TILE
4. UPGRADE SIDING
5. UPGRADE WINDOWS THROUGHOUT
6. UPGRADE CARPET THROUGHOUT
7. REPAIR AND RESURFACE GYM FLOOR
8. ADD DAYLITE IN CAFETERIA
9. REPAIR CEILING DAMAGE
10. ROOF REPAIRS
11. NEW ROOFTOP UNITS AT NON-VENTILATED CLASSROOMS
12. ELECTRICAL SERVICE UPGRADES
13. INSTALL NEW ASTRONOMICAL CLOCKS
14. INSTALL NEW EXHAUST FAN AT RANGE HOOD

REFURBISH EXISTING  
BLEACHERS


NEW RAMP ACCESS  
TO EAST WING  
CLASSROOMS

NEW 36" HIGH TRANSACTION  
COUNTER

NEW ADA STAFF TOILET  
ROOM



APPLEGATE ELEMENTARY SCHOOL  
FLOOR PLAN - PRIORITY 5



SCALE: 1" = 60'-0"

**CROW-APPLEGATE-LORANE SCHOOL DISTRICT - APPLEGATE ELEMENTARY SCHOOL**

**FACILITIES ASSESSMENT - DEFICIENCIES AND RECOMMENDATIONS - JANUARY 30, 2016**

|                                   |  |                              |   |        |  |  |  |  |  |
|-----------------------------------|--|------------------------------|---|--------|--|--|--|--|--|
| ABBR:                             |  |                              |   | NOTES: |  |  |  |  |  |
| ADA = ADA Upgrades                |  | Safety = Safety and Security | 1. Needs further study. Feasible solution not identified. |        |  |  |  |  |  |
| Deficient = Facility Deficiencies |  | Tech = Technology            |   |        |  |  |  |  |  |
| LS = Lump Sum                     |  | Elect = Electrical Systems   |   |        |  |  |  |  |  |
| Maint = Maintenance Needs         |  | Mech = Mechanical Systems    |   |        |  |  |  |  |  |

| No.                                | School    | Category | Priority Source | Item  | Qty   | Units | Unit Price (\$) | Const. Cost (\$)   | With Soft Cost (1.45%) | Notes   |
|------------------------------------|-----------|----------|-----------------|---|-------|-------|-----------------|--------------------|------------------------|---------|
| <b>APPLEGATE ELEMENTARY SCHOOL</b> |           |          |                 | <b>Priority 1 Total Cost</b>  |       |       |                 | <b>\$1,601,740</b> | <b>\$2,322,523</b>     |         |
| 1                                  | Main Bldg | Safety   | 1               | Front entry is not visually observed by office - move office                                      | 1,900 | SF    | 160             | 304,000            | 440,800                |         |
| 2                                  | Main Bldg | Safety   | 1               | Control entry for visitors - new doors, see elect for locks                                       | 9     | EA    | 7,500           | 67,500             | 97,875                 |         |
| 3                                  | Main Bldg | ADA      | 1               | Upgrade student toilet rooms to ADA   | 4     | EA    | 40,000          | 160,000            | 232,000                |         |
| 4                                  | Main Bldg | ADA      | 1               | Provide lever hardware  | 62    | EA    | 500             | 31,000             | 44,950                 |         |
| 5                                  | Site      | Maint    | 1               | Reroute drainage at east drive end  | 1     | LS    | 8,000           | 8,000              | 11,600                 |         |
| 6                                  | Site      | ADA      | 1               | Provide new ADA parking   | 540   | SF    | 6               | 3,240              | 4,698                  |         |
| 7                                  | Main Bldg | Maint    | 1               | Replace Classroom Unit Ventilator Consoles with VRF style units                                   | 20    | ea    | 4,500           | 90,000             | 130,500                | Use VRF |
| 8                                  | Main Bldg | Maint    | 1               | • Install new toilet exhaust fans for each toilet room or toilet room group.                      | 6     | ea    | 3,000           | 18,000             | 26,100                 |         |
| 9                                  | Main Bldg | Maint    | 1               | • Install ventilation unit for Gym with heat recovery.  | 1     | ea    | 25,000          | 25,000             | 36,250                 |         |
| 10                                 | Main Bldg | Maint    | 1               | • Install an electronic control system.   | 1     | ea    | 15,000          | 15,000             | 21,750                 |         |
| 11                                 | Main Bldg | Safety   | 1               | • Seismically brace basement water heater.  | 1     | ea    | 500             | 500                | 725                    |         |
| 12                                 | Main Bldg | Maint    | 1               | • Replace older fixtures with new low flow fixtures.  | 25    | ea    | 300             | 7,500              | 10,875                 |         |
| 13                                 | Main Bldg | Maint    | 1               | • Replace existing fluorescent surface wrap luminaires with new – common areas and support areas. | 1     | lot   | 45,000          | 45,000             | 65,250                 |         |

| No. | School    | Category  | Priority Source | Item  | Qty   | Units | Unit Price (\$) | Const. Cost (\$) | With Soft Cost (1.45%) | Notes |
|-----|-----------|-----------|-----------------|---|-------|-------|-----------------|------------------|------------------------|-------|
| 14  | Main Bldg | Maint     | 1               | • Replace existing fluorescent acrylic linear pendant luminaires with new – cafeteria and kitchen.  | 1     | lot   | 20,000          | 20,000           | 29,000                 |       |
| 15  | Main Bldg | Maint     | 1               | • Provide local occupancy sensor control to occupied rooms and support spaces.  | 1     | lot   | 34,000          | 34,000           | 49,300                 |       |
| 16  | Main Bldg | Deficient | 1               | • Provide A/V media equipment at each classroom, and permanent conduit and junction box provisions for installation of ceiling projectors, media connectivity at the teacher’s station, and speakers. | 11    | lot   | 5,000           | 55,000           | 79,750                 |       |
| 17  | Main Bldg | Maint     | 1               | • Replace horizontal copper cabling and upgrade to CAT 6. 1 drop per classroom.   | 1     | lot   | 5,000           | 5,000            | 7,250                  |       |
| 18  | Main Bldg | Safety    | 1               | • Provide magnetic door locks for exterior doors, centrally controlled from the office, and replace doors.  | 8     | lot   | 6,000           | 48,000           | 69,600                 |       |
| 19  | Main Bldg | Safety    | 1               | • Provide new manual fire alarm/sprinkler monitoring system with voice evacuation/alarm communication and visual strobe notification  | 1     | lot   | 65,000          | 65,000           | 94,250                 |       |
| 20  | Main Bldg | ADA       | 1               | Convert existing locker rooms to two team rooms, two single occupancy toilet rooms, an office and an equipment storage room.  | 2,000 | SF    | 300             | 600,000          | 870,000                |       |
| 21  |           |           |                 |   |       |       |                 |                  |                        |       |
| 22  |           |           |                 | <b>Priority 2 Total Cost</b>  |       |       |                 | <b>\$103,000</b> | <b>\$149,350</b>       |       |
| 23  | Main Bldg | ADA       | 2               | Add ramp access around main hall stair  | 1     | LS    | 60,000          | 60,000           | 87,000                 |       |
| 24  | Main Bldg | ADA       | 2               | Provide ADA access to cafeteria stage - add lift  | 1     | EA    | 40,000          | 40,000           | 58,000                 |       |
| 25  | Main Bldg | ADA       | 2               | Replace drinking fountains  | 2     | EA    | 1,500           | 3,000            | 4,350                  |       |
| 26  |           |           |                 |   |       |       |                 |                  |                        |       |
| 27  |           |           |                 | <b>Priority 3 Total Cost</b>  |       |       |                 | <b>\$161,154</b> | <b>\$233,673</b>       |       |

| No. | School    | Category  | Priority Source | Item  | Qty    | Units | Unit Price (\$) | Const. Cost (\$) | With Soft Cost (1.45%) | Notes |
|-----|-----------|-----------|-----------------|---|--------|-------|-----------------|------------------|------------------------|-------|
| 28  | Main Bldg |           | 3               | Cafeteria floor tile  | 2,718  | SF    | 3               | 8,154            | 11,823                 |       |
| 29  | Main Bldg | ADA       | 3               | Modify classroom sink faucets to ADA  | 7      | EA    | 500             | 3,500            | 5,075                  |       |
| 30  | Main Bldg | Seismic   | 3               | Seismic retrofit  |        |       |                 | 0                | 0                      |       |
| 31  | Main Bldg | Deficient | 3               | Update cold storage room - upgrade exhaust  | 1      | EA    | 1,500           | 1,500            | 2,175                  |       |
| 32  | Site      | Maint     | 3               | Improve bus lane - new full depth base  | 15,000 | SF    | 9               | 135,000          | 195,750                |       |
| 33  | Main Bldg | Safety    | 3               | <ul style="list-style-type: none"> <li>Replace select fixtures in corridor egress paths and at gym with local battery pack ballast with 90-minute backup in order to illuminate egress paths with minimum code required footcandle levels. Provide constant-hot charging branch circuit.</li> </ul> | 1      | lot   | 13,000          | 13,000           | 18,850                 |       |
| 34  |           |           |                 |   |        |       |                 |                  |                        |       |
| 35  |           |           |                 | <b>Priority 5 Total Cost</b>  |        |       |                 | <b>\$818,578</b> | <b>\$1,186,938</b>     |       |
| 36  | Main Bldg | ADA       | 5               | Provide ADA staff toilet room and improve finishes  | 1      | EA    | 25,000          | 25,000           | 36,250                 |       |
| 37  | Main Bldg | ADA       | 5               | Provide 36" high transaction counter in Library   | 1      | EA    | 1,000           | 1,000            | 1,450                  |       |
| 38  | Main Bldg | Energy    | 5               | Upgrade windows   | 2,920  | SF    | 65              | 189,800          | 275,210                |       |
| 39  | Main Bldg | Maint     | 5               | Upgrade siding  |        | SF    | 6               | 0                | 0                      |       |
| 40  | Main Bldg | Safety    | 5               | Abate and replace asbestos floor tile   | 16,600 | SF    | 12              | 199,200          | 288,840                |       |
| 41  | Main Bldg | Maint     | 5               | Provide new bleachers   | 1      | EA    | 40,000          | 40,000           | 58,000                 |       |
| 42  | Main Bldg | Deficient | 5               | Add daylight in cafeteria   | 1      | EA    | 5,000           | 5,000            | 7,250                  |       |
| 43  | Main Bldg | Maint     | 5               | Update carpeting  |        |       |                 | 0                | 0                      |       |
| 44  | Main Bldg | Maint     | 5               | Repair ceilings   |        |       |                 | 0                | 0                      |       |
| 45  | Main Bldg | Seismic   | 5               | Provide positive connections at basement columns  | 1      | LS    | 3,000           | 3,000            | 4,350                  |       |
| 46  | Main Bldg | Maint     | 5               | Repair & resurface gym floor  |        |       |                 | 0                | 0                      |       |
| 47  | Main Bldg | Safety    | 5               | <ul style="list-style-type: none"> <li>Provide new packaged rooftop units for non-ventlated rooms</li> </ul>  | 3      | ea    | 5,000           | 15,000           | 21,750                 |       |

| No. | School    | Category  | Priority Source | Item   | Qty    | Units | Unit Price (\$) | Const. Cost (\$) | With Soft Cost (1.45%) | Notes |
|-----|-----------|-----------|-----------------|--|--------|-------|-----------------|------------------|------------------------|-------|
| 48  | Main Bldg | Safety    | 5               | • Install the correct style exhaust fan for the range hood and a makeup air source.  | 1      | ea    | 3,500           | 3,500            | 5,075                  |       |
| 49  | Main Bldg | Maint     | 5               | • Insulate domestic water piping where needed.   | 400    | LF    | 20              | 8,000            | 11,600                 |       |
| 50  | Main Bldg | Deficient | 5               | • Install an automatic fire suppression system.  | 43,526 | sf    | 3               | 130,578          | 189,338                |       |
| 51  | Main Bldg | Safety    | 5               | • Install a hood fire suppression system.  | 1      | ea    | 8,500           | 8,500            | 12,325                 |       |
| 52  | Main Bldg | Maint     | 5               | • Service #1: Replace with a new 800-amp 120/240-volt 1-phase service equipment. Remove overhead service and install underground service lateral with utility termination cabinet and meter located on the exterior wall outside of the electrical room. Coordinate with utility company for new service provisions and removal of overhead.                                     | 1      | lot   | 55,000          | 55,000           | 79,750                 |       |
| 53  | Main Bldg | Safety    | 5               | • Service #2: Test distribution circuit breakers by current injection method and replace failed, as needed. Torque check of feeder terminations. Test (Megger) feeder conductors to panelboards. Visually inspect internal bussing for signs of corrosion. De-energize and clean interior of dust and debris. Check supply houses for circuit breaker and hardware availability. | 1      | lot   | 20,000          | 20,000           | 29,000                 |       |
| 54  | Main Bldg | Maint     | 5               | • Replace all branch panels with new panelboards.  | 1      | lot   | 70,000          | 70,000           | 101,500                |       |
| 55  | Main Bldg | Maint     | 5               | • Provide astronomical time clock controls for corridors and common areas, and exterior lighting.  | 1      | lot   | 20,000          | 20,000           | 29,000                 |       |

| No. | School    | Category | Priority Source | Item  | Qty | Units | Unit Price (\$) | Const. Cost (\$)   | With Soft Cost (1.45%) | Notes |
|-----|-----------|----------|-----------------|---|-----|-------|-----------------|--------------------|------------------------|-------|
| 56  | Main Bldg | Maint    | 5               | <ul style="list-style-type: none"> <li>Demolish/remove old clock/speaker system and cabling. Provide new central synchronized clock system, capable of networking with school network and interfacing with server software applications.</li> </ul>                 | 1   | lot   | 25,000          | 25,000             | 36,250                 |       |
| 57  |           |          |                 |   |     |       |                 |                    |                        |       |
| 58  |           |          |                 | <b>M Total Cost</b>   |     |       |                 | <b>\$45,000</b>    | <b>\$65,250</b>        |       |
| 59  | Main Bldg | Maint    | M               | Check roofing schedule  |     |       |                 | 0                  | 0                      |       |
| 60  | Main Bldg | Maint    | M               | <ul style="list-style-type: none"> <li>Replace all luminaires in locker rooms with new impact resistant surface mount lensed wraps, LED type.</li> </ul>  | 1   | lot   | 5,000           | 5,000              | 7,250                  |       |
| 61  | Main Bldg | Safety   | M               | <ul style="list-style-type: none"> <li>Provide new intercom/bell system and speakers, compatible with the new school phone system. Intercom system shall be capable of networking with school network and interfacing with server software applications.</li> </ul> | 1   | lot   | 40,000          | 40,000             | 58,000                 |       |
|     |           |          |                 |   |     |       |                 | <b>\$2,729,472</b> | <b>3,957,734</b>       |       |

# PLANNING FOR THE FUTURE

## SETTING PRIORITIES

### PRIORITY 1


1. SAFETY AND SECURITY UPGRADES, INCLUDING:
  - RECONFIGURED SCHOOL OFFICE TO PROVIDE A DIRECT VISUAL CONNECTION TO EVERYONE ENTERING THE FACILITY
  - CENTRALIZED MAGNETIC DOOR CONTROLS AND NEW EXTERIOR DOORS FOR LOCKDOWNS
  - ATTRACTIVE BUT SECURE FENCING TO IMPROVE PERIMETER SECURITY
  - UPDATED FIRE ALARM SYSTEM
  - NEW, MORE SECURE AND ADA COMPLIANT CLASSROOM DOOR HARDWARE
  - ADA IMPROVEMENTS FOR SAFE ACCESS FOR ALL STUDENTS

### PRIORITY 2

2. IMPROVEMENTS FOR ADEQUATE LEARNING SPACES INCLUDE:
  - CEILING MOUNTED INTEGRATED AV SYSTEMS TO FREE UP CLASSROOM SPACE
  - A NEW MAINTENANCE BUILDING THAT WILL FREE UP THE EXISTING AUTO SHOP AND ALLOW THAT PROGRAM TO RESTART
3. RENEWAL AND REPLACEMENT OF VITAL BUILDING SYSTEMS, INCLUDING:
  - NEW HIGH EFFICIENCY HEATING AND VENTILATION EQUIPMENT IN CLASSROOMS
  - IMPROVED DRAINAGE AT THE NORTH PARKING AREA
  - RETROFIT EXISTING LIGHTING FOR IMPROVED ENERGY EFFICIENCY

### PRIORITY 2

1. ADD A NEW STEM WING
  - TWO NEW SCIENCE ROOMS, ONE DESIGNED FOR MIDDLE SCHOOL SCIENCE AND ONE SET UP WITH LAB SPACES, SINKS AND A FUME HOOD FOR HIGH SCHOOL LEVEL SCIENCE CLASSES
  - CREATE A NEW ENGINEERING AND TECHNOLOGY SUITE BY RECONFIGURING THE EXISTING COMPUTER LAB AND PROVIDING LECTURE, LARGE PROJECT AND SMALL PROJECT SPACES
  - TWO NEW FULLY ADA COMPLIANT RESTROOMS
2. ADD A NEW SERVERY AT THE CAFETERIA
  - SPACE FOR FOOD WARMERS, SINKS, DISHWASHER AND A SERVING LINE
  - STORAGE FOR STAGE PROPS
  - A NEW JANITORS CLOSET
3. REPLACE THE BUS LOOP PAVING




## CROW HIGH SCHOOL MASTER SITE PLAN


CROW APPLEGATE LORANE SCHOOL DISTRICT

MAY 26, 2016

**GLAS**  
Architects, LLC




CROW MIDDLE SCHOOL  
 EXISTING SITE PLAN



SCALE: 1" = 200'-0"





1  
A2

CROW MIDDLE SCHOOL  
EXISTING FLOOR PLAN

SCALE: 1" = 50'-0"




**gLas**  
Architects,  
LLC


**PRIORITY I - ADDITIONAL IMPROVEMENTS**

1. REPLACE WINDOWS
2. UPDATE DOOR HARDWARE
3. REPLACE CLASSROOM HYAC UNITS PUMP
4. REPLACE OLDER INEFFICIENT FLUORESCENT SURFACE WRAP LUMINARIES WITH NEW
5. INSTALL CEILING MOUNTED INTEGRATED AV SYSTEMS


**NEW 1500 SF  
FIELD  
MAINTENANCE  
BUILDING**




**CONVERT EXISTING MAINTENANCE  
SHOP INTO AUTOMOTIVE/  
METALS SHOP**



**NEW ADA  
TOILET ROOM**



**ADMINISTRATION OFFICE  
REMODEL WITH NEW ADA  
TOILET ROOM**




**NEW ENTRY, SEE**




**CROW MIDDLE SCHOOL**

**FLOOR PLAN - PRIORITY I**

**SCALE: 1" = 50'-0"**






**ADMINISTRATION  
OFFICE REMODEL**

**CONTROL ENTRY  
AND BUILDING  
PERIMETER**

CROW MIDDLE SCHOOL

**ENLARGED FLOOR PLAN - PRIORITY I**

SCALE: 1/16" = 1'-0"



**PRIORITY 2 - ADDITIONAL IMPROVEMENTS**


**I. REPAIR BUS LOOP PAVING**

**NEW S.T.E.M. WING**

- \* TWO SCIENCE CLASSROOMS
- \* TECHNOLOGY AND ENGINEERING SUITE
- \* TOILET ROOMS

**NEW TEACHER'S LOUNGE**


**NEW SERVING ROOM AND NEW LANITOR ROOM**



CROW MIDDLE SCHOOL


**FLOOR PLAN - PRIORITY 2**

SCALE: 1" = 50'-0"



PRIORITY 3 - ADDITIONAL IMPROVEMENTS

1. REPLACE LOCKER ROOM EXHAUST SYSTEM.
2. REPLACE ALL ROOF EXHAUST FANS.
3. REPLACE EXISTING GALVANIZED WATER PIPING.




NEW WRESTLING  
WING

NORTH



CROW MIDDLE SCHOOL

FLOOR PLAN - PRIORITY 3




SCALE: 1" = 50'-0"

**gLas**  
Architects,  
LLC

**PRIORITY 5 - ADDITIONAL IMPROVEMENTS**

1. UPDATE PLUMBING FIXTURES.
2. REPLACE AND ABATE ASBESTOS FLOOR TILE.
3. RETROFIT OR REPLACE FOOTBALL GRANDSTAND.
4. ADD SEISMIC BRACING AT MECHANICAL AND PLUMBING UNITS.
5. INSTALL A NEW AUTOMATIC FIRE SUPPRESSION SYSTEM.
6. INSTALL NEW ELECTRICAL SYSTEM UPGRADES.



ADA ACCESS TO UPPER LEVEL


REMODEL LOCKER ROOM, SHOWERS, AND THEIR ENTRIES FOR ADA ACCESSIBILITY

NORTH




CROW MIDDLE SCHOOL

FLOOR PLAN - PRIORITY 5



SCALE: 1" = 50'-0"



CROW MIDDLE SCHOOL  
 SITE PLAN - PRIORITY 5

1  
 A8

SCALE: 1" = 100'-0"



**CROW-APPLEGATE-LORANE SCHOOL DISTRICT - CROW MIDDLE/HIGH SCHOOL**

**FACILITIES ASSESSMENT - DEFICIENCIES AND RECOMMENDATIONS - JANUARY 30, 2016**

|                                   |  |                              |  |        |  |  |  |  |  |
|-----------------------------------|--|------------------------------|--|--------|--|--|--|--|--|
| ABBR:                             |  |                              |  | NOTES: |  |  |  |  |  |
| ADA = ADA Upgrades                |  | Safety = Safety and Security |  |        |  |  |  |  |  |
| Deficient = Facility Deficiencies |  | Tech = Technology            |  |        |  |  |  |  |  |
| LS = Lump Sum                     |  | Elect = Electrical Systems   |  |        |  |  |  |  |  |
| Maint = Maintenance Needs         |  | Mech = Mechanical Systems    |  |        |  |  |  |  |  |

| No.               | School    | Category  | Priority Source | Item   | Qty   | Units | Unit Price (\$) | Const. Cost (\$)  | With Soft Cost (1.45%) | Notes         |
|-------------------|-----------|-----------|-----------------|--|-------|-------|-----------------|-------------------|------------------------|---------------|
| <b>CROW MS/HS</b> |           |           |                 | <u>Priority 1 Total Cost</u>   |       |       |                 | \$973,585         | \$1,411,698            |               |
| 1                 | Main Bldg | Safety    | 1               | Main entry points are not visually observed by office - reconfigure office - study option 1                      | 1,700 | SF    | 160             | 272,000           | 394,400                |               |
| 2                 | Main Bldg | Safety    | 1               | Control entry for visitors - new doors and fencing, see elect for locks  | 1     | LS    | 30,000          | 30,000            | 43,500                 |               |
| 3                 | Main Bldg | ADA       | 1               | Update toilet rooms to ADA - add unisex room   | 1     | LS    | 45,000          | 45,000            | 65,250                 |               |
| 4                 | Main Bldg | Maint     | 1               | Update staff toilet rooms  | 1     | LS    | 25,000          | 25,000            | 36,250                 |               |
| 5                 | Main Bldg | Energy    | 1               | Replace windows  | 1,009 | SF    | 65              | 65,585            | 95,098                 |               |
| 6                 | Main Bldg | ADA       | 1               | Provide lever hardware   | 82    | EA    | 500             | 41,000            | 59,450                 |               |
| 7                 | Site      | Maint     | 1               | Connect parking lot drainage - add catch basin and perforated underdrain and outflow to drainage ditch           | 1     | LS    | 17,500          | 17,500            | 25,375                 |               |
| 8                 | Site      | Deficient | 1               | Field maintenance building   | 1,500 | SF    | 75              | 112,500           | 163,125                |               |
| 9                 | Main Bldg | Maint     | 1               | • Replace classroom consoles with heat pump consoles   | 10    | ea    | 3,000           | <del>30,000</del> | <del>43,500</del>      |               |
| 10                | Main Bldg |           | 1               | <b>Or</b> replace with VRF consoles  | 10    | ea    | 4,500           | 45,000            | 65,250                 | VRF Cost Used |
| 11                | Main Bldg | Maint     | 1               | • Replace existing fluorescent surface wrap luminaires with new – common areas and support areas                 | 1     | lot   | 45,000          | 45,000            | 65,250                 |               |
| 12                | Main Bldg | Maint     | 1               | • Replace existing fluorescent acrylic linear pendant luminaires with new – classrooms, support areas, cafeteria | 1     | lot   | 75,000          | 75,000            | 108,750                |               |



| No. | School    | Category  | Priority Source | Item   | Qty    | Units | Unit Price (\$) | Const. Cost (\$)   | With Soft Cost (1.45%) | Notes                       |
|-----|-----------|-----------|-----------------|--|--------|-------|-----------------|--------------------|------------------------|-----------------------------|
| 13  | Main Bldg | Maint     | 1               | • Provide local occupancy sensor control to occupied rooms and support spaces.   | 1      | lot   | 40,000          | 40,000             | 58,000                 |                             |
| 14  | Main Bldg | Safety    | 1               | • Remove old fire alarm system pull station devices and sirens. Provide new manual fire alarm/sprinkler monitoring and alarm system with voice evacuation/alarm communication and visual strobe notification                                     | 1      | lot   | 75,000          | 75,000             | 108,750                |                             |
| 15  | Main Bldg | Maint     | 1               | • Demolish/remove old clock/ speaker system and cabling. Raceways are to remain to serve new systems. Provide new central synchronized clock system, capable of networking with school network and interfacing with server software applications | 1      | lot   | 25,000          | 25,000             | 36,250                 |                             |
| 16  | Main Bldg | Safety    | 1               | • Provide magnetic door locks for exterior doors, centrally controlled from the office.  | 30     | lot   | 2,000           | 60,000             | 87,000                 |                             |
| 17  |           |           |                 |  |        |       |                 |                    |                        |                             |
| 18  |           |           |                 | <b>Priority 2 Total Cost</b>   |        |       |                 | <b>\$2,656,480</b> | <b>\$3,851,896</b>     |                             |
| 19  | Main Bldg | Deficient | 2               | Update science in existing location: option 1 - replace cabinets   | 175    | LF    | 0               | 0                  | 0                      | Up to \$250,000 for 2 rooms |
| 20  | Main Bldg | Maint     | 2               | Update science classroom - add science wing - option 2   | 7,560  | SF    | 300             | 2,268,000          | 3,288,600              |                             |
| 21  | Site      | Maint     | 2               | Repair bus loop paving   | 18,720 | SF    | 9               | 168,480            | 244,296                | 24' strip                   |
| 22  | Main Bldg | Deficient | 2               | Add serving area to cafeteria  | 800    | SF    | 275             | 220,000            | 319,000                |                             |
| 23  |           |           |                 |  |        |       |                 |                    |                        |                             |
| 24  |           |           |                 | <b>Priority 3 Total Cost</b>   |        |       |                 | <b>\$707,250</b>   | <b>\$1,025,513</b>     |                             |
| 25  | Main Bldg | Deficient | 3               | Add new weight room facility   | 2,100  | SF    | 275             | 577,500            | 837,375                |                             |
| 26  | Main Bldg | Deficient | 3               | Replace old classroom furniture  |        |       |                 | 0                  | 0                      |                             |
| 27  | Main Bldg | Maint     | 3               | • Replace locker room exhaust system   | 2      | ea    | 4,500           | 9,000              | 13,050                 |                             |
| 28  | Main Bldg | Maint     | 3               | • Replace all roof exhaust fans  | 17     | ea    | 3,000           | 51,000             | 73,950                 |                             |
| 29  | Main Bldg | Maint     | 3               | • Replace existing galvanized water piping   | 550    | ea    | 45              | 24,750             | 35,888                 |                             |

| No. | School    | Category  | Priority Source | Item   | Qty   | Units | Unit Price (\$) | Const. Cost (\$)   | With Soft Cost (1.45%) | Notes |
|-----|-----------|-----------|-----------------|--|-------|-------|-----------------|--------------------|------------------------|-------|
| 30  | Main Bldg | Maint     | 3               | <ul style="list-style-type: none"> <li>Remove flood lights where coverage is aimed at parking and driveways. Provide new exterior pole mounted area lighting and pathway lighting to replace flood lights removed.</li> </ul>  | 1     | lot   | 20,000          | 20,000             | 29,000                 |       |
| 31  | Main Bldg | Maint     | 3               | <ul style="list-style-type: none"> <li>Replace all luminaires in locker rooms with new impact resistant surface mount lensed wraps, LED type.</li> </ul>   | 1     | lot   | 7,000           | 7,000              | 10,150                 |       |
| 32  | Main Bldg | Safety    | 3               | <ul style="list-style-type: none"> <li>Replace select fixtures in corridor egress paths, at cafeteria, and at gym with local battery pack ballast with 90-minute backup in order to illuminate egress paths with minimum code required footcandle levels. Provide constant-hot charging branch circuit.</li> </ul> | 1     | lot   | 18,000          | 18,000             | 26,100                 |       |
| 33  |           |           |                 |  |       |       |                 |                    |                        |       |
| 34  |           |           |                 | <b>Priority 4 Total Cost</b>   |       |       |                 | <b>\$81,000</b>    | <b>\$117,450</b>       |       |
| 35  | Main Bldg | Deficient | 4               | Add storage off stage  | 540   | SF    | 150             | 81,000             | 117,450                |       |
| 36  |           |           |                 |  |       |       |                 |                    |                        |       |
| 37  |           |           |                 | <b>Priority 5 Total Cost</b>   |       |       |                 | <b>\$1,363,837</b> | <b>\$1,977,564</b>     |       |
| 38  | Main Bldg | ADA       | 5               | Provide ADA access to locker rooms   | 1     | LS    | 30,000          | 30,000             | 43,500                 |       |
| 39  | Main Bldg | ADA       | 5               | Provide ADA access to 2nd floor in gym   | 1     | LS    | 45,000          | 45,000             | 65,250                 |       |
| 40  | Main Bldg | ADA       | 5               | Provide accessible showers   | 2     | EA    | 3,000           | 6,000              | 8,700                  |       |
| 41  | Main Bldg | Maint     | 5               | Replace sink on stage  | 1     | LS    | 2,000           | 2,000              | 2,900                  |       |
| 42  | Main Bldg | Maint     | 5               | Update faucets at art room sink  | 1     | LS    | 1,500           | 1,500              | 2,175                  |       |
| 43  | Main Bldg | Maint     | 5               | Update dust collection system  | 1     | LS    | 20,000          | 20,000             | 29,000                 |       |
| 44  | Main Bldg | Safety    | 5               | Replace and abate asbestos floor tile  |       |       |                 | 0                  | 0                      |       |
| 45  | Main Bldg | Maint     | 5               | Update shop sink   | 1     | LS    | 1,500           | 1,500              | 2,175                  |       |
| 46  | Main Bldg |           | 5               | Remodel locker rooms   | 4,100 | SF    | 200             | 820,000            | 1,189,000              |       |
| 47  | Site      | Safety    | 5               | Retrofit or replace football grandstand  |       |       |                 | 0                  | 0                      |       |

| No. | School    | Category  | Priority Source | Item  | Qty    | Units | Unit Price (\$) | Const. Cost (\$) | With Soft Cost (1.45%) | Notes |
|-----|-----------|-----------|-----------------|---|--------|-------|-----------------|------------------|------------------------|-------|
| 48  | Site      | Safety    | 5               | Fence parking 160' plus gate  | 1      | LS    | 12,800          | 12,800           | 18,560                 |       |
| 49  | Main Bldg | Safety    | 5               | • Replace water heater in mechanical pit and seismically brace  | 1      | ea    | 2,000           | 2,000            | 2,900                  |       |
| 50  | Main Bldg | Safety    | 5               | • Seismically brace pressure tanks in pump house  | 2      | ea    | 500             | 1,000            | 1,450                  |       |
| 51  | Main Bldg | Maint     | 5               | • Replace older fixtures with new low flow fixtures   | 22     | ea    | 300             | 6,600            | 9,570                  |       |
| 52  | Main Bldg | Safety    | 5               | • Relocate Science classroom emergency eye wash   | 1      | ea    | 250             | 250              | 363                    |       |
| 53  | Main Bldg | Safety    | 5               | • Replace the existing fire pump system   | 1      | ea    | 20,000          | 20,000           | 29,000                 |       |
| 54  | Main Bldg | Deficient | 5               | • Install an automatic fire suppression system for the entire building.   | 41,329 | sf    | 3               | 123,987          | 179,781                |       |
| 55  | Main Bldg | Safety    | 5               | • Main Switchboard: Test distribution circuit breakers by current injection method and replace failed as needed. Torque check of feeder terminations. Test (Megger) feeder conductors to panelboards. Visually inspect internal bussing for signs of corrosion. De-energize and clean interior of dust and debris. Check supply houses for circuit breaker and hardware availability. | 1      | lot   | 20,000          | 20,000           | 29,000                 |       |
| 56  | Main Bldg | Maint     | 5               | • Replace all branch panels with new panelboards.   | 1      | lot   | 115,000         | 115,000          | 166,750                |       |
| 57  | Main Bldg | Safety    | 5               | • Replace pond metered service and pump/controls equipment with new.  | 1      | lot   | 15,000          | 15,000           | 21,750                 |       |
| 58  | Main Bldg | Safety    | 5               | • Provide tap ahead of main and overcurrent device to serve fire pump improvements listed in Fire Protection improvements. Provide new underground fire pump feeder to fire pump location, approximately 250 feet away.   | 1      | lot   | 25,000          | 25,000           | 36,250                 |       |

| No. | School    | Category  | Priority Source | Item  | Qty | Units | Unit Price (\$) | Const. Cost (\$)   | With Soft Cost (1.45%) | Notes |
|-----|-----------|-----------|-----------------|---|-----|-------|-----------------|--------------------|------------------------|-------|
| 59  | Main Bldg | Safety    | 5               | • Replace flexible cord wiring to wood shop equipment with conduit and wiring.  | 1   | lot   | 1,200           | 1,200              | 1,740                  |       |
| 60  | Main Bldg | Maint     | 5               | • Provide astronomical time clock controls for corridors and common areas, and exterior lighting.   | 1   | lot   | 20,000          | 20,000             | 29,000                 |       |
| 61  | Main Bldg | Deficient | 5               | • Provide A/V media equipment at each classroom, and permanent conduit and junction box provisions for installation of ceiling projectors, media connectivity at the teacher's station, and speakers.               | 12  | lot   | 5,000           | 60,000             | 87,000                 |       |
| 62  | Main Bldg | Maint     | 5               | • Replace horizontal copper cabling and upgrade to CAT 6. 3 drops per classroom.  | 1   | lot   | 15,000          | 15,000             | 21,750                 |       |
| 63  |           |           |                 |   |     |       |                 |                    |                        |       |
| 64  |           |           |                 | <b>M Total Cost</b>   |     |       |                 | <b>\$275,000</b>   | <b>\$398,750</b>       |       |
| 65  | Main Bldg | Maint     | M               | Replace siding (in progress)  |     |       |                 | 0                  | 0                      |       |
| 66  | Main Bldg | Maint     | M               | • Provide phone system upgrade to VOiP, as specified by the District IT department.   | 1   | lot   | 20,000          | 20,000             | 29,000                 |       |
| 67  | Main Bldg | Safety    | M               | • Provide new intercom/bell system and speakers, compatible with the new school phone system. Intercom system shall be capable of networking with school network and interfacing with server software applications. | 1   | lot   | 40,000          | 40,000             | 58,000                 |       |
| 68  | Main Bldg | Maint     |                 | Schedule roofing work   |     |       |                 | 0                  | 0                      |       |
| 69  | Main Bldg | Maint     |                 | • Install new packaged roof top units for interior spaces   | 1   | ea    | 5,000           | 5,000              | 7,250                  |       |
| 70  | Main Bldg | Maint     |                 | • Replace old air handling units  | 6   | pt    | 35,000          | 210,000            | 304,500                |       |
|     |           |           |                 |   |     |       |                 | <b>\$6,057,152</b> | <b>8,782,870</b>       |       |

# **Crow / Applegate / Lorane School District Facility Assessments: MEP Building Assessment**

December 18, 2015

This page intentionally left blank.



## Contents

|  |          |
|--|----------|
| <b>1.0 Crow-Applegate-Lorane Elementary School .....</b> | <b>1</b> |
| 1.1 Mechanical Systems.....                              | 1        |
| 1.2 Plumbing Systems .....                               | 3        |
| 1.3 Fire Protection Systems.....                         | 3        |
| 1.4 Electrical Systems .....                             | 3        |
| 1.5 Lighting Systems.....                                | 6        |
| 1.6 Fire/Life Safety .....                               | 7        |
| 1.7 Technology .....                                     | 8        |
| <b>2.0 Crow High School .....</b>                        | <b>9</b> |
| 2.1 Mechanical Systems.....                              | 9        |
| 2.2 Plumbing Systems .....                               | 12       |
| 2.3 Fire Protection Systems.....                         | 13       |
| 2.4 Electrical Systems .....                             | 14       |
| 2.5 Lighting Systems.....                                | 15       |
| 2.6 Fire/Life Safety .....                               | 16       |
| 2.7 Technology .....                                     | 17       |



## Figures

|  |    |
|--|----|
| Figure 1: Unit Ventilator Console.....   | 1  |
| Figure 2: Electric Unit Heater in Gym.....                                     | 1  |
| Figure 3: New Kitchen Exhaust Fans.....  | 2  |
| Figure 4: Water Heater below Kitchen without Seismic Bracing .....             | 3  |
| Figure 5: Service #1 120/240V Switchboard at Electrical/Storage Room .....     | 4  |
| Figure 6: Service #2 277/480V Equipment at Building Exterior .....             | 4  |
| Figure 7: Trumbell Electric Panel Flush-Mounted in Gym .....                   | 5  |
| Figure 8: Surface Wrap in Corridor .....                                       | 6  |
| Figure 9: Linear fluorescent pendants at classroom. ....                       | 6  |
| Figure 10: Existing Fire Alarm Control Panel in Electrical/Storage Room .....  | 7  |
| Figure 11: Pull Station and Notification in Gym .....                          | 7  |
| Figure 12: Existing MDF Rack at Computer Lab Classroom. ....                   | 8  |
| Figure 13: Older Unit Ventilator Console .....                                 | 9  |
| Figure 14: Gym Heating and Ventilation Unit .....                              | 9  |
| Figure 15: Stage Pit Forced Air Fan Unit.....                                  | 10 |
| Figure 16: Several Roof Exhaust Fans.....                                      | 10 |
| Figure 17: Exhaust Fan with Cover Lifted Off, Exposing Rusted Components ..... | 11 |
| Figure 18: Water Heater in Stage Pit without Seismic Bracing.....              | 12 |
| Figure 19: Pump House Pressure Tanks without Seismic Bracing.....              | 12 |
| Figure 20: Science Room Emergency Eyewash.....                                 | 13 |
| Figure 21: Fire Sprinkler Riser for Stage Area .....                           | 13 |
| Figure 22: Main Metered Service Switchboard at Electrical Room .....           | 14 |
| Figure 23: Existing 120/240V Metered Service at Pond .....                     | 14 |
| Figure 24: Linear Fluorescent Pendants at Computer Lab Classroom.....          | 15 |
| Figure 25: Floodlight Lighting at East End of Building and Driveway .....      | 15 |
| Figure 26: Fire Alarm Siren and Pull Station .....                             | 17 |
| Figure 27: MDF Equipment at Computer Lab Classroom .....                       | 17 |





## Project Directory

### Owner

#### **Crow-Applegate-Lorane School District 66**

85955 Territorial Road  
Eugene OR 97402  
541-935-2100

#### **Aaron B. Brown**

*Superintendent/Elementary Principal*

[abrown@cal.k12.or.us](mailto:abrown@cal.k12.or.us)

### Architect

#### **gLAs Architects**

115 West 8<sup>th</sup> Ave, Ste 285  
Eugene, OR 97401  
(541)686-2014

#### **Walter R. Gresl, AIA**

*Principal, Member*

[wgresl@glas-arch.com](mailto:wgresl@glas-arch.com)

### Mechanical & Electrical Engineer

#### **PAE Consulting Engineers, Inc.**

522 SW Fifth Avenue, Suite 1500  
Portland, OR 97204  
503-226-2921

#### **Nick Collins, PE**

*Project Manager*

[nick.collins@pae-engineers.com](mailto:nick.collins@pae-engineers.com)

#### **Adam Koble, PE**

*Electrical Lead*

[adam.koble@pae-engineers.com](mailto:adam.koble@pae-engineers.com)

#### **Michael Scupien, PE**

*Mechanical Lead*

[mike.scupien@pae-engineers.com](mailto:mike.scupien@pae-engineers.com)

#### **Mallory Buck**

*Project Assistant*

[mallory.buck@pae-engineers.com](mailto:mallory.buck@pae-engineers.com)



## 1.0 Crow-Applegate-Lorane Elementary School

### 1.1 Mechanical Systems

#### Description

Heating for most classrooms in the school is provided by individual unit ventilator consoles with electric heat. The console units were installed in the early 1980s and are beyond their normal expected service life. A few rooms have newer electric baseboard heaters, and a few rooms have electric wall heaters. Corridors have larger recessed electric cabinet unit heaters. The district office has a new LG through the wall air conditioner. The Gym is heated by three suspended unit heaters and a fan coil system located under the stage. Locker Rooms have small suspended electric unit heaters. Below the Stage/Cafeteria is a large storage room with one suspended electric unit heater and one wall heater.



Figure 1: Unit Ventilator Console



Figure 2: Electric Unit Heater in Gym

Ventilation air is absent from most rooms, except for windows that can be opened. Some rooms, such as the band room and several interior office spaces do not appear to have ventilation capabilities at all.



Toilet and Locker Room exhaust fans, where present, appear to be beyond their expected service life. The Kitchen has two new exhaust fans to serve the dishwasher hood and the range hood. The range hood fan is a downdraft style and is not code compliant. The Gym has a large wall-mounted exhaust fan high on the



east wall. Several rooms with exhaust fans, mainly the Kitchen and Gym, do not have a means of makeup air. A converted classroom at the southwest corner of the building has food storage freezers and refrigerators. These units generate heat, which is dealt with by a window exhaust fan that operates continuously.

*Figure 3: New Kitchen Exhaust Fans*

*Note: Middle unit is a downdraft style connected to the range hood.*

Teachers manually operate the electric heat and open windows as deemed necessary. The school has an aggressive attitude concerning saving energy which is reducing energy consumption and utility bills.

### **Recommendations**

- Replace existing classroom heating only consoles with heat pump consoles that have outside air intakes. These may be independent or connected to a common refrigerant system utilizing variable refrigerant flow (VRF) technology. VRF systems have a higher energy saving ability, but are more expensive.
- In classrooms with clearstory windows, remove some windows and install motorized dampers to use natural convection to relieve ventilation air from the space (whether from open windows or consoles with ventilation).
- Install new packaged rooftop units for spaces that are interior and have no other way for ventilation air. The units to be heat pump style.
- Install new toilet exhaust fans for each toilet room.
- Install ventilation unit for the Gym with heat recovery.
- Install the correct style exhaust fan for the range hood and a makeup air source.
- Install an electronic control system to automatically start and stop mechanical systems. A new digital system has the advantage of being able to trend or track unit performance and can send alarms to maintenance staff at the time of failure for quick response. Provide system capable of networking with school network and interfacing with server software applications.



## 1.2 Plumbing Systems



### Description

Domestic Hot water is generated by two electric water heaters. A newer (2014) 119-gallon Bradford White heater with a recirculation pump is located in the old Boiler Room. The water heater is seismically secured with straps but does not have a housekeeping pad nor is it sitting in a pan.

A second 119-gallon older (2003) Bradford White electric water heater is located in the storage room below the Kitchen. This heater does not have seismic bracing or a pan.

Most if not all of the galvanized pipe in the domestic water system (hot and cold water) has been replaced with copper. Some portions of the domestic piping are not insulated, particularly near the water heaters.

*Figure 4: Water Heater below Kitchen without Seismic Bracing*

Roof drains appear to be older style (pipe size opening rather than a roof drain assembly), but mostly in good condition. Drains have wire cage style leaf guards.

The plumbing fixtures are typically older vintage type with high water usage faucets or flush valves. The school is implementing a program to replace older units with new fixtures with electronically actuated flush valves.

### Recommendations

- Seismically brace the basement water heater.
- Insulate domestic water piping where needed.
- Replace older fixtures with new low flow fixtures.

## 1.3 Fire Protection Systems

### Description

The building does not have a fire suppression system.

The Kitchen range hood does not have a fire suppression system.

### Recommendations

- Install an automatic fire sprinkler system for the building.
- Install a hood fire suppression system with emergency shutoff switch.

## 1.4 Electrical Systems



### Description

The elementary school campus is currently receives utility company power via two (2) separate metered electrical services, served from separate utility transformers.

Service #1, general lighting and receptacles metered service #61934 is 120/240-volt, 1-phase, 3-wire, and is served overhead from a pole mounted service transformer across the street from the main school entrance. The service entrance equipment appears to be original and in poor to fair condition at best. Nameplate information is missing from the main service switchboard, but it appears to be either 600-amp or 800-amp rated equipment.

Figure 5: Service #1 120/240V Switchboard at Electrical/Storage Room



Service #2, mechanical equipment metered service #50187 is 277/480-volt, 3-phase, 4-wire, and is served underground from pad mounted service transformers at the rear of the school building. The service entrance equipment appears to be original and in fair to good condition. Nameplate information is missing from the main service switchboard, but appears to be 800-amp rated equipment.

Figure 6: Service #2 277/480V Equipment at Building Exterior



Branch panels located in the main electrical area are vintage Square D equipment, and there are also Trumbell Electric panels flush mounted in the gym and corridors. They are old and need replacement.

There is no centralized emergency power system present on-site.



*Figure 7: Trumbell Electric Panel Flush-Mounted in Gym*

### **Recommendations**

- Service #1: Replace with a new 800-amp 120/240-volt 1-phase service equipment. Remove overhead service and install underground service lateral with utility termination cabinet and meter located on the exterior wall outside of the electrical room. Coordinate with utility company for new service provisions and removal of overhead.
- Service #2: Manually cycle on/off distribution circuit breakers and replace failed, as needed. Torque check of feeder terminations. Test (Megger) feeder conductors to panelboards. Visually inspect internal bussing for signs of corrosion. De-energize and clean interior of dust and debris. Check supply houses for circuit breaker and hardware availability.
- Replace all branch panels with new panelboards.



## 1.5 Lighting Systems



Figure 8: Surface Wrap in Corridor

### Description

Building interior lighting consists mostly of lensed T-8 linear fluorescent luminaires in corridors, classrooms, and support spaces. Some smaller spaces have compact fluorescent and incandescent lighting. All areas appear to be controlled by manual switches only.

Gym lighting has been retrofitted with fluorescent high-bay luminaires and occupancy sensor controls.




Figure 9: Linear fluorescent pendants at classroom.

Locker room luminaires are old and damaged.

Exterior lighting is controlled by photocell controls.

Emergency powered egress lighting does not appear to be present in the building.

### Recommendations

- Replace all luminaires in locker rooms with new impact resistant surface mount lensed wraps, LED type.
- Replace existing fluorescent surface wrap luminaires with LED type – common areas and support areas.
- Replace existing fluorescent acrylic linear pendant luminaires with LED type – classrooms, support areas, cafeteria.
- Replace existing exterior canopy acrylic lens luminaires with new LED type.
- Provide local occupancy sensor control to occupied rooms and support spaces.



- Provide astronomical time clock controls for corridors and common areas, and exterior lighting.
- Replace select luminaires in corridor egress paths and at gym with local battery pack ballast with 90-minute backup in order to illuminate egress paths with minimum code required footcandle levels. Provide constant-hot charging branch circuit and UL924 relays to bypass manual controls as applicable.


## 1.6 Fire/Life Safety



### Description

The fire alarm system consists of a fire alarm control panel located near Service #1 in the electrical/storage room. The panel is manufactured by Digital Monitoring Products, installed around 2008. Area smoke detection is provided at main corridors and select rooms, with manual pull station at main office and near exits. Notification appliance coverage is limited to audible devices only, with no visual strobe coverage. The auto-dialer has malfunctioned in the past and is currently deactivated due to false dial-outs.

Figure 10: Existing Fire Alarm Control Panel in Electrical/Storage Room



### Recommendations


Provide new fire alarm/sprinkler monitoring system with voice evacuation/alarm communication and visual strobe notification, with approved dial-out equipment to central monitoring station.

Figure 11: Pull Station and Notification in Gym





## 1.7 Technology



### Description

The existing MDF is centrally located in the building inside the computer lab classroom. Horizontal distribution is mostly CAT5e cabling and jacks.

The existing phone system is currently being upgraded and switching to VoIP. This effort will not be impacted by the bond.

The new paging system equipment was on-site but not yet installed. The IT staff plans to integrate the new devices with the new phone system.

The existing clock system is old, does not synchronize and needs replacement.

The classroom audio-visual equipment is not consistent between classrooms and permanent provisions are not present for installation of new A/V system.

Figure 12: Existing MDF Rack at Computer Lab Classroom.

### Recommendations

- Provide fixed, mounted A/V media equipment at each classroom, and permanent conduit and junction box provisions for installation of ceiling projectors, media connectivity at the teacher's station, and speakers.
- Replace horizontal copper cabling and upgrade to CAT 6. 3 drops per classroom.
- Demolish/remove old clock/speaker system and cabling.
- Provide new central synchronized wireless clock system, capable of networking with school network and interfacing with server software applications.
- Provide new intercom/bell system and speakers, compatible with the new school phone system. Intercom system shall be capable of networking with school network and interfacing with server software applications.
- Provide magnetic door locks for exterior doors, centrally and manually controlled from the office as requested by the District.



## 2.0 Crow High School

### 2.1 Mechanical Systems



Figure 13: Older Unit Ventilator Console

#### Description

Heating for most classrooms is produced by individual unit ventilator consoles with electric heat and through the wall connections for outside air ventilation. Most consoles have been replaced over the years as units fail, with only a one original construction consoles still in service.



Figure 14: Gym Heating and Ventilation Unit

The console units are serviceable due to ongoing good maintenance plan which is extending the units use beyond their normal expected service life.

A few spaces have forced air electric heat with furnace type air handling units. These spaces include the Library, Admin, Home Ec, and the north classroom. The Gym has two larger air handling units accessible by ladder from the mezzanine.



There is also a large forced air unit located in a pit below the stage. These units appear to be 1975 vintage, and although functional are beyond their expected service life.

A few Admin rooms have electric baseboard heaters and shop areas have suspended electric unit heaters.

*Figure 15: Stage Pit Forced Air Fan Unit*



Ventilation for classrooms takes place by way of a motorized damper in the console outside air connection. In rooms with forced air furnaces and air handlers, ventilation air is derived from similar connections to outside louver. Most furnace units have high wall or soffit supply with floor returns, including the Gym, the Stage and Multi-Purpose room. The Shop Classroom does not appear to have ventilation.

Exhaust fans located on the roof appear to be original equipment and are starting fail with cover frames rusting. Exhaust grilles in the locker shower areas are badly rusted. Condition of connecting ductwork not established.

*Figure 16: Several Roof Exhaust Fans. The near unit with a broken cover support.*



The Shop has a dust collector with under floor duct routing. The unit appears to be original equipment and is beyond the normal service life.

The building control system is new Paragon EC732 Energy Management System. The system functions as an automatic time clock for turning equipment on and off.

*Figure 17: Exhaust Fan with Cover Lifted Off, Exposing Rusted Components*

### **Recommendations**

- Replace existing classroom heating only consoles with heat pump consoles. These may be independent or connected to a common refrigerant system utilizing variable refrigerant flow (VRF) technology. VRF systems have a higher energy saving ability, but are more expensive.
- Install new packaged rooftop units for spaces that are interior and have no other way for ventilation air. The units to be heat pump style.
- Replace or rebuild vintage air handling units.
- Replace locker room exhaust grilles and ductwork.
- Replace all roof exhaust fans.



## 2.2 Plumbing Systems



### Description

Domestic Hot water is generated by two (2) new (2014) Bradford White electric water heaters, mounted in the old boiler room. The units are seismically braced, but are not on housekeeping pads or have pans.

An older water heater is located in the mechanical pit at the Stage. This unit serves the Multipurpose Room/Cafeteria. The water heater appears to be older and is not seismically braced.

An instantaneous water heater is located below a service sink in Multipurpose Janitor area.

*Figure 18: Water Heater in Stage Pit without Seismic Bracing*



Domestic water piping is new in the boiler room around the new water heaters, although most of the distribution piping is older galvanized pipe. The school has a well for its source of domestic water. The pumps are located in a pump house to the northwest of the main building. Two new pressure tanks are in the pump house and do not have seismic bracing.

Roof drains appear to be older style (pipe size opening rather than a roof drain assembly), but mostly in good condition. Drains have wire cage style leaf guards.

Plumbing fixtures are a mix of old and new, subject to the progress of planned upgrades and replacement of old fixtures. Older fixtures appear to be functional, but do not comply with current code water flow rates.

*Figure 19: Pump House Pressure Tanks without Seismic Bracing*



The Science classroom has an emergency eye wash that may splash on the electric unit ventilator console.

*Figure 20: Science Room Emergency Eyewash Close to an Electric Unit Ventilator Console.*

### **Recommendations**

- Replace the water heater in the mechanical pit and seismically brace.
- Replace existing galvanized water distribution piping.
- Seismically brace pressure tanks in pump house.
- Replace older fixtures with new low flow fixtures.
- Relocate Science classroom emergency eye wash.

### **2.3 Fire Protection Systems**



#### **Description**

The building has a wet sprinkler system for the Stage area only. It is reported that the well water fire pump assembly does not produce sufficient water flow or pressure for the system to be compliant.

*Figure 21: Fire Sprinkler Riser for Stage Area*



## Recommendations

- Replace the existing fire pump system with a unit to produce the required flow and pressure for the Stage and other areas.
- Add fire sprinklers to remaining existing classrooms.

## 2.4 Electrical Systems



### Description

The building main electrical service is located in dedicated electrical room, rated 1600A, 277/480VAC, 3-phase, 4-wire, Siemens ITE gear installed in 1968 – fair condition. Service comes from pad-mounted utility transformer approximately 100 feet away in the unpaved parking drive/parking area. A utility-interactive solar photovoltaic system is currently installed on this service, which appears to be new and in good condition.

Figure 22: Main Metered Service Switchboard at Electrical Room

Distribution and branch panels throughout the building are a mixture of surface and flush mounted in corridors and other spaces, same manufacturer and vintage as the service equipment.

Transformers are installed throughout the building in attic spaces.



There is a pond and separate metered pump service at the driveway entrance to the high school campus. This equipment appears to be rated 200A, 120/240VAC, 1-phase, 3-wire. The meter socket and pump connections equipment appear to be corroded and in poor condition. Nearby vegetation is grown-in and inhibits equipment access.

There is no centralized emergency power system present on-site.

Figure 23: Existing 120/240V Metered Service at Pond

The wood shop appears to have flexible cord cabling installed as a permanent wiring method, which does not comply with electrical code.



## Recommendations

- Main Switchboard: Manually cycle on/off distribution circuit breakers and replace failed as needed. Torque check of feeder terminations. Test (Megger) feeder conductors to panelboards. Visually inspect internal bussing for signs of corrosion. De-energize and clean interior of dust and debris. Check supply houses for circuit breaker and hardware availability.
- Replace all branch panels with new panelboards.
- Replace pond metered service and pump/controls equipment with new.
- Provide tap ahead of main and overcurrent device to serve fire pump improvements listed in Fire Protection improvements. Provide new underground fire pump feeder to fire pump location, approximately 250 feet away.
- Replace flexible cord wiring to wood shop equipment with conduit and wiring.

## 2.5 Lighting Systems



### Description

Building interior lighting consists mostly of lensed T-8 linear fluorescent luminaires in corridors, classrooms and support spaces. Some smaller spaces have compact fluorescent and incandescent lighting. All areas appear to be controlled by manual switches only.

Figure 24: Linear Fluorescent Pendants at Computer Lab Classroom



Gym lighting has been retrofitted with fluorescent high-bay luminaires and occupancy sensor controls. The occupancy sensors appear to be separately zoned into 4-6 isolated occupancy sensor controlled areas. These should be combined to allow an occupant to walk in and use part of the gym space without portions of it appearing dark. Locker room luminaires have damaged and/or discolored lenses.

Figure 25: Floodlight Lighting at East End of Building and Driveway





Exterior lighting is controlled by photocell controls. Canopy lighting has recently had LED sources as replacement and District is satisfied with the performance. Perimeter lighting is existing HID flood lights mounted at the top of building.

Emergency powered egress lighting is limited to battery pack bug-eye luminaires at selected locations.

### **Recommendations**

- Remove flood lights where coverage is aimed at parking and driveways. Provide new exterior pole mounted area lighting and pathway lighting to replace flood lights removed.
- Replace all luminaires in locker rooms with new impact resistant surface mount lensed wraps, LED type.
- Combine multiple occupancy sensor control zones at Gym into a single zone, so all lights in the Gym turn on when an occupant walks in.
- Replace existing fluorescent surface wrap luminaires with LED type – common areas and support areas.
- Replace existing fluorescent acrylic linear pendant luminaires with LED type – classrooms, support areas, cafeteria.
- Provide local occupancy sensor control to occupied rooms and support spaces.
- Provide astronomical time clock controls for corridors and common areas, and exterior lighting.
- Replace select luminaires in corridor egress paths, at cafeteria, and at gym with local battery pack ballast with 90-minute backup in order to illuminate egress paths with minimum code required footcandle levels. Provide constant-hot charging branch circuit and UL924 relays to bypass manual controls as applicable.

## **2.6 Fire/Life Safety**

### **Description**

The fire alarm system consists of an old manual system with pull stations, and bells with several loud sirens for notification, with no visual strobe coverage. The District has expressed a concern with the annunciating sirens being excessively loud and that some devices have been physically muffled, disconnected or deactivated.




Figure 26: Fire Alarm Siren and Pull Station

### Recommendations

- Remove old fire alarm system pull station devices and sirens. Provide new manual fire alarm/sprinkler monitoring and alarm system with voice evacuation/alarm communication and visual strobe notification, with approved dial-out equipment to central monitoring station.

## 2.7 Technology




Figure 27: MDF Equipment at Computer Lab Classroom

### Description

The existing MDF is located in the building inside the computer lab classroom. Horizontal distribution is mostly CAT5e cabling and jacks.

The phone system is in need of an upgrade to a VoIP system similar to the elementary school upgrade being implemented.

The existing paging system equipment was on-site but not yet installed. The IT staff plans to integrate the new devices with the new phone system.

The existing clock system is old, does not synchronized, and needs replacement.

The classroom audio-visual equipment is not consistent between classrooms, and permanent provisions are not present for installation of new A/V system.



## **Recommendations**

- Provide phone system upgrade to VoIP, as specified by the District IT department.
- Provide A/V media equipment at each classroom, and permanent conduit and junction box provisions for installation of ceiling projectors, media connectivity at the teacher's station, and speakers.
- Replace horizontal copper cabling and upgrade to CAT 6. 3 drops per classroom.
- Demolish/remove old clock/speaker system and cabling. Raceways are to remain to serve new systems.
- Provide new central synchronized wireless clock system, capable of networking with school network and interfacing with server software applications.
- Provide new intercom/bell system and speakers, compatible with the new school phone system. Intercom system shall be capable of networking with school network and interfacing with server software applications.
- Provide magnetic door locks for exterior doors, centrally controlled from the office as requested by the District.