

# CHAIN OF CUSTODY

508121252

**UNIVERSAL ENVIRONMENTAL CONSULTANTS**  
 12 BREWSTER ROAD  
 FRAMINGHAM, MASSACHUSETTS 01702  
 TEL: (508) 628-5486 • FAX: (508) 628-5488

ADMIN #12 → #21  
 H.S. #22 → #36  
 Green Meadow #37 → #56  
 1988 Green Meadow #57 → #66  
 FOWLER #67 → #81

Town/City: MAYNARD Building Name: Admin Job Number: \_\_\_\_\_

Sample	Description of Material	Sample Location
1 A	green vinyl stair tread	rear stairwell
2 A	green vinyl floor covering (landing)	" " "
3	adhesive #2 (backing)	" " "
4	pipe insul	Bsm't, stairwell - left
5	unit vent line	1 <sup>st</sup> fl meeting rm
6	adhesive #5	" " " "
7	unit vent line	2 <sup>nd</sup> fl, rm #7
8	ceiling plaster (CP)	underside of stairs, 1 <sup>st</sup> fl
9	CP	Bsm't, over refrigerator
10	CP	Bsm't, gas meter rm
11	CP	Boiler rm, corner
12	CP	Boiler rm, out side wall
13	CP	1 <sup>st</sup> fl meeting rm
14	CP	2 <sup>nd</sup> fl main hall
15 B	spray applied cty <del>wall plaster (WP)</del>	" " " " <del>rear stairwell - bsm't</del>
16	WP (wall plaster)	2 <sup>nd</sup> fl, rm-6
17	spray cty WP	2 <sup>nd</sup> rear stairwell, bsm't <del>2<sup>nd</sup> fl, rm-6</del>
18 B	spray applied cty	2 <sup>nd</sup> fl, rm-6
19 B	spray applied cty	2 <sup>nd</sup> fl, main hall by refrigerator
20 B	spray applied cty	2 <sup>nd</sup> fl, rm-7 - etc

Reported By: Lemuel B... Date: 12/31/08 Due Date: 01/05/09  
 Received By: Vanna Date: 12/31/08 1200

204

# CHAIN OF CUSTODY

**UNIVERSAL ENVIRONMENTAL CONSULTANTS**  
 12 BREWSTER ROAD  
 FRAMINGHAM, MASSACHUSETTS 01702  
 TEL: (508) 628-5486 • FAX: (508) 628-5488

508121252

Town/City: Maynard Building Name: Admin, Greenmeadow 1956/1974 H.S. Job Number: \_\_\_\_\_

Sample	Description of Material	Sample Location
21 C	spray applied cty	2 <sup>nd</sup> FL. cm-7 - side
22	FIBERGLASS (FP)	High School Boiler room by rear access
23	FP	Boiler room upper @ outside wall
24	FP	Boiler room by X-tanks
25	FP	Boiler room - CTR
26	FP	Boiler room, over sink
27	wall plaster (WP)	cm #102
28	WP	cm #112
29	WP	cm #206 - prep
30	WP	2 <sup>nd</sup> FL BOOK STORAGE
31	WP	1 <sup>st</sup> FL main cor by Handicapped
32	wood door insul	double doors to shops
33	wood transoms (over wood door)	Faculty office
34	transite window sill	cm 105
35	new black 12x12 vt	landing by cm #201
36	new white 12x12 vt	main cor by cjm
37 D	2x4 SAT-T	Conference cor @ main offices
38 D	2x4 SAT-T	Mrs. Green cm
39 D	2x4 SAT-T	Music Storage
40 E	Joint compound (JC)	main corridor wall (Mrs Green)

ADMIN

H.S.

Green Window

Reported By: Samuel P. Brown Date: 12/31/08 Due Date: 01/05/09  
 Received By: Voniga Date: 12/31/08 1200

# CHAIN OF CUSTODY

**UNIVERSAL ENVIRONMENTAL CONSULTANTS**  
 12 BREWSTER ROAD  
 FRAMINGHAM, MASSACHUSETTS 01702  
 TEL: (508) 628-5486 • FAX: (508) 628-5488

508121252

Town/City: Raymond Building Name: Green Meadow E.S. 1956/1974 Job Number: Green Meadow E.S. 1988

Sample	Description of Material	Sample Location
④1 E	JC	main corridor wall / by bathrooms
42 F	green vinyl floor tile	CAFE m.c. side
43 F	green vinyl floor tile	CAFE Exit door
44 G	1x1 AT-T	wallace wing main cor
45 G	1x1 AT-T	Mrs. Smart's room
46 G	1x1 AT-T	McCarthy's room
47 H	VT-T (under carpet)	McCarthy's room
48 H	VT-T (under carpet)	main corridor (wallace wing)
49 H	VT-T (exposed by sink)	Wallace's room
⑤0	12x12 Beige VT	MUSIC STORAGE
⑤1	CAFE door	CAFE STORAGE
⑤2	residue on H.W. tank	Boiler room
⑤3	residue gasket on duct hatch	stairs down to Boiler room
⑤4 I	mud on seam of EG DUCT INSUL (under EG jacketing)	Boiler room before
⑤5 I	" " " " " "	" " " " " "
⑤6 I	" " " " " "	" " " " " "
⑤7	(new) 12x12 VT BEIGE	Mrs. Fink
⑤8	adhesive #57	Mrs. Fink
⑤9	(new) 12x12 VT BLUE	Book storage
⑥0	adhesive #59	Book storage

1956/1974  
1988

Reported By: James J. ... Date: 12/31/08 Due Date: 01/05/09  
 Received By: Vannga Date: 12/31/08 1200

404

1-21 Admin  
32-36 HS  
37-56 GM - 56/74  
57-66 GM - 1988  
67-82 Fowler

# CHAIN OF CUSTODY

UNIVERSAL ENVIRONMENTAL CONSULTANTS  
12 BREWSTER ROAD  
FRAMINGHAM, MASSACHUSETTS 01702  
TEL: (508) 628-5486 • FAX: (508) 628-5488

508121252

Town/City: Maynard Building Name: Fowler Job Number: Green Meadow ES. - 1988

Sample	Description of Material	Sample Location
61 ✓	WOOD FIRE DOOR INSUL.	Mrs. George
62 ✓	WOOD FIRE DOOR INSUL.	Mrs. Holly
63	gypsum wall	JACCEE
64	gypsum wall	Duddy
65	JOINT COMPOUND #63	JACCEE
66	JOINT COMPOUND #64	Duddy
67	ENCASING (EP)	on metal deck ch. gym rear hall
68	(EP) ✓	" " " gym rear hall
69	(EP)	" " " gym rear hall
70	(new) 12x12 VT	1 <sup>st</sup> Fl connecting hall to B-wing (from kitchen)
71	(new) 12x12 VT	auditorium
72	(new) 12x12 VT	2 <sup>nd</sup> Fl main corridor (circular)
73	(new) 12x12 VT	gym rear stairwell
74	MASTIC #73	" " " "
75	MASTIC #71	auditorium
76	2x4 SAT	2 <sup>nd</sup> Fl Team room
77	2x2 SAT	1 <sup>st</sup> Fl NURSE
78	2x4 SAT	1 <sup>st</sup> Fl Teacher's room
79	2x2 SAT	auditorium chair storage
80	WOOD FIRE DOOR INSULATION	Gym storage

Green Meadow ES

Fowler

Fowler

Reported By: Sharon Burr Date: 12/31/08 Due Date: 01/25/09

Received By: Vanna Date: 12/31/08 1200

81 wood fire door insulation

2<sup>nd</sup> Fl double door to B-wing



**AmeriSci Boston**

8 SCHOOL STREET  
WEYMOUTH, MA 02189  
TEL: (781) 337-9334 • FAX: (781) 337-7642

January 5, 2009

Universal Environmental Consultant  
Attn: Ammar Dieb  
12 Brewster Road  
Framingham, MA 01702

RE: Universal Environmental Consultant  
Job Number 508121252  
P.O. #  
Maynard; Admin

28212.00

Dear Ammar Dieb:

Enclosed are the results for PLM asbestos analysis of the following Universal Environmental Consultant samples received at AmeriSci on Wednesday, December 31, 2008, for a 5 day turnaround:

1A, 2A, 3, 4, 5, 6, 7, 8, 9, 10, 11, 12, 13, 14, 15B, 16, 17, 18B, 19B, 20B, 21C, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37D, 38D, 39D, 40E, 41E, 42F, 43F, 44G, 45G, 46G, 47H, 48H, 49H, 50, 51, 52, 53, 54I, 55I, 56I, 57, 58, 59, 60, 61J, 62J, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81

The 81 samples contained in Zip Lock Bags were shipped to AmeriSci via Hand Delivery. These samples were prepared and analyzed according to the EPA Interim Method (EPA 600/M4-82-020 per 40 CFR 763, subpt F, App. A). The required analytical information, analysis results, analyst signature and laboratory identification is contained in the Analyst's Report.

This report relates ONLY to the sample analysis expressed as percent asbestos. The CV for this analysis is expected to range from 0.3 to 1.2, depending on the quantity of the analyte present. AmeriSci assumes no responsibility for customer supplied data such as "sample type", "location", or "area sampled". This report must not be used to claim product endorsement by AmeriSci, NVLAP or any agency of the U. S. Government. The National Institute of Standards and Technology Accreditation requirements, mandates that this report must not be reproduced, except in full without the written approval of the laboratory. This report may contain specific data not covered by NVLAP or ELAP accreditations respectively, if so identified in relevant footnotes.

AmeriSci appreciates this opportunity to serve your organization. Please contact us for any further assistance or with any questions.

Sincerely,

  
Bryan H. Clark  
Asbestos Lab Director



**AmeriSci Boston**

8 SCHOOL ST.

WEYMOUTH, MA 02189

TEL: (781) 337-9334 • FAX: (781) 337-7642

## PLM Bulk Asbestos Report

Universal Environmental Consultant  
Attn: Ammar Dieb  
12 Brewster Road  
Framingham, MA 01702

Date Received 12/31/08  
Date Examined 01/05/09  
RE Maynard; Admin

AmeriSci Job No. 508121252  
P.O. #  
Page 1 of 17

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
1A 1 Location: Rear Stairwell	508121252-01	Yes	2 % (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> Green, Homogeneous, Non-Fibrous, Vinyl Stair Tread <b>Asbestos Types:</b> Chrysotile 2.0 % <b>Other Material:</b> Non-fibrous 98 %			
2A 1 Location: Rear Stairwell	508121252-02		NA/PS
<b>Analyst Description:</b> Vinyl Floor Covering <b>Asbestos Types:</b> <b>Other Material:</b>			
3 Location: Rear Stairwell	508121252-03	No	NAD (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> Brown/Black, Heterogeneous, Fibrous, Adhesive #2 <b>Asbestos Types:</b> <b>Other Material:</b> Cellulose 65 %, Non-fibrous 35 %			
4 Location: Basement - Stairwell - Left	508121252-04	Yes	25 % (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> Off-White/Grey/White, Heterogeneous, Fibrous, Pipe Insulation <b>Asbestos Types:</b> Chrysotile 25.0 % <b>Other Material:</b> Cellulose 55 %, Non-fibrous 20 %			
5 Location: 1st Floor - Meeting Room	508121252-05	No	NAD (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> White/Beige, Homogeneous, Fibrous, Unit Vent Lino <b>Asbestos Types:</b> <b>Other Material:</b> Cellulose 25 %, Non-fibrous 75 %			

# PLM Bulk Asbestos Report

Maynard; Admin

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
6	508121252-06 Location: 1st Floor - Meeting Room	No	NAD (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> Brown, Homogeneous, Non-Fibrous, Adhesive #5 <b>Asbestos Types:</b> <b>Other Material:</b> Cellulose Trace, Non-fibrous 100 %			
7	508121252-07 Location: 2nd Floor - Room #7	No	NAD (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> White/Beige, Homogeneous, Fibrous, Unit Vent Lino <b>Asbestos Types:</b> <b>Other Material:</b> Cellulose 30 %, Non-fibrous 70 %			
8	508121252-08 Location: Underside Of Stairs - 1st Floor	No	NAD (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> Brown/White, Heterogeneous, Non-Fibrous, Cementitious, Ceiling Plaster <b>Asbestos Types:</b> <b>Other Material:</b> Animal hair 1 %, Cellulose Trace, Non-fibrous 99 %			
9	508121252-09.1 Location: Basement - Over Refrigerator	No	NAD (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> White, Homogeneous, Non-Fibrous, Ceiling Plaster <b>Asbestos Types:</b> <b>Other Material:</b> Cellulose Trace, Non-fibrous 100 % <b>Comment:</b> Skim Coat			
9	508121252-09.2 Location: Basement - Over Refrigerator	No	NAD (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> Brown, Homogeneous, Fibrous, Cementitious, Ceiling Plaster <b>Asbestos Types:</b> <b>Other Material:</b> Animal hair 3 %, Cellulose Trace, Non-fibrous 97 % <b>Comment:</b> Base Coat			

See Reporting notes on last page

Client Name: Universal Environmental Consultant

**PLM Bulk Asbestos Report**

Maynard; Admin

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
10	508121252-10.1 Location: Basement - Gas Meter Room	No	NAD (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> White, Homogeneous, Non-Fibrous, Ceiling Plaster			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Cellulose Trace, Non-fibrous 100 %			
<b>Comment:</b> Skim Coat			
10	508121252-10.2 Location: Basement - Gas Meter Room	No	NAD (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> Brown, Homogeneous, Fibrous, Cementitious, Ceiling Plaster			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Animal hair 2 %, Cellulose Trace, Non-fibrous 98 %			
<b>Comment:</b> Base Coat			
11	508121252-11.1 Location: Boiler Room - Corner	No	NAD (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> White, Homogeneous, Non-Fibrous, Ceiling Plaster			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Non-fibrous 100 %			
<b>Comment:</b> Skim Coat			
11	508121252-11.2 Location: Boiler Room - Corner	No	NAD (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> Brown, Homogeneous, Non-Fibrous, Cementitious, Ceiling Plaster			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Cellulose 1 %, Non-fibrous 99 %			
<b>Comment:</b> Base Coat			
12	508121252-12.1 Location: Boiler Room - Outside Wall	No	NAD (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> White, Homogeneous, Non-Fibrous, Ceiling Plaster			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Non-fibrous 100 %			
<b>Comment:</b> Skim Coat			

See Reporting notes on last page



Client Name: Universal Environmental Consultant

**PLM Bulk Asbestos Report**

Maynard; Admin

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
12	508121252-12.2 Location: Boiler Room - Outside Wall	No	NAD (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> Brown, Homogeneous, Non-Fibrous, Cementitious, Ceiling Plaster			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Cellulose Trace, Non-fibrous 100 %			
13	508121252-13 Location: 1st Floor - Meeting Room	No	NAD (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> Off-White, Homogeneous, Fibrous, Cementitious, Ceiling Plaster			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Animal hair 1 %, Cellulose Trace, Non-fibrous 99 %			
14	508121252-14.1 Location: 2nd Floor - Main Hall	No	NAD (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> White, Homogeneous, Non-Fibrous, Cementitious, Ceiling Plaster			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Cellulose Trace, Non-fibrous 100 %			
<b>Comment:</b> Skim Coat			
14	508121252-14.2 Location: 2nd Floor - Main Hall	No	NAD (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> Brown, Homogeneous, Fibrous, Cementitious, Ceiling Plaster			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Animal hair 3 %, Cellulose Trace, Non-fibrous 97 %			
<b>Comment:</b> Base Coat			
15B 2	508121252-15 Location: 2nd Floor - Main Hall	No	NAD (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> White, Homogeneous, Non-Fibrous, Spray Applied Ceiling			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Cellulose Trace, Non-fibrous 100 %			

See Reporting notes on last page

Client Name: Universal Environmental Consultant

**PLM Bulk Asbestos Report**

Maynard; Admin

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
16	508121252-16 Location: 2nd Floror - Room 6	No	NAD (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> Off-White, Homogeneous, Fibrous, Cementitious, Wall Plaster			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Animal hair 1 %, Cellulose Trace, Non-fibrous 99 %			
17	508121252-17.1 Location: Rear Stairwell - Basement	No	NAD (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> White, Homogeneous, Non-Fibrous, Cementitious, Wall Plaster			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Cellulose Trace, Non-fibrous 100 %			
<b>Comment:</b> Skim Coat			
17	508121252-17.2 Location: Rear Stairwell - Basement	No	NAD (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> Brown, Homogeneous, Fibrous, Cementitious, Wall Plaster			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Animal hair 2 %, Cellulose Trace, Non-fibrous 98 %			
<b>Comment:</b> Base Coat			
18B 2	508121252-18 Location: 2nd Floor - Room 6	No	NAD (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> White, Homogeneous, Non-Fibrous, Spray Applied Ceiling			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Cellulose Trace, Non-fibrous 100 %			
19B 2	508121252-19 Location: 2nd Floor - Main Hall By Refrigerator	No	NAD (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> White, Homogeneous, Non-Fibrous, Spray Applied Ceiling			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Cellulose Trace, Non-fibrous 100 %			

See Reporting notes on last page

Client Name: Universal Environmental Consultant

**PLM Bulk Asbestos Report**

Maynard; Admin

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
20B 2	508121252-20 Location: 2nd Floor Room 7 - Center	No	NAD (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> White, Homogeneous, Non-Fibrous, Spray Applied Ceiling			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Cellulose Trace, Non-fibrous 100 %			
21C 3	508121252-21 Location: 2nd Floor - Room 7 - Side	No	NAD (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> White, Homogeneous, Non-Fibrous, Spray Applied Clg			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Cellulose Trace, Non-fibrous 100 %			
22	508121252-22 Location: High School - Boiler Room By Roof Access	No	NAD (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> Off-White, Homogeneous, Fibrous, Firerproofing			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Cellulose Trace, Fibrous glass 80 %, Non-fibrous 20 %			
23	508121252-23 Location: Boiler Room - Upper At Outside Wall	No	NAD (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> Off-White, Homogeneous, Fibrous, Firerproofing			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Cellulose Trace, Fibrous glass 85 %, Non-fibrous 15 %			
24	508121252-24 Location: Boiler Room By X-Tanks	No	NAD (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> Off-White, Homogeneous, Fibrous, Firerproofing			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Cellulose Trace, Fibrous glass 85 %, Non-fibrous 15 %			
25	508121252-25 Location: Boiler Room - Center	No	NAD (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> Off-White, Homogeneous, Fibrous, Firerproofing			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Cellulose Trace, Fibrous glass 80 %, Non-fibrous 20 %			

See Reporting notes on last page

Client Name: Universal Environmental Consultant

**PLM Bulk Asbestos Report**

Maynard; Admin

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
26	508121252-26 Location: Boiler Room - Over Sink	No	NAD (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> Off-White, Homogeneous, Fibrous, Firerproofing			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Cellulose Trace, Fibrous glass 75 %, Non-fibrous 25 %			
27	508121252-27 Location: C'Room #102	No	NAD (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> Brown/White, Heterogeneous, Non-Fibrous, Cementitious, Wall Plaster			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Cellulose Trace, Non-fibrous 100 %			
28	508121252-28 Location: C'Room #112	No	NAD (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> Brown/White, Heterogeneous, Non-Fibrous, Cementitious, Wall Plaster			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Cellulose Trace, Non-fibrous 100 %			
29	508121252-29.1 Location: C'Room #206 - Prep	No	NAD (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> White, Homogeneous, Non-Fibrous, Wall Plaster			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Non-fibrous 100 %			
<b>Comment:</b> Skim Coat			
29	508121252-29.2 Location: C'Room #206 - Prep	No	NAD (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> Brown, Homogeneous, Non-Fibrous, Cementitious, Wall Plaster			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Cellulose Trace, Non-fibrous 100 %			
<b>Comment:</b> Base Coat			

See Reporting notes on last page

Client Name: Universal Environmental Consultant

**PLM Bulk Asbestos Report**

Maynard; Admin

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
30	508121252-30 Location: 2nd Floor - Book Storage	No	NAD (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> Brown/White, Heterogeneous, Non-Fibrous, Cementitious, Wall Plaster			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Cellulose Trace, Non-fibrous 100 %			
31	508121252-31.1 Location: 1st Floor - Main Corridor By Handicapped	No	NAD (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> White, Homogeneous, Non-Fibrous, Wall Plaster			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Non-fibrous 100 %			
<b>Comment:</b> Skim Coat			
31	508121252-31.2 Location: 1st Floor - Main Corridor By Handicapped	No	NAD (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> Brown, Homogeneous, Non-Fibrous, Cementitious, Wall Plaster			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Cellulose Trace, Non-fibrous 100 %			
<b>Comment:</b> Base Coat			
32	508121252-32 Location: Double Doors To Shops	Yes	20 % (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> White, Homogeneous, Fibrous, Wood Door Insulation			
<b>Asbestos Types:</b> Chrysotile 15.0 %, Amosite 5.0 %			
<b>Other Material:</b> Non-fibrous 80 %			
33	508121252-33 Location: Faculty Office	No	NAD (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> Off-White, Homogeneous, Fibrous, Wood Transom			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Cellulose 7 %, Fibrous glass 3 %, Non-fibrous 90 %			

See Reporting notes on last page

Client Name: Universal Environmental Consultant

**PLM Bulk Asbestos Report**

Maynard; Admin

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
34	508121252-34 Location: C'Room #105	Yes	25 % (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> Black, Homogeneous, Fibrous, Cementitious, Transite Window Sill			
<b>Asbestos Types:</b> Chrysotile 25.0 %			
<b>Other Material:</b> Cellulose Trace, Non-fibrous 75 %			
35	508121252-35 Location: Landing By C'Room #201	No	NAD (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> Black, Homogeneous, Non-Fibrous, New 12x12 VT			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Cellulose Trace, Non-fibrous 100 %			
36	508121252-36 Location: Main Corridor By Gym	No	NAD (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> White, Homogeneous, Non-Fibrous, New 12x12 VT			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Cellulose Trace, Non-fibrous 100 %			
37D 4	508121252-37 Location: Conference Room @ Main Offices	Yes	Trace (<1 %) (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> White, Homogeneous, Fibrous, 2x4 SAT I			
<b>Asbestos Types:</b> Chrysotile <1. %			
<b>Other Material:</b> Cellulose Trace, Fibrous glass 75 %, Non-fibrous 25 %			
38D 4	508121252-38 Location: Mrs. Green's Classroom	Yes	Trace (<1 %) (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> White, Homogeneous, Fibrous, 2x4 SAT I			
<b>Asbestos Types:</b> Chrysotile <1. %			
<b>Other Material:</b> Cellulose 15 %, Fibrous glass 60 %, Non-fibrous 25 %			
39D 4	508121252-39 Location: Music Storage	No	NAD (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> White, Homogeneous, Fibrous, 2x4 SAT I			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Cellulose 45 %, Fibrous glass 35 %, Non-fibrous 20 %			

See Reporting notes on last page

# PLM Bulk Asbestos Report

Maynard; Admin

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
40E 5	508121252-40 Location: Main Corridor Wall By Bathroom	Yes	2 % (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> Off-White, Homogeneous, Fibrous, Joint Compound <b>Asbestos Types:</b> Chrysotile 2.0 % <b>Other Material:</b> Cellulose Trace, Non-fibrous 98 %			
41E 5	508121252-41 Location: Main Corridor Wall By Bathroom		NA/PS
<b>Analyst Description:</b> Joint Compound <b>Asbestos Types:</b> <b>Other Material:</b>			
42F 6	508121252-42 Location: Cafe - M.C. Side	No	NAD (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> Green, Homogeneous, Non-Fibrous, Vinyl Floor Tile <b>Asbestos Types:</b> <b>Other Material:</b> Cellulose Trace, Non-fibrous 100 %			
43F 6	508121252-43 Location: Cafe - By Exit Door	No	NAD (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> Green, Homogeneous, Non-Fibrous, Vinyl Floor Tile <b>Asbestos Types:</b> <b>Other Material:</b> Cellulose Trace, Non-fibrous 100 %			
44G 7	508121252-44 Location: Wallace Ving Main Corridor	Yes	2 % (by CVES) by Ivan H Reyes on 01/05/09
<b>Analyst Description:</b> White, Homogeneous, Fibrous, 1x1 AT I <b>Asbestos Types:</b> Chrysotile 2.0 % <b>Other Material:</b> Cellulose Trace, Fibrous glass 75 %, Non-fibrous 23 %			
45G 7	508121252-45 Location: Mrs. Smart C'Room		NA/PS
<b>Analyst Description:</b> 1x1 AT I <b>Asbestos Types:</b> <b>Other Material:</b>			

Client Name: Universal Environmental Consultant

**PLM Bulk Asbestos Report**

Maynard; Admin

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
46G 7	508121252-46 Location: McCarthy C'Rm		NA/PS
<b>Analyst Description:</b> 1x1 AT I			
<b>Asbestos Types:</b>			
<b>Other Material:</b>			
47H 8	508121252-47 Location: McCarthy's C'rm	Yes	5 % (by CVES) by Sophetra Ken on 01/05/09
<b>Analyst Description:</b> Brown, Homogeneous, Fibrous, VT I			
<b>Asbestos Types:</b> Chrysotile 5.0 %			
<b>Other Material:</b> Non-fibrous 95 %			
48H 8	508121252-48 Location: Main Corridor		NA/PS
<b>Analyst Description:</b> VT I			
<b>Asbestos Types:</b>			
<b>Other Material:</b>			
49H 8	508121252-49 Location: Wallace C'Rm		NA/PS
<b>Analyst Description:</b> VT I			
<b>Asbestos Types:</b>			
<b>Other Material:</b>			
50	508121252-50 Location: Music Storage	No	NAD (by CVES) by Sophetra Ken on 01/05/09
<b>Analyst Description:</b> Beige, Homogeneous, Non-Fibrous, 12x12 VT			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Non-fibrous 100 %			
51	508121252-51 Location: Cafe Storage	No	NAD <sup>1</sup> (by CVES) by Sophetra Ken on 01/05/09
<b>Analyst Description:</b> Brown, Homogeneous, Non-Fibrous, Glue Daub			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Fibrous Talc 2 %, Non-fibrous 98 %			

See Reporting notes on last page



# PLM Bulk Asbestos Report

Maynard; Admin

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
52	508121252-52 Location: Boiler Room	Yes	60 % (by CVES) by Sophetra Ken on 01/05/09
<b>Analyst Description:</b> Off-White, Homogeneous, Fibrous, Residue On H.W Tank <b>Asbestos Types:</b> Chrysotile 60.0 % <b>Other Material:</b> Non-fibrous 40 %			
53	508121252-53 Location: Stairs Down To Boiler Room	Yes	60 % (by CVES) by Sophetra Ken on 01/05/09
<b>Analyst Description:</b> Off-White, Homogeneous, Fibrous, Residue Gasket On Duct Hatch <b>Asbestos Types:</b> Chrysotile 60.0 % <b>Other Material:</b> Non-fibrous 40 %			
54I 9	508121252-54 Location: Room Before Boiler Room	Yes	60 % (by CVES) by Sophetra Ken on 01/05/09
<b>Analyst Description:</b> Off-White, Homogeneous, Fibrous, Mud On Seam Of FG Duct Insulat <b>Asbestos Types:</b> Chrysotile 60.0 % <b>Other Material:</b> Non-fibrous 40 %			
55I 9	508121252-55 Location: Room Before Boiler Room		NA/PS
<b>Analyst Description:</b> Mud On Seam Of FG Duct Insulat <b>Asbestos Types:</b> <b>Other Material:</b>			
56I 9	508121252-56 Location: Room Before Boiler Room		NA/PS
<b>Analyst Description:</b> Mud On Seam Of FG Duct Insulat <b>Asbestos Types:</b> <b>Other Material:</b>			
57	508121252-57 Location: Mrs. Fink	No	NAD <sup>1</sup> (by CVES) by Sophetra Ken on 01/05/09
<b>Analyst Description:</b> Pink, Homogeneous, Non-Fibrous, 12x12 VT <b>Asbestos Types:</b> <b>Other Material:</b> Non-fibrous 100 %			

Client Name: Universal Environmental Consultant

**PLM Bulk Asbestos Report**

Maynard; Admin

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
58	508121252-58 Location: Ms. Fink	No	NAD (by CVES) by Sopheetra Ken on 01/05/09
<b>Analyst Description:</b> Black, Homogeneous, Non-Fibrous, Adhesive #57			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Non-fibrous 100 %			
59	508121252-59 Location: Book Storage	No	NAD <sup>1</sup> (by CVES) by Sopheetra Ken on 01/05/09
<b>Analyst Description:</b> Blue-Grey, Homogeneous, Non-Fibrous, 12x12 VT			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Non-fibrous 100 %			
60	508121252-60 Location: Book Storage	No	NAD (by CVES) by Sopheetra Ken on 01/05/09
<b>Analyst Description:</b> Black, Homogeneous, Non-Fibrous, Adhesive #59			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Non-fibrous 100 %			
61J 10	508121252-61 Location: Mrs. George	No	NAD (by CVES) by Sopheetra Ken on 01/05/09
<b>Analyst Description:</b> Off-White, Homogeneous, Fibrous, Wood Fire Door Insulation			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Cellulose 85 %, Non-fibrous 15 %			
62J 10	508121252-62 Location: Mrs. Holly	No	NAD (by CVES) by Sopheetra Ken on 01/05/09
<b>Analyst Description:</b> Off-White, Homogeneous, Fibrous, Wood Fire Door Insulation			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Cellulose 85 %, Non-fibrous 15 %			
63	508121252-63 Location: Jaffee	No	NAD (by CVES) by Sopheetra Ken on 01/05/09
<b>Analyst Description:</b> Off-White, Homogeneous, Fibrous, Gypsum Wall			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Cellulose Trace, Non-fibrous 100 %			

See Reporting notes on last page

Client Name: Universal Environmental Consultant

**PLM Bulk Asbestos Report**

Maynard; Admin

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
64	508121252-64 Location: Duddy	No	NAD (by CVES) by Sopheetra Ken on 01/05/09
<b>Analyst Description:</b> Off-White, Homogeneous, Fibrous, Gypsum Wall			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Non-fibrous 100 %			
65	508121252-65 Location: Jaffee	No	NAD (by CVES) by Sopheetra Ken on 01/05/09
<b>Analyst Description:</b> Off-White, Homogeneous, Non-Fibrous, Joint Compound #63			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Non-fibrous 100 %			
66	508121252-66 Location: Duddy	No	NAD (by CVES) by Sopheetra Ken on 01/05/09
<b>Analyst Description:</b> Off-White, Homogeneous, Non-Fibrous, Joint Compound #64			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Non-fibrous 100 %			
67	508121252-67 Location: On Metal Deck Clg - Gym Rear Hall	No	NAD (by CVES) by Sopheetra Ken on 01/05/09
<b>Analyst Description:</b> Grey, Homogeneous, Fibrous, Fireproofing			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Fibrous glass 60 %, Non-fibrous 40 %			
68	508121252-68 Location: On Metal Deck Clg - Gym Rear Hall	No	NAD (by CVES) by Sopheetra Ken on 01/05/09
<b>Analyst Description:</b> Grey, Homogeneous, Fibrous, Fireproofing			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Fibrous glass 60 %, Non-fibrous 40 %			
69	508121252-69 Location: On Metal Deck Clg - Gym Rear Hall	No	NAD (by CVES) by Sopheetra Ken on 01/05/09
<b>Analyst Description:</b> Grey, Homogeneous, Fibrous, Fireproofing			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Fibrous glass 60 %, Non-fibrous 40 %			

See Reporting notes on last page

Client Name: Universal Environmental Consultant

**PLM Bulk Asbestos Report**

Maynard; Admin

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
70	508121252-70 Location: 1st Floor - Connecting Hall To B-Wing	No	NAD (by CVES) by Sopheetra Ken on 01/05/09
<b>Analyst Description:</b> Off-White, Homogeneous, Non-Fibrous, 12x12 VT			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Non-fibrous 100 %			
71	508121252-71 Location: Auditorium	No	NAD (by CVES) by Sopheetra Ken on 01/05/09
<b>Analyst Description:</b> Off-White, Homogeneous, Non-Fibrous, 12x12 VT			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Non-fibrous 100 %			
72	508121252-72 Location: 2nd Floor - Main Corridor	No	NAD (by CVES) by Sopheetra Ken on 01/05/09
<b>Analyst Description:</b> Off-White, Homogeneous, Non-Fibrous, 12x12 VT			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Non-fibrous 100 %			
73	508121252-73 Location: Gym Rear Stairwell	No	NAD (by CVES) by Sopheetra Ken on 01/05/09
<b>Analyst Description:</b> Off-White, Homogeneous, Non-Fibrous, 12x12 VT			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Non-fibrous 100 %			
74	508121252-74 Location: Gym Rear Stairwell	No	NAD (by CVES) by Sopheetra Ken on 01/05/09
<b>Analyst Description:</b> Black, Homogeneous, Non-Fibrous, Mastic #73			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Non-fibrous 100 %			
75	508121252-75 Location: Auditorium	No	NAD (by CVES) by Sopheetra Ken on 01/05/09
<b>Analyst Description:</b> Black, Homogeneous, Non-Fibrous, Mastic #71			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Non-fibrous 100 %			

See Reporting notes on last page

Client Name: Universal Environmental Consultant

**PLM Bulk Asbestos Report**

Maynard; Admin

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
76	508121252-76 Location: 2nd Floor - Team Room	No	NAD (by CVES) by Sopheetra Ken on 01/05/09
<b>Analyst Description:</b> Brown/Off-White, Homogeneous, Fibrous, 2x4 SAT			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Cellulose 30 %, Fibrous glass 10 %, Non-fibrous 60 %			
77	508121252-77 Location: 1st Floor - Nurse	No	NAD (by CVES) by Sopheetra Ken on 01/05/09
<b>Analyst Description:</b> Brown/Off-White, Homogeneous, Fibrous, 2x4 SAT			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Cellulose 30 %, Fibrous glass 10 %, Non-fibrous 60 %			
78	508121252-78 Location: 1st Floor - Teacher's Room	No	NAD (by CVES) by Sopheetra Ken on 01/05/09
<b>Analyst Description:</b> Brown/Off-White, Homogeneous, Fibrous, 2x4 SAT			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Cellulose 30 %, Fibrous glass 10 %, Non-fibrous 60 %			
79	508121252-79 Location: Auditorium Chair Storage	No	NAD (by CVES) by Sopheetra Ken on 01/05/09
<b>Analyst Description:</b> Brown/Off-White, Homogeneous, Fibrous, 2x2 SAT			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Cellulose 30 %, Fibrous glass 10 %, Non-fibrous 60 %			
80	508121252-80 Location: Gym Storage	No	NAD (by CVES) by Sopheetra Ken on 01/05/09
<b>Analyst Description:</b> Brown/Off-White, Homogeneous, Fibrous, Wood Fire Door Insulation			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Cellulose 5 %, Fibrous glass Trace, Non-fibrous 95 %			
81	508121252-81 Location: 2nd Floor - Double Door To B-Wing	No	NAD (by CVES) by Sopheetra Ken on 01/05/09
<b>Analyst Description:</b> Brown, Homogeneous, Fibrous, Wood Fire Door Insulation			
<b>Asbestos Types:</b>			
<b>Other Material:</b> Cellulose 5 %, Fibrous glass Trace, Non-fibrous 95 %			

See Reporting notes on last page

Client Name: Universal Environmental Consultant


# PLM Bulk Asbestos Report

Maynard; Admin

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
------------------	---------	------------------	------------------

### Reporting Notes:

(1) TEM confirmation of PLM results recommended

Analyzed by: Ivan H Reyes ; Date Analyzed: 1/5/09

NAD = no asbestos detected; CVES = Calibrated Visual Estimate; NA = not analyzed; NA/PS = not analyzed / positive stop; "Present" or NVA = "No Visible Asbestos" are observations made during a qualitative analysis; PLM Bulk Asbestos Analysis by EPA 600/M4-82-020 per 40 CFR 763 (NVLAP Lab #102079-0) or NY ELAP PLM Analysis Protocol 198.1 for New York friable samples (198.6 for NOB samples) (NY ELAP Lab # 10982); Note: PLM is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. NAD or Trace results by PLM are inconclusive, TEM is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos-containing in New York State (also see EPA Advisory for floor tile, FR 59, 146, 38970, 8/1/94). NIST Accreditation requirements mandate that this report must not be reproduced except in full without the approval of the laboratory. This PLM report relates ONLY to the items tested.

Reviewed By: 