PART II: EVALUATION DE	TAIL	Da	nte of Inspection:	08/29/17	-	School Name	Gustine H	gh School						-	Page 5 of
CATEGORY	GAS LEAKS	2 MECHANAS	3 SEWER	4 INTERIOR SURFACES	GVERALL OLEANLINESS	PEST/VEHMIN INFESTATION	7 ELECTRICAL	8 RESTROOM	SINKS:	10 FIRE SAFETY	11 HAZARBOUS MATERIALS	12 BIRUCTURAL DAMAGE	13 Rooes	HAYBROUNDSELL HOOL GROUNDS	15 WINDUMS DODRS
Freshman Hall	✓	✓	✓	D	✓	✓	✓	✓	✓	D	✓	✓	✓	✓	√
	COMMENTS	There are o	ceiling tiles th	at are hangin	g down in th	e theatre. Th	ere are wate	r stained cei	ling tiles at th	ne right side.	There is no	water pressu	re at the drir	iking fountai	1,
KITCHEN/	✓	✓	✓	✓	✓	✓	✓	✓	D	D	✓	✓	✓	✓	D
cafeteria	COMMENTS	The triple s	ink has a loo	se faucet. The	e hand wash	sink is loose	. The door e	ntering the v	valk-in is rotte	ed.				410	
AG GARAGE	✓	✓	✓	✓	✓	✓	D	NA	✓	✓	✓	✓	✓	✓	D
	COMMENTS	The entry d	loor is rotted.	There are lig	hts that are	that are out. The electical panel is missing a blank. There is siding damage on the left outside wall.									
Staff Lounge	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	GOMMENTS:					W-1-2-11-11									
JR HALL	✓	✓	✓	D	✓	✓	✓	✓	✓	D	✓	✓	✓	√	✓
	COMMENTS	There are o	damaged lock	ers and the f	re extinguisi	hers in the fo	yer need to I	oe labeled.							
Room 19	✓	✓	✓	✓	✓	✓	✓	NA	✓	✓	✓	✓	✓	✓	✓
	COMMENTS														
Room 8	✓	/	✓	D	✓	✓	✓	NA	✓	✓	✓	✓	✓	✓	✓
	COMMENTS	There are e	electrical wire	s that need a	cord cover.	·		,							
Girls locker	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
room	COMMENTS										*				
Boys locker	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
room	COMMENTS:					- Jill									7.
GYM	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS		,												
Welding shop	✓	✓	✓	✓	✓	✓	✓	NA	✓	✓	✓	✓	✓	✓	✓
	COMMENTS														
Wood shop	√	✓	✓	✓	✓	✓	D	NA	D	✓	✓	✓	✓	✓	✓
	COMMENTS:	The electric	al switch by t	he entrance i	s missing the	e knock out.	The eye was	h station has	s no water pr	essure. The	e are lights t	hat are out.			
Band room	√	✓	✓	✓	✓	✓	✓	NA	✓	✓	✓	✓	✓	✓	1
	COMMENTS														
F tior	✓	✓	✓	✓	✓	✓	1	✓	✓	✓	✓	✓	√	✓	1

(NEV 03/08)															Page 5 of 6
PART II: EVALUATION DE	TAIL		te of Inspection	08/29/17		School Name:	Gustine Hi	gh School							
AREA	1 GASTLEANS	2 мерниуло	3 SEWER	4 INTERIOR SURFACES	5 OVERALL ELEANLINESS	6 PESTIVERMIN INFESTATION	7 ELECTRICAL	8 RESTROOM	9 SHAKSI FOUNTAINS	10 FIRE SAFETY	11 HAZARIOCHS MATERIALS	12 STEUDTURAL DAMAGE	13 Romes	FLAVOROUNDSO	15 www.pows poors
LXIOTIOI	COMMENTS.)	S CONTRACTOR OF THE STATE OF TH			Constant Con	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Possible United St.	I, management	and deal	PRAISE	The second secon	LUATESPENCES
Room 21	✓	✓	✓	D	✓	✓	D	NA	✓	✓	✓	✓	V	1	1
ROUIII Z I	COMMENTS	There is some missing cove base and there is a light out.													
Room 14	✓	✓	✓	D	✓	✓	D	NA	✓	✓	✓	✓	✓	✓	✓
	COMMENTS	The light switch needs the proper cover. The cabinet face is peeling.													
Room 20	✓	✓	✓	D	✓	✓	✓	NA	✓	✓	✓	✓	1	✓	✓
	COMMENTS	There is rus	There is rust and chipped paint on the ceiling beam.												
Computer lab	✓	✓	✓	✓	✓	✓	✓	NA	✓	✓	✓	✓	✓	✓	✓
·	COMMENTS				,				4						
Room 16	✓	✓	✓	D	✓	✓	✓	NA	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:	There is a b	oroken drawe	r, one drawer	is missing, a	and there are	several bro	ken drawer l	handles.						
Room 15	✓	✓	✓	D	✓	✓	✓	NA	D	✓	✓	✓	✓	✓	✓
	COMMENTS	There is peeling paint at the door. There is a loose faucet at the work station and there is a faucet handle missing at a work station.													
Room 12	✓	✓	✓	D	✓	✓	✓	NA	✓	✓	✓	✓	✓	✓	✓
	COMMENTS.		ssing floor tile).											
Room 9	√	✓	✓	✓	✓	✓	✓	NA	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:					r									
Room 4	√	✓	✓	✓	✓	✓	✓	NA	✓	✓	✓	✓	✓	✓	✓
	COMMENTS			,		r									
Room 34	√	✓	✓	D	✓	✓	✓	NA	✓	✓	✓	✓	✓	✓	✓
	COMMENTS	There are s	everal ceiling	tiles that are	sagging.				r		p		r		
Weight Room	√	✓	✓	✓	✓	✓	D	NA	✓	✓	✓	✓	✓	✓	✓
	COMMENTS	There are s	everal lights	hat are out.											
Room 6	✓	✓	✓	D	✓	✓	✓	NA	✓	✓	✓	✓	✓	✓	✓
	COMMENTS		ssing floor tile	. There is ripp	oed tackboar	rd.									
Room 18	√	D	✓	D	✓	✓	✓	NA	✓	✓	✓	✓	✓	✓	✓
	COMMENTS	There is ripp	ped tackboar	d. The A.C. ve	ents are dirty	'									

PART II: EVALUATION DE	TAIL	Dat	e of Inspection:	08/29/17	•	School Name:	Gustine Hig	gh School							
CATEGORY	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15 Wildows
AREA	GAS LEAKS	MEGH/HVAG	SEWER	BURFACES	OVERALL CLEANLINESS	PESTIVERMIN INFESTATION	ELECTRICAL	RESTROOM	FOUNTAINS	HIRE SAFETY	MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUND/SO HODE GROUNDS	DOORS SATESFENCES
Room 34	✓	✓	✓	✓	✓	√	1	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:							1							
Restrooms by	1	✓	✓	✓	V	✓	✓	1	1	1	✓	1	✓	V	✓
rm 11	COMMENTS:														

Marks: ✓ = Good Repair (When filling up the electronic version, please use ctrl+G); D = Deficiency; X = Extreme Deficiency; NA = Not Applicable Use additional sheets as necessary.

(REV 05/09)

FACILITY INSPECTION TOOL(FIT)

SCHOOL FACILITY CONDITIONS EVALUATION

STATE ALLOCATION BOARD OFFICE OF PUBLIC SCHOOL CONSTRUCTION

Page 6 of 6

SCHOOL DISTRICT/COUNTY OFFICE OF EDUCATION		COUNTY				
Gustine Unified School District		MERCED				
SCHOOL SITE		SCHOOL TYPE (GRADE LEVELS)	NUMBER OF CLASSROOMS ON SITE			
Gustine High School		9 thru 12	33			
INSPECTOR'S NAME	INSPECTOR'S TITLE	NAME OF DISTRICT REPRESENTATIVE ACCO	IMPANYING THE INSPECTOR(S) (IF APPLICABLE)			
RAY BIRCH	UTILITY SUPERVISOR	Russell Hazan				
TIME OF INSPECTION	WEATHER CONDITION AT TIME OF INSPECTION	The state of the s				
8:00						

PART III: CATEGORY TOTALS AND RANKING (round all calculations to two decimal places)

TOTAL NUMBER CATEGORY		A SYSTEMS			R. INTERIOR	C/CLEANLINESS		D. ELECTRICAL	EL RESTROOMS/FOUNTAINS		F. BAFETY		G. STRUCTURAL		AL EXTERNAL	
OF AREAS EVALUATED	TOTALS	DAS LEAKS	MECHNIVAC	зеуун	INTERIOR SURFACES	OVERALL CLEANLINESS	RESTITUTEMENT INFESTATION	ELECTRICAL	RESTROOMS	NEWS FOUNTAINS	EMP SAFETY	HAZARDOUS MATERIALS	OTBUQTURAL DAMAGE	ROOFS	PLAYORDUND 96HOOL GROUNDS	WINDOWS/DODRS/ GATEMPENCES
	Number of Nfs.	29	28	29	17	29	29	24	10	26	26	29	29	29	29	27
	Number of "D"s	0	1 -	0	12	0	0	.5	0	3	3	0	0	0	0	2
29	Number of 14th:	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
	Number of N/As	0	0	0	0	0	0	0	19	0	0	0	0	0	0	0
Number of - To divi	im in Good Repair ided by (Tota - "NA"s)"	100.00%	96.55%	100.00%	58.62%	100.00%	100.00%	82.76%	100,00%	89.66%	89.66%	100.00%	100.00%	100.00%	100.00%	93.10%
Total Percent	I per Category of above)*		98.85%		58.62%	100	.00%	82.76%	94.	83%	94.	83%	100.	00%	96	6.55%
G000 = FAIR = 75	(Ircle one) 90%-100% 5%-89.99% 0%-74.99%		GOOD		POOR	go	OOD	FAIR	Go	OOD	GC	OOD	GO	OD	G	OOD

^{*}Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category and a zero for "Total Percent per Category".

OVERALL RATING:

ETERMINE AVERAGE PERCENTAGE OF 8 CATEGORIES ABOVE	90.80%	SCHOOL RATING**	GOOD

**For School Rating, apply the Percentage Range below to the average percentage determined above, taking into account the rating Description below.

DESCRIPTION	RATING
The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.	EXEMPLARY
The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.	GOOD
The school is not in good repair. Some deficiencies noted are critical and/or widespread. Repairs and/or additional maintenance are necessary in several areas of the school site.	FAIR
The school facilities are in poor condition, Deficiencies of various degrees have been noted throughout the site. Major repairs and maintenance are necessary throughout the campus.	POOR
	The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school. The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated. The school is not in good repair. Some deficiencies noted are critical and/or widespread. Repairs and/or additional maintenance are necessary in several areas of the school site.

COMMENTS AND RATING EXPLANATION:	