(REV 05/09)

Page 6 of 6

| | | | | _ |
|--|--|---------------------------------------|---|---|
| SCHOOL DISTRICT COUNTY OFFICE OF EDUCATION | | COUNTY | | _ |
| Gustine Unified School District | | MERCED | | |
| SCHOOL SITE | | SCHOOL TYPE (GRADELEVELS) | NUMBER OF CLASSROOMS ON SITE | _ |
| ROMERO ELEMENTARY | | TK-5TH | | |
| WSPECTOR'S NAME | NSFECTOR'S TILE | NAME OF DISTRICT REPRESENTATIVE ACCOM | PANYING THE INSPECTOR (S) (IF APPLICABLE) | |
| Ray Birch | Custodial Supervisor | Russell Hazan | | |
| TIME OF INSPECTION | WEATHER CONDITION AT TIME OF IN SPECTION | | | _ |
| 8:30 AM | CLEAR | | | |

PART III: CATEGORY TOTALS AND RANKING (round all calculations to two decimal places)

| TOTAL NUMBER | CATEGORY | | A. SYSTEMS | | B.NTERIOR | C.CLEA | NLINESS | D.ELECTRICAL | E.RESTROOM | MSFOUNTAINS | F. SA | FETY | G. STRUC | TURAL | H.E | XTERNAL |
|---|--|----------|------------|---------|----------------------|------------------------|---------------------------|--------------|------------|---------------------|-------------|------------------------|----------------------|--------|----------------------------------|-----------------------------|
| OF AREAS EVALUATED | TOTALS | GASLEAKS | MECH/HVAC | SEWER | INTERIOR SURFACES | OVERALL CLEANLINESS | PESTMERMIN INFESTATION | ELECTRICAL. | RESTROOMS | SINKS/ FOUNTAINS | FIRE SAFETY | HAZARDOUS MATERIALS | STRUCTURAL DAMAGE | ROOFS | PLAYGROUND/ SCHOOL GROUNDS | WINDOWSDOORS GATESFENCES |
| | Number of "√"s: | 15 | 14 | 15 | 12 | 14 | 15 | 15 | 11 | 14 | 15 | 15 | 15 | 14 | 2 | 13 |
| | Number of "D"s | 0 | 1 | 0 | 3 | 1 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 1 | 1 | 2 |
| 15 | Number of "X"s: | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| | Number of N/As: | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 4 | 0 | 0 | 0 | 0 | 0 | 12 | 0 |
| Percent of Syster Number of "V" (Total Area | 's divided by | 100.00% | 93.33% | 100.00% | 80.00% | 93.33% | 100.00% | 100.00% | 100.00% | 93,33% | 100,00% | 100.00% | 100.00% | 93.33% | 66.67% | 86.67% |
| Total Percent (average o | The second secon | | 97.78% | | 80.00% | 96.6 | 67% | 100.00% | 96.0 | 67% | 100. | .00% | 96,6 | 7% | 76 | 6.67% |
| Rank (C) GOOD = 9 FAIR = 75° POOR = 0° | 0%-100% %-89.99% | | GOOD | | FAIR | GO | OD | GOOD | GC | OOD | GC | OOD | GOO | OD | F | FAIR |

*Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category and a zero for "Total Percent per Category".

| OVERALL RATING: | DETERMINE AVERAGE PERCENTAGE OF 8 CATEGORIES ABOVE | note its | 93.06% | SCHOOL RATING** | GOOD |
|-----------------|--|----------|--------|-----------------|------|
| | | | | | |

**For School Rating, apply the Percentage Range below to the average percentage determined above, taking into account the rating Description below.

| PERCENTAGE | DESCRIPTION | RATING |
|-------------|---|-----------|
| 99%-100% | The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school. | EXEMPLARY |
| 90%-98.99% | The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated. | GOOD |
| 75.%-89.99% | The school is not in good repair. Some deficiencies noted are critical and/or widespread. Repairs and/or additional maintenance are necessary in several areas of the school site. | FAIR |
| 0%-74.99% | The school facilities are in poor condition. Deficiencies of various degrees have been noted throughout the site. Major repairs and maintenance are necessary throughout the campus. | POOR |

| COMMENTS AND RATING EXPLANATION: | |
|----------------------------------|--|
| | |
| | |
| | |
| | |

Page 5 of 6

| ART II: EVALUATION DE | TAIL | Da | ate of Inspection | 09/06/18 | - | School Name: | Romero E | lementar | School | | | | | <u></u> n | Page 5 |
|---|-----------|------------------|--------------------|----------------------|------------------------|----------------------------|---------------|----------|---------------------|-------------|-----------------------------------|----------------------|----------|-------------------------------|---|
| CATEGORY | 1 | 2 | 3 | 4 11 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 WINDOWS |
| REA | GAS LEAKS | MECH/HVAC | SEWER | INTERIOR SURFACES | OVERALL CLEANLINESS | PEST/VERMIN INFESTATION | ELECTRICAL | RESTROOM | SINKS/ FOUNTAINS | FIRE SAFETY | HAZARDOUS MATERIALS | STRUCTURAL DAMAGE | ROOFS | PLAYGROUND/SC HOOL GROUNDS | DOORS GATES/FEN |
| MEDIA | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | √- | ✓ | ✓ | ✓ | √ | NA | ✓ |
| MEDIA | COMMENTS: | | | 7.1 | | | | | | | | | | | |
| CAEÉMADO | ✓ | ✓ | ✓ | D | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | NA | ✓ |
| CAFE/IVIFK | COMMENTS: | The boys re | estroom has | peeling pain | t. | ••• | | | | • | HAZARDOUS STRUCTURAL DAMAGE ROOFS | | | | |
| MEDIA CAFÉ/MPR TEACHERS LOUNGS PLAYGROUND A-2 B-3 A-1 C-2 C-3 D-1 G-5 B WING RESTROOMS C WING RESTROOMS D WING RESTROOMS | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | √ | √ | ✓ | √ |
| LOUNGS | COMMENTS: | | | | | | | | • | | | | | | *************************************** |
| DI AVODOUND | ✓ | √ | ✓ | ✓ | ✓ | ✓ | ✓ | NA | ✓ | ✓ | ✓ | ✓ | √ | D | ✓ |
| PLATGROUND | COMMENTS: | | | | | | | | | • | | | | | |
| 4.3 | ✓ | √ | ✓ | ✓ | ✓ | ✓ | √ | ✓ | D | ✓ | ✓ | √ | √ | NA | √ |
| A-2 | COMMENTS: | There is a le | oose faucet | | | | | | | , | | | | | |
| | ✓ | ✓ | ✓ | √ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | D | NA | √ |
| 8-3 | COMMENTS: | There is w | vater stain | ed ceiling ti | les. | | | | | | | | | - il | |
| | ✓ | ✓ | ✓ | D | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | NA | √ |
| A-1 | COMMENTS: | There is a h | ole in the w | all near the v | viring that ne | eds to be co | overed. | | | | | | | | |
| 0.0 | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | NA | √ | ✓ | ✓ | ✓ | ✓ | NA | √ |
| U-2 | COMMENTS: | | | | | | | | | | | | | | |
| 0.3 | ✓ | ✓ | ✓ | ✓ | D | ✓ | ✓ | NA | √ | ✓ | ✓ | √ | ✓ | NA | D |
| C-3 | COMMENTS: | The cabinet | t handles ne | ed repair, an | d the baseb | oard neeed | s to be re-gl | ued. | | | | | | | |
| D.4 | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | NA | ✓ |
| | COMMENTS: | | | | | | | | | | | | | | |
| 0.5 | ✓ | D | ✓ | ✓ | ✓ | ✓ | ✓ | NA | √ | ✓ | √ | ✓ | √ | NA | ✓ |
| G-5 | COMMENTS: | There is an A.C. | vent that is loose | 2. | | | | | | | | | | 1 1 | |
| B WING | √ | √ | ✓ | ✓ | ✓ | √ | √ | √ | ✓ | √ | √ | √ | ✓ | NA | √ |
| RESTROOMS | COMMENTS: | | | | | | | | | ! | | | | | |
| C WING | ✓ | ✓ | ✓ | ✓ | ✓ | √ | ✓ | ✓ | √ | √ | √ | √ | ✓ | NA | √ |
| RESTROOMS | COMMENTS: | | | | | | | | | | | - | | | |
| D WING | ✓ | ✓ | ✓ | D | ✓ | √ | √ | √ | ✓ | √ | √ | √ | √ | NA | √ |
| RESTROOMS | COMMENTS: | The girls res | troom has o | lamaged floo | ring under th | ne sink | | | | | | | | | |

| PART II: EVALUATION DE | TAIL | Da | le of Inspection | 09/06/18 | | School Name: | Romero E | lementary | y School | | | | | | Page 5 o |
|------------------------|-----------|--------------|------------------|----------------------|------------------------|----------------------------|------------|-----------|---------------------|-------------|------------------------|----------------------|-------|-------------------------------|----------|
| CATEGORY | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 |
| AREA | GAS LEAKS | MECHINAG | SEWER | INTERIOR SURFACES | OVERALL CLEARLINESS | PEST/VERMIN INFESTATION | ELECTRICAL | RESTROOM | SINKS/ FOUNTAINS | FIRE SAFETY | HAZARDOUS MATERIALS | STRUCTURAL DAMAGE | ROOFS | PLAYGROUND/SC HOOL GROUNDS | DOORS? |
| E WING | ✓ | ✓ | \checkmark | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | D |
| RESTROOMS | COMMENTS: | The stalls a | re rusting o | ut. | | | | | | - | | · | | | |

Marks: $\sqrt{\ }$ = Good Repair; **D** = Deficiency; **X** = Extreme Deficiency; **NA** = Not Applicable
Use additional Area Lines as necessary.

Gustine Unified School District 2018-2019 Williams Monitoring

| | | al Materials | Crede | ntials | Facilities | | SARC | Additional | |
|---------------|-------------------------------------|---------------|----------------------------|------------------|------------------------|--------|-----------------------------|--------------------------|--|
| Gustine | Deficiencies Identified By Grade | Date Resolved | Deficiencies Identified | Date Resolved | Emergencies Identified | Score | Discrepancies Identified | Settlement Monitoring | |
| Romero ESD | None | | None | | None | 93.06% | None | NA | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |