

75

Valenzuela/CAHSEE Lawsuit Settlement
Quarterly Report on Williams Uniform Complaints
[Education Code §35186(d)]

District: Bishop Unified School District

Date: 12/29/2017

Person completing this form: Midge Milici

Title: Chief Business Officer

Quarterly Report Submission Date:
(check one)

- October 2017 (Jul – Sep)
- January 2018 (Oct – Dec)
- April 2018 (Jan – Mar)
- July 2018 (Apr – Jun)


Date for information to be reported publicly at governing board meeting: January 18, 2018

Please check the box that applies:

- No complaints were filed with any school in the district during the quarter indicated above.
- Complaints were filed with schools in the district during the quarter indicated above. The following chart summarizes the nature and resolution of these complaints.

General Subject Area	Total # of Complaints	# Resolved	# Unresolved
Textbooks and Instructional Materials			
Teacher Vacancy or Misassignment			
Facilities Conditions			
CAHSEE Intensive Instruction and Services			
TOTALS			

Barry Simpson
Print Name of District Superintendent


Signature of District Superintendent

01/04/2018
Date

SCHOOL DISTRICT/COUNTY OFFICE OF EDUCATION		COUNTY
Bishop Unified School District		Inyo
SCHOOL SITE	SCHOOL TYPE (GRADE LEVELS)	NUMBER OF CLASSROOMS ON SITE
Palisades Glacier High School	Tenth - twelfth	4
INSPECTOR'S NAME	NAME OF DISTRICT REPRESENTATIVE ACCOMPANYING THE INSPECTOR(S) (IF APPLICABLE)	
Todd Remley	Katie Kolker	
INSPECTOR'S TITLE		
MOT Director		
TIME OF INSPECTION		
11:00	Cool	

PART III: CATEGORY TOTALS AND RANKING (round all calculations to two decimal places)

TOTAL NUMBER OF AREAS EVALUATED	A. SYSTEMS			B. INTERIOR INTERIOR SURFACES	C. CLEANLINESS		D. ELECTRICAL ELECTRICAL	E. RESTROOMS/FOUNTAINS		F. SAFETY		G. STRUCTURAL		H. EXTERNAL	
	GAS LEAKS	MECH/HVAC	SEWER		OVERALL CLEANLINESS	PEST/VERMIN INFESTATION		RESTROOMS	SINKS/FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUND/ SCHOOL GROUNDS	WINDOWS/DOORS/ GATES/FENCES
7	6	7	3	7	7	7	7	1	2	7	7	7	7	7	7
	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
	1	0	4	0	0	0	0	6	5	0	0	0	0	0	0
Percent of System in Good Repair Number of "v"s divided by (Total Areas - "NA"s)*	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%
Total Percent per Category (average of above)*	100.00%			100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%
Rank (Circle one) GOOD = 90%-100% FAIR = 75%-89.99% POOR = 0%-74.99%	GOOD			GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD

*Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category and a zero for "Total Percent per Category".

OVERALL RATING: DETERMINE AVERAGE PERCENTAGE OF 8 CATEGORIES ABOVE → 100.00% → SCHOOL RATING** → EXEMPLARY

**For School Rating, apply the Percentage Range below to the average percentage determined above, taking into account the rating Description below.

PERCENTAGE	DESCRIPTION	RATING
99%-100%	The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.	EXEMPLARY
90%-98.99%	The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.	GOOD
75 %-89.99%	The school is not in good repair. Some deficiencies noted are critical and/or widespread. Repairs and/or additional maintenance are necessary in several areas of the school site.	FAIR
0%-74.99%	The school facilities are in poor condition. Deficiencies of various degrees have been noted throughout the site. Major repairs and maintenance are necessary throughout the campus.	POOR

COMMENTS AND RATING EXPLANATION:

Siding to be placed on the five year plan. Due to cost, the project will be completed over 3 years.

PART II: EVALUATION DETAIL		School Name: Palisades Glacier High School													
		Date of Inspection: 12/28/11													
CATEGORY	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
AREA	GAS LEAKS	MECH/HVAC	SEWER	INTERIOR SURFACES	OVERALL CLEANLINESS	PEST/VERMIN INFESTATION	ELECTRICAL	RESTROOM	SINKS/ FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUND/ SCHOOL GROUNDS	WINDOWS/ DOORS/ GATES/FENCES
Restroom Bldg	NA	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:														
Office Bldg	✓	✓	NA	✓	✓	✓	✓	NA	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:														
English Bldg	✓	✓	NA	✓	✓	✓	✓	NA	NA	✓	✓	✓	✓	✓	✓
	COMMENTS:														
Science Bldg	✓	✓	✓	✓	✓	✓	✓	NA	NA	✓	✓	✓	✓	✓	✓
	COMMENTS:														
Social Sciences Bldg	✓	✓	NA	✓	✓	✓	✓	NA	NA	✓	✓	✓	✓	✓	✓
	COMMENTS:														
Computer Lab	✓	✓	✓	✓	✓	✓	✓	NA	NA	✓	✓	✓	✓	✓	✓
	COMMENTS:														
Tool Shed, Pump House, Storage Area	✓	✓	NA	✓	✓	✓	✓	NA	NA	✓	✓	✓	✓	✓	✓
	COMMENTS:														
	COMMENTS:														
	COMMENTS:														
	COMMENTS:														
	COMMENTS:														
	COMMENTS:														

Marks: ✓ = Good Repair (When filling up the electronic version, please use **ctrl+G**); D = Deficiency; X = Extreme Deficiency; NA = Not Applicable
Use additional sheets as necessary.

SCHOOL DISTRICT/COUNTY OFFICE OF EDUCATION		COUNTY
Bishop Unified School District		Inyo
SCHOOL SITE	SCHOOL TYPE (GRADE LEVELS)	NUMBER OF CLASSROOMS ON SITE
Bishop Union High School	Nine - Twelve	38
INSPECTOR'S NAME	NAME OF DISTRICT REPRESENTATIVE ACCOMPANYING THE INSPECTOR(S) (IF APPLICABLE)	
Todd Remley	Randy Cook, Principal	
INSPECTOR'S TITLE	WEATHER CONDITION AT TIME OF INSPECTION	
MOT Director	Cool	
TIME OF INSPECTION		
10:00		

PART III: CATEGORY TOTALS AND RANKING (round all calculations to two decimal places)

TOTAL NUMBER OF AREAS EVALUATED	CATEGORY TOTALS	A. SYSTEMS			B. INTERIOR SURFACES	C. CLEANLINESS	D. ELECTRICAL		E. RESTROOMS/FOUNTAINS		F. SAFETY		G. STRUCTURAL		H. EXTERNAL	
		GAS LEAKS	MECH/NVAC	SEWER			OVERALL CLEANLINESS	PEST/VERMIN INFESTATION	ELECTRICAL	RESTROOMS	SINKS/FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUND/SCHOOL GROUNDS
↓	Number of "V"s:	8	8	7	8	8	8	8	8	8	8	8	8	8	6	8
	Number of "D"s:	0	0	1	0	0	0	0	0	0	0	0	0	0	2	0
	Number of "X"s:	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
	Number of N/A's:	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
	Percent of System in Good Repair (Number of "V"s divided by (Total Areas - "N/A"s)*)	100.00%	100.00%	87.50%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	75.00%	100.00%
	Total Percent per Category (average of above)	95.83%		87.50%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	87.50%	87.50%	
	Rank (Circle one) GOOD = 90%-100% FAIR = 75%-89.99% POOR = 0%-74.99%	GOOD		FAIR	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	FAIR	

*Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category and a zero for "Total Percent per Category".

OVERALL RATING: DETERMINE AVERAGE PERCENTAGE OF 8 CATEGORIES ABOVE → 96.35% → SCHOOL RATING** → GOOD

**For School Rating, apply the Percentage Range below to the average percentage determined above, taking into account the rating Description below.

PERCENTAGE	DESCRIPTION	RATING
99%-100%	The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.	EXEMPLARY
90%-98.99%	The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.	GOOD
75 %-99.99%	The school is not in good repair. Some deficiencies noted are critical and/or widespread. Repairs and/or additional maintenance are necessary in several areas of the school site.	FAIR
0%-74.99%	The school facilities are in poor condition. Deficiencies of various degrees have been noted throughout the site. Major repairs and maintenance are necessary throughout the campus.	POOR

COMMENTS AND RATING EXPLANATION:

PART II: EVALUATION DETAIL Date of Inspection: 12/28/17 School Name: Bishop Union High School

CATEGORY	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
AREA	GAS LEAKS	MECH/HVAC	SEWER	INTERIOR SURFACES	OVERALL CLEANLINESS	PEST/VERMIN INFESTATION	ELECTRICAL	RESTROOM	SINKS/ FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUND/ SCHOOL GROUNDS	WINDOWS/ DOORS/ GATES/FENCES
Bldg 100	✓	✓	✓	D	✓	✓	✓	✓	✓	✓	✓	✓	✓	D	✓
	COMMENTS: Multiple damaged flooring areas.														
Bldg 200	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	D	✓
	COMMENTS: Tree roots have lifted pipe - trip hazard, mall area.														
Bldg 300	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:														
Group 400	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:														
Group 500	✓	✓	D	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS: Tree roots have lifted pipe - trip hazard, mall area.														
Bldg 600	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:														
Bldg 700	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:														
Bldg 800	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:														
	COMMENTS:														
	COMMENTS:														
	COMMENTS:														
	COMMENTS:														
	COMMENTS:														

Marks: ✓ = Good Repair (When filling up the electronic version, please use ctrl+G); D = Deficiency; X = Extreme Deficiency; NA = Not Applicable
 Use additional sheets as necessary.

SCHOOL DISTRICT/COUNTY OFFICE OF EDUCATION		COUNTY
Bishop Unified School District		Inyo
SCHOOL SITE	SCHOOL TYPE (GRADE LEVELS)	NUMBER OF CLASSROOMS ON SITE
Bishop Elementary	K - 5	50
INSPECTOR'S NAME	NAME OF DISTRICT REPRESENTATIVE ACCOMPANYING THE INSPECTOR(S) (IF APPLICABLE)	
Todd Remley	Heather Carr - Principal	
INSPECTOR'S TITLE	INSPECTOR'S TITLE	
MOT Director	MOT Director	
TIME OF INSPECTION	WEATHER CONDITION AT TIME OF INSPECTION	
9:00	Cool	

PART III: CATEGORY TOTALS AND RANKING (round all calculations to two decimal places)

TOTAL NUMBER OF AREAS EVALUATED	CATEGORY TOTALS	A. SYSTEMS			B. INTERIOR INTERIOR SURFACES	C. CLEANLINESS OVERALL CLEANLINESS	D. ELECTRICAL ELECTRICAL	E. RESTROOMS/FOUNTAINS		F. SAFETY FIRE SAFETY	G. STRUCTURAL STRUCTURAL DAMAGE	H. EXTERNAL PLAYGROUND/ SCHOOL GROUNDS		WINDOWS/DOORS/ GATES/FENCES
		GAS LEAKS	MECH/HVAC	SEWER				RESTROOMS	SINKS/ FOUNTAINS			HAZARDOUS MATERIALS	ROOFS	
↓	Number of "Y"s:	8	8	8	7	8	8	7	8	8	8	8	8	8
	Number of "D"s:	0	0	0	1	0	0	1	0	0	0	0	0	0
	Number of "X"s:	0	0	0	0	0	0	0	0	0	0	0	0	0
	Number of N/A's:	0	0	0	0	0	0	0	0	0	0	0	0	0
	Percent of System in Good Repair	100.00%	100.00%	100.00%	87.50%	100.00%	100.00%	87.50%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%
	Number of "Y"s divided by (Total Areas - "N/A"s)*	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	93.75%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%
	Total Percent per Category (average of above)*	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	93.75%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%
	Rank (Circle one)	GOOD												
	GOOD = 90%-100%													
	FAIR = 75%-89.99%													
	POOR = 0%-74.99%													

*Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category and a zero for "Total Percent per Category".

OVERALL RATING: DETERMINE AVERAGE PERCENTAGE OF 8 CATEGORIES ABOVE → 99.22% → **SCHOOL RATING**** → **EXEMPLARY**

**For School Rating, apply the Percentage Range below to the average percentage determined above, taking into account the rating Description below.

PERCENTAGE	DESCRIPTION	RATING
99%-100%	The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.	EXEMPLARY
90%-98.99%	The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.	GOOD
75.-%-89.99%	The school is not in good repair. Some deficiencies noted are critical and/or widespread. Repairs and/or additional maintenance are necessary in several areas of the school site.	FAIR
0%-74.99%	The school facilities are in poor condition. Deficiencies of various degrees have been noted throughout the site. Major repairs and maintenance are necessary throughout the campus.	POOR

COMMENTS AND RATING EXPLANATION:

CATEGORY	AREA	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
		GAS LEAKS	MECH/HVAC	SEWER	INTERIOR SURFACES	OVERALL CLEANLINESS	PEST/VERMIN INFESTATION	ELECTRICAL	RESTROOM	SINKS/ FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUND/ SCHOOL GROUNDS	WINDOWS/ DOORS/ GATES/FENCES
Kindergarten		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:															
First Grade		✓	✓	✓	✓	✓	✓	✓	D	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:	Restroom needs patch and paint.														
Second Grade		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:															
Office Buildings		✓	✓	✓	D	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:	Office floor needs new flooring.														
Third/Fourth Grade		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:															
Bungalows		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:															
Fifth Grade		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:															
BAC		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:															
	COMMENTS:															
	COMMENTS:															
	COMMENTS:															

Marks: ✓ = Good Repair (When filling up the electronic version, please use ctrl+G); D = Deficiency; X = Extreme Deficiency; NA = Not Applicable
 Use additional sheets as necessary.

SCHOOL DISTRICT/COUNTY OFFICE OF EDUCATION		COUNTY	
Bishop Unified School District		Inyo	
SCHOOL SITE		SCHOOL TYPE (GRADE LEVELS)	NUMBER OF CLASSROOMS ON SITE
Home Street Middle School		Six - Eight	25
INSPECTOR'S NAME		NAME OF DISTRICT REPRESENTATIVE ACCOMPANYING THE INSPECTOR(S) (IF APPLICABLE)	
Todd Remley		Patrick Twomey	
INSPECTOR'S TITLE			
MOT Director			
TIME OF INSPECTION		WEATHER CONDITION AT TIME OF INSPECTION	
9:30		Cool	

PART III: CATEGORY TOTALS AND RANKING (round all calculations to two decimal places)

TOTAL NUMBER OF AREAS EVALUATED	CATEGORY TOTALS	A. SYSTEMS			B. INTERIOR	C. CLEANLINESS		D. ELECTRICAL	E. RESTROOMS/FOUNTAINS		F. SAFETY		G. STRUCTURAL		H. EXTERNAL		
		GAS LEAKS	MECH/HVAC	SEWER		INTERIOR SURFACES	OVERALL CLEANLINESS		PEST/VERMIN INFESTATION	ELECTRICAL	RESTROOMS	SIWS/ FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUND/ SCHOOL GROUNDS
↓	Number of "1's":	6	6	6	3	6	6	6	6	6	6	6	6	6	5	6	
	Number of "0's":	0	0	0	3	0	0	0	0	0	0	0	0	0	1	0	
	Number of "X's":	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
	Number of N/A's:	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
	Percent of System in Good Repair	100.00%	100.00%	100.00%	50.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	83.33%	100.00%	
	Number of "✓'s" divided by (Total Areas - "NA's")																
	Total Percent per Category (average of above)	100.00%			50.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	91.67%	91.67%	
	Rank (Circle one)																
	GOOD = 90%-100%																
	FAIR = 75%-89.99%																
	POOR = 0%-74.99%																
		GOOD	GOOD	GOOD	POOR	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD

*Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category and a zero for "Total Percent per Category".

OVERALL RATING: DETERMINE AVERAGE PERCENTAGE OF 8 CATEGORIES ABOVE → 92.71% → SCHOOL RATING** → GOOD

**For School Rating, apply the Percentage Range below to the average percentage determined above, taking into account the rating Description below.

PERCENTAGE	DESCRIPTION	RATING
99%-100%	The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.	EXEMPLARY
90%-98.99%	The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.	GOOD
75 %-89.99%	The school is not in good repair. Some deficiencies noted are critical and/or widespread. Repairs and/or additional maintenance are necessary in several areas of the school site.	FAIR
0%-74.99%	The school facilities are in poor condition. Deficiencies of various degrees have been noted throughout the site. Major repairs and maintenance are necessary throughout the campus.	POOR

COMMENTS AND RATING EXPLANATION:

AREA	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	
CATEGORY	GAS LEAKS	MECH/HVAC	SEWER	INTERIOR SURFACES	OVERALL CLEANLINESS	PEST/VERMIN INFESTATION	ELECTRICAL	RESTROOM	SINKS/ FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUND/ SCHOOL GROUNDS	WINDOWS/ DOORS/ GATES/FENCES	
6th Wing	✓	✓	✓	D	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	COMMENTS:	Restroom needs patch and paint.														
7th Wing	✓	✓	✓	D	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	COMMENTS:	Restroom needs patch and paint.														
8th Wing	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	COMMENTS:															
Main Hall	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	D	✓	
	COMMENTS:	Curb by handicap ramp uneven														
Science/Music	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	COMMENTS:															
MP Room	✓	✓	✓	D	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	COMMENTS:	Restroom needs patch and paint.														
	COMMENTS:															
	COMMENTS:															
	COMMENTS:															
	COMMENTS:															
	COMMENTS:															
	COMMENTS:															
	COMMENTS:															
	COMMENTS:															

Marks: ✓ = Good Repair (When filling up the electronic version, please use **ctrl+G**); D = Deficiency; X = Extreme Deficiency; NA = Not Applicable
 Use additional sheets as necessary.