

Water Sampling Log

Name of Building
Building Owner

Madison High School
Madison Board of Education

Date Collected 12-Aug-21
Sample Collected by _____

Sample No.	Tap No.	Sample Type	Type of Outlet	Manufacturer		Time	Results (mg/L)	
							Cu	Pb
RK-081221-01	1	1st	Sink		Kitchen, center alley, food prep area	7:25	0.189	0.0064
RK-081221-02	2	1st	Coffee Maker		Kitchen	7:26	0.236	0.0088
RK-081221-03	3	1st	Chiller		Lunch Room	7:33	0.373	0.0021
RK-081221-04	4	1st	Chiller		A Hallway, next to Boys' Room, left side	7:38	0.255	< 0.0010
RK-081221-05	5	1st	Chiller		A Hallway, next to Boys' Room, right side	7:39	0.246	< 0.0010
RK-081221-06	6	1st	Bubbler		A Hallway, next to Room A4, left side	7:45	0.148	0.0027
RK-081221-07	7	1st	Bubbler		A Hallway, next to Room A4, right side	7:46	0.073	< 0.0010
RK-081221-08	8	1st	Coffee Maker		Main Office, work room	7:50	0.334	0.0014
RK-081221-09	9	1st	Bubbler		B Hallway, across from Main Office/Guidance, right side	7:58	0.118	< 0.0010
RK-081221-10	10	1st	Chiller		F Hallway, by Boys' Room, left side	8:05	0.192	< 0.0010
RK-081221-11	11	1st	Chiller		F Hallway, by Boys' Room, right side	8:06	0.339	0.0014
RK-081221-12	12	1st	Bubbler		Gym Hallway outside girl's locker room	8:10	0.039	< 0.0010
RK-081221-13	13	1st	Sink		Trainer's Office, next to Ice Machine	8:17	0.283	< 0.0010
RK-081221-14	14	--	Ice Machine		Ice Machine, next to Trainer's Office	8:18	0.090	< 0.0010
RK-081221-15	15	1st	Sink		Health Office	8:23	0.163	0.0112
RK-081221-16	16	1st	Bottle Filler		C Hallway, by Girls' Room, left side	7:05	0.274	< 0.0010
RK-081221-17	17	1st	Chiller		C Hallway, by Girls' Room, right side	7:06	0.213	< 0.0010
RK-081221-18	18	1st	Bottle Filler		C Hallway, by Boys' Room, right side	7:10	0.078	< 0.0010
RK-081221-19	19	1st	Bottle Filler		G Hallway, across from Rooms G51/G52, right side	8:30	0.129	< 0.0010
RK-081221-20	20	1st	Bubbler		G Hallway, across from Rooms G57/G58, left side	8:35	0.284	0.0011

Sample Type: **1st:** First Draw sample collected after water sat in pipe between 8 and 18 hours
FL: Water flushed through tap for at least 2 minutes
 <: means Not Detected at or above the Reliability Detection Limit (RDL) of 0.0010 mg/L for Lead.

Water Sampling Log

Name of Building Madison High School
 Building Owner Madison Board of Education

Date Collected 12-Aug-21
 Sample Collected by _____

Sample No.	Tap No.	Sample Type	Type of Outlet	Manufacturer	Location	Time	Results (mg/L)	
							Cu	Pb
RK-081221-21	21	1st	Bubbler		G Hallway, across from Rooms G57/G58, right side	8:36	0.273	< 0.0010
RK-081221-22	22	1st	Fountain		Near Baseball field	8:45	0.208	0.0044
RK-081221-23	23	1st	Fountain		Far Baseball field	8:48	0.009	0.0038
RK-081221-24	24	1st	Sink		snack bar by football field	8:50	0.764	0.0423

Sample Type: **1st**: First Draw sample collected after water sat in pipe between 8 and 18 hours
FL: Water flushed through tap for at least 2 minutes
 <: means Not Detected at or above the Reliability Detection Limit (RDL) of 0.0010 mg/L for Lead.

Water Sampling Log

Name of Building
Building Owner

Madison Junior School
Madison Board of Education

Date Collected 12-Aug-21
Sample Collected by _____

Sample No.	Tap No.	Sample Type	Type of Outlet	Manufacturer		Time	Results (mg/L)	
							Cu	Pb
RK-081221-102	1	1st	Bottle Filler	Elkay	Hallway, next to Room 102, right side (low flow)	7:37	0.132	< 0.0010
RK-081221-103	2	1st	Bottle Filler	Elkay	1st Floor Elevator Lobby	7:38	0.113	< 0.0010
RK-081221-104	3	1st	Sink		Nurse's Office	7:39	0.111	0.0011
RK-081221-105	4	1st	Sink		Faculty Room	7:40	0.073	< 0.0010
RK-081221-106	5	1st	Hose Filler		Kitchen - hose filler in center of room	7:44	0.079	0.0185
RK-081221-107	6	1st	Bottle Filler	Elkay	Hallway, outside Gym, across from Room 111	7:46	0.742	< 0.0010
RK-081221-108	7	1st	Fountain	Elkay	Boy's Locker Room	7:50	0.190	0.0032
RK-081221-109	8	1st	Chiller	Haws	2nd Floor Elevator Lobby	7:54	0.226	0.0097
RK-081221-110	9	1st	Bottle Filler	Elkay	Hallway, next to Room 217, left side	7:55	0.096	< 0.0010

Sample Type: **1st:** First Draw sample collected after water sat in pipe between 8 and 18 hours
FL: Water flushed through tap for at least 2 minutes
 <: means Not Detected at or above the Reliability Detection Limit (RDL) of 0.0010 mg/L for Lead.

Water Sampling Log

Name of Building
Building Owner

Central Avenue Elementary School
Madison Board of Education

Date Collected 11-Aug-21
Sample Collected by Adam R. Simon

Sample No.	Tap No.	Sample Type	Type of Outlet	Manufacturer		Time	Results (mg/L)	
							Cu	Pb
RK-081121-CA01	1	1st	Bottle Filler	Elkay	Hallway, next to Room 103, left side	09:16	0.051	< 0.0010
RK-081121-CA02	2	1st	Sink		Faculty Work Room	09:17	0.135	< 0.0010
RK-081121-CA03	3	1st	Bottle Filler	Elkay	2nd Floor 'Hallway, next to bathrooms	09:18	0.004	< 0.0010
RK-081121-CA04	4	1st	Bottle Filler	Elkay	Hallway - across from Room #3	09:19	0.036	< 0.0010
RK-081121-CA05	5	1st	Sink		Main Office	09:20	0.121	< 0.0010
RK-081121-CA06	6	1st	Bubbler		Nurse's Office	09:21	0.181	0.0014
RK-081121-CA07	7	1st	Chiller	Halsey Taylor	Hallway, next to Room 13, left side	09:23	0.131	< 0.0010
RK-081121-CA08	8	1st	Chiller	Halsey Taylor	Hallway, next to Room 13, right side	09:23	0.170	< 0.0010

Sample Type: **1st:** First Draw sample collected after water sat in pipe between 8 and 18 hours
FL: Water flushed through tap for at least 2 minutes
 <: means Not Detected at or above the Reliability Detection Limit (RDL) of 0.0010 mg/L for Lead.

Water Sampling Log

Name of Building
Building Owner

Kings Road Elementary School
Madison Board of Education

Date Collected 12-Aug-21
Sample Collected by _____

Sample No.	Tap No.	Sample Type	Type of Outlet	Manufacturer		Time	Results (mg/L)	
							Cu	Pb
RK-081221-201	1	1st	Fountain		Faculty Work Room	8:25	0.161	0.0032
RK-081221-202	2	1st	Bottle Filler	Elkay	1st Floor Hallway, by Boy's Room	8:27	0.327	< 0.0010
RK-081221-203	3	1st	Fountain		2nd Floor Hallway, by Boy's Room, left side	8:29	0.273	< 0.0010
RK-081221-204	4	1st	Fountain		2nd Floor Hallway, by Boy's Room, right side	8:31	0.364	0.0193
RK-081221-205	5	1st	Sink		Room 4	8:32	0.390	0.0042
RK-081221-206	6	1st	Bubbler		Nurse's Office	8:35	0.155	< 0.0010
RK-081221-207	7	1st	Ceramic Bubbler		Hallway by Room 7, between bathrooms, left side	8:35	0.156	< 0.0010
RK-081221-208	8	1st	Ceramic Bubbler		Hallway by Room 7, between bathrooms, center	8:37	0.128	< 0.0010
RK-081221-209	9	1st	Ceramic Bubbler		Hallway by Room 7, between bathrooms, right side	8:39	0.125	< 0.0010

Sample Type: **1st:** First Draw sample collected after water sat in pipe between 8 and 18 hours
FL: Water flushed through tap for at least 2 minutes
<: means Not Detected at or above the Reliability Detection Limit (RDL) of 0.0010 mg/L for Lead.

Water Sampling Log

Name of Building
Building Owner

Tory Sabatini Elementary School
Madison Board of Education

Date Collected 12-Aug-21
Sample Collected by _____

Sample No.	Tap No.	Sample Type	Type of Outlet	Manufacturer		Time	Results (mg/L)	
							Cu	Pb
RK-081221-301	1	1st	Bottle Filler	Elkay	Multi-Purpose Room, next to Room 112	9:30	0.118	< 0.0010
RK-081221-302	2	1st	Ceramic Bubbler	elkay	Hallway, between Boys' Room and Men's Faculty Room	9:40	0.137	< 0.0010
RK-081221-303	3	1st	Ceramic Bubbler	standard	Hallway, next to Room 120 (low flow)	9:42	0.150	0.0052
RK-081221-304	4	1st	Sink		Faculty Work Room	9:45	0.262	0.0011
RK-081221-305	5	1st	Chiller	Elkay	Hallway, next to Room 122, left side	9:48	0.161	< 0.0010
RK-081221-306	6	1st	Bottle Filler		Hallway next to Room 122 - Rightside	9:49	0.125	< 0.0010
RK-081221-307	7	1st	Fountain		Hallway, next to Room 218	9:54	0.325	0.0027
RK-081221-308	8	1st	Bubbler		Nurse's Office	9:56	0.378	< 0.0010
RK-081221-309	9	1st	Ceramic Bubbler		2nd Floor Hallway, across from Room 205	9:58	0.154	< 0.0010
RK-081221-310	10	1st	Sink		Kitchen Sink	9:32	0.787	0.0218

Sample Type: **1st:** First Draw sample collected after water sat in pipe between 8 and 18 hours
FL: Water flushed through tap for at least 2 minutes
 <: means Not Detected at or above the Reliability Detection Limit (RDL) of 0.0010 mg/L for Lead.

Water Sampling Log

Name of Building _____ (see below)
 Building Owner Madison Board of Education

Date Collected 12-Aug-21
 Sample Collected by _____

Sample No.	Tap No.	Sample Type	Type of Outlet	Manufacturer		Time	Results (mg/L)	
							Cu	Pb
					<u>Board Office</u>			
RK-081221-401	1	1 st	Faucet		1st Floor restroom sink	8:53	0.097	0.0091
					<u>Bus Garage</u>			
RK-081221-501	1	1 st	Faucet		Lunch Room sink	7:21	0.168	< 0.0010

Sample Type: **1st:** First Draw sample collected after water sat in pipe between 8 and 18 hours
FL: Water flushed through tap for at least 2 minutes
 <: means Not Detected at or above the Reliability Detection Limit (RDL) of 0.0010 mg/L for Lead.