

## Water Testing Results - Lake County School District #7

### Action Level is 20 parts per billion (ppb)

Fixture Location/Description	Fixture ID #	Test Date	Test Result	Remediation
LHS Cafeteria Drinking Fountain	20590401-005DW	8/22/2016	27.8 ppb	Faucet replaced October 2016
LHS Agriculture Shop Facility Drinking Fountain	20590402-006DW	8/22/2016	14.2 ppb	
LHS Wood Shop Facility Drinking Fountain	20590402-007DW	8/22/2016	8.1 ppb	
LHS Cafeteria Sink - South Wall	20590401-008KF	8/22/2016	31.4 ppb	Faucet replaced October 2016
LHS Cafeteria Sink - East Wall	20590401-009KF	8/22/2016	11.4 ppb	
LHS Gym Drinking Fountain	20590401-010DW	8/22/2016	16.7 ppb	
LHS South Hallway Drinking Fountain	20590401-001DW	8/22/2016	3.27 ppb	
LHS Science Room Fountain	20590401-002DW	8/22/2016	18.5 ppb	
LHS North Hallway Drinking Fountain West	20590401-003DW	8/22/2016	3.04 ppb	
LHS North Hallway Drinking Fountain East	20590401-004DW	8/22/2016	1.03 ppb	
LHS Football Concession Building - No test conducted				
LHS Baseball Concession Building - No test conducted				
Fremont North Hallway Drinking Fountain East	20590202-001DW	8/23/2016	23.7 ppb	Fountain replaced October 2016
Fremont North Hallway Drinking Fountain West	20590202-002DW	8/23/2016	20.7 ppb	Fountain replaced October 2016
Fremont Classroom Drinking Fountain # 270	20590202-003DW	8/23/2016	36.7 ppb	Shut down, taped off..
Fremont Upstairs Hallway Drinking Fountain #4	20590202-004DW	8/23/2016	4.15 ppb	
Fremont Upstairs Classroom Drinking Fountain #274	20590202-005DW	8/23/2016	3.2 ppb	
Fremont Teachers Lounge Sink	20590202-006SF	8/23/2016	15.9 ppb	
A.D. Hay South Hallway Drinking Fountain	20590201-001DW	8/3/2016	13.6 ppb	
A.D. Hay Classroom #234 Drinking Fountain	20590201-002DW	8/3/2016	11.1 ppb	
A.D. Hay Classroom #209 Drinking Fountain	20590201-003DW	8/3/2016	11.3 ppb	
A.D. Hay North Hallway Fountain	20590201-004DW	8/3/2016	4.38 ppb	
A.D. Hay Classroom #216 Drinking Fountain	20590201-005DW	8/3/2016	5.58 ppb	
A.D. Hay Classroom #235 Drinking Fountain	20590201-006DW	8/23/2016	66.6 ppm	Shut down, taped off.
A.D. Hay Cafeteria Sink	20590201-007KF	8/23/2016	18.4 ppb	
A.D. Hay Teachers Lounge Sink	20590201-008SF	8/23/2016	42.7 ppb	Faucet replacement
Daly Middle School Upper Hallway Drinking Fountain	20590301-001DW	8/22/2016	24.4 ppb	Replaced with new fountain and bottle station.
Daly Middle School Lower Hallway Drinking Fountain	20590301-002DW	8/22/2016	8.70 ppb	
Daly Middle School Music Room Fountain	20590301-003DW	8/22/2016	9.14 ppb	
Daly Middle School North Wing Main Floor Fountain	20590301-004DW	8/22/2016	8.64 ppb	
Daly Middle School Home Ec. Room Fawcett	20590301-005KF	8/22/2016	7.74 ppb	
Daly Middle School Home Ec. Room Fountain	20590301-006DW	8/22/2016	16.4 ppb	
Union School - Well water, cafeteria	20590101-001KF	8/3/2016	8.59 ppb	Bottled Water is used for drinking in every classroom.

**ND = Non Detect - Lead level is below the set detection limits**