

## **Indoor Air Quality Report**

### **Liberty OHM File Number 12-179**

**Survey Location:** Bixby Central Intermediate

**Office #111** 

9401 E. 161<sup>st</sup> St. S. Bixby, OK 74008

**Survey Date:** April 1<sup>st</sup>, 2013

**Report Date:** April 4<sup>th</sup>, 2013

**Prepared For:** Mr. Marty Foutch

Facilities Director 109 N. Armstrong Bixby, OK 74008

CC: Jarred Doubrava

**Operations Support Manager/District** 

**Safety Coordinator** 

**Prepared By:** Jack Kerr

**EH&S Consultant** 

**Liberty OHM** 

Bixby Central Intermediate – Office 111 IAQ Liberty OHM File Number 12-179

Survey Date: 4/1/2013 Report Date: 4/4/2013

Page: 2

### **CONTENTS**

1.0 **SUMMARY** 

2.0 **OBSERVATIONS AND NOTES** 

3.0 ANALYSIS AND RECOMMENDATIONS

APPENDIX A

LABORATORY RESULTS

Bixby Central Intermediate – Office 111 IAQ

Liberty OHM File Number 12-179

Survey Date: 4/1/2013 Report Date: 4/4/2013

Page: 3

#### 1.0 **SUMMARY**

On April 1<sup>st</sup>, 2013, Liberty OHM visited Bixby Central Intermediate located at 9401 E. 161<sup>st</sup> St. S., Bixby, OK. The purpose of this visit was to perform a survey and sampling in order to determine the type, concentration and causation of any mold/fungi present.

The ratio of *total* (all species combined) indoor/outdoor airborne mold concentrations <u>was not</u> elevated on the day of testing. There were no higher than outside concentrations of the water intrusion/indicator mold Penicillium/Aspergillus and/or Stachybotrys in the office on the day of testing. See Section 3.0 for detailed analysis and recommendations.

#### 2.0 OBSERVATIONS AND NOTES

Liberty OHM arrived on site and was met by Jarred Doubrava of Bixby Public Schools. Mr. Doubrava proceeded to escort us to Office #111 and show us all suspect areas. No carpet staining was noticed throughout the office. No water staining was noticed on ceiling tiles, walls, etc. A moisture meter was used to check the percent of moisture in walls throughout Office #111. No high levels of moisture were observed on day of testing.

#### 3.0 ANALYSIS AND RECOMMENDATIONS

The following areas were selected for testing:

- 1. Office #111 (Air)
- 2. Outside Reference (Air)

Results are summarized in Table 1 below.

Bixby Central Intermediate – Office 111 IAQ

Liberty OHM File Number 12-179

Survey Date: 4/1/2013 Report Date: 4/4/2013

Page: 4

# Table 1 Bixby Central Intermediate – Office #111 IAQ Spore Trap Analysis Sample Date: 4/1/13

Location	Total spores/m3	Species	Raw count	Calc. count	% of total
1: Office 111	340	Cladosporium	21	140	41
		Alternaria	11	73	22
		Penicillium/Aspergillus types	6	40	12
		Ascospores	6	40	12
		Basidiospores	5	33	10
		Smuts, Periconia, Myxomycetes	1	7	2
		Other brown	1	7	2
2: Outside	6,600	Cladosporium	22	5,900	88
Reference		Basidiospores	43	290	4
		Alternaria	33	220	3
		Bipolaris/Drechslera group	21	140	2
		Penicillium/Aspergillus types	10	67	1
		Ascospores	9	60	1
		Epicoccum	1	7	< 1

Interpretation of the findings have been addressed in the following four ways: 1) Indoor/outdoor concentration ratios 2) Comparisons of the species compositions indoors and out 3) The presence of indicator species in the indoor environment, and 4) Visual inspection.

Our investigation of the property using the above criteria indicates the following:

- 1. The ratio of *total* (all species combined) indoor/outdoor airborne mold concentrations was not elevated on the day of testing. There were no higher than outside concentrations of Penicillium/Aspergillus.
- 2. Comparing the types of airborne mold present in the property, they are typically similar to those isolated in the outside air.
- 3. The laboratory classifies Penicillium/Aspergillus as a water intrusion/indicator mold. Higher than outside concentrations of Penicillium/Aspergillus are indicative of an environment that has been subjected to excessive moisture.

Bixby Central Intermediate – Office 111 IAQ

Liberty OHM File Number 12-179

Survey Date: 4/1/2013 Report Date: 4/4/2013

Page: 5

Recommendations are provided below. See Appendix A for detailed laboratory results, indoor/outdoor comparison ratios, and fungal descriptions.

#### Recommendations

• No recommendations are provided at this time. Liberty OHM will continue to monitor this room during the next 25% sampling at Central Intermediate.

\*Recommendations are based in part on professional publication guidelines including the IICRC S500 Standard and Reference Guide for Professional Water Damage Restoration and IICRC S520 Standard and Reference Guide for Professional Mold Remediation.

#### Disclaimer

Liberty OHM makes no assertion as to the health risks associated with the levels reported in this report. We make no correlation that the levels reported are safe for occupancy or do not pose a risk from exposure. We advise you, our client to consult with an Occupational Health or other qualified physician for additional information and guidance.

Please contact our office if you have any questions or need any additional information.

Sincerely,

Jack Kerr EHS Consultant

Liberty OHM



## APPENDIX A LABORATORY RESULTS



Report for:

Jack Kerr Liberty OHM 1211 E 39th St Tulsa, OK 74105

Regarding: Project: 12-179; Bisby Central Intermediate

EML ID: 1045249

Approved by:

Dates of Analysis:

Spore trap analysis: 04-03-2013

Technical Manager Aaron Agajanian

Service SOPs: Spore trap analysis (1038 (previously I100000 and I100007)) AIHA-LAP, LLC accredited service, Lab ID #102297

All samples were received in acceptable condition unless noted in the Report Comments portion in the body of the report. Due to the nature of the analyses performed, field blank correction of results is not applied. The results relate only to the items tested.

EMLab P&K ("the Company") shall have no liability to the client or the client's customer with respect to decisions or recommendations made, actions taken or courses of conduct implemented by either the client or the client's customer as a result of or based upon the Test Results. In no event shall the Company be liable to the client with respect to the Test Results except for the Company's own willful misconduct or gross negligence nor shall the Company be liable for incidental or consequential damages or lost profits or revenues to the fullest extent such liability may be disclaimed by law, even if the Company has been advised of the possibility of such damages, lost profits or lost revenues. In no event shall the Company's liability with respect to the Test Results exceed the amount paid to the Company by the client therefor.

1501 West Knudsen Drive, Phoenix, AZ 85027 (800) 651-4802 Fax (623) 780-7695 www.emlab.com

Client: Liberty OHM Date of Sampling: 04-01-2013 Date of Receipt: 04-02-2013 C/O: Jack Kerr Date of Report: 04-03-2013 Re: 12-179; Bisby Central Intermediate

#### SPORE TRAP REPORT: NON-VIABLE METHODOLOGY

Location:		1:				2:		
		Office 111				Outside Refere	ence	
Comments (see below)		None				None		
Lab ID-Version‡:		4695650-1				4695651-1		
Analysis Date:		04/03/2013				04/03/2013		
Sample volume (liters)		150				150		
Background debris (1-4+)††		3+				3+		
Buckground debris (1 11)	Count	Count/m3	DL/m3*	%	Count	Count/m3	DL/m3*	%
Hyphal fragments		<u> </u>			6	40	7	n/a
Pollen	1	7	7	n/a	27	180	7	n/a
§ TOTAL FUNGAL SPORES	51	340	n/a	100	139	6,600	n/a	100
Alternaria	11	73	7	22	33	220	7	3
Ascospores	6	40	7	12	9	60	7	1
Basidiospores	5	33	7	10	43	290	7	4
Bipolaris/Drechslera group					21	140	7	2
Chaetomium								
Cladosporium	21	140	7	41	22	5,900	270	88
Epicoccum					1	7	7	< 1
Other brown	1	7	7	2				
Penicillium/Aspergillus types	6	40	7	12	10	67	7	1
Smuts, Periconia, Myxomycetes	1	7	7	2				
Stachybotrys								
Stemphylium								
Torula								
Ulocladium								
Zygomycetes								

#### **Comments:**

Spore types listed without a count or data entry were not detected during the course of the analysis for the respective sample.

The analytical sensitivity is the spores/m3 divided by the raw count. The limit of detection is the analytical sensitivity multiplied by the sample volume divided by 1000.

Aerotech Laboratories, Inc EMLab ID: 1045249, Page 2 of 2

<sup>\*</sup>The DL/m3 has been rounded to a whole number.

<sup>‡</sup> A "Version" indicated by -"x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x". § Total Fungal Spores has been rounded to two significant figures to reflect analytical precision.

#### Introduction

Molds are a natural and important part of our environment. They are ubiquitous and are found virtually everywhere. Molds produce tiny spores to reproduce. These spores can be found in both indoor and outdoor air and on indoor and outdoor surfaces. When mold spores land on a damp spot, they may begin growing and digesting whatever they are growing on in order to survive, leading to adverse conditions. In response to increasing public concern, a number of government authorities, including the United States EPA, California Department of Health Services and New York City Department of Health, have developed recommendations and guidelines for assessment and remediation of mold. Websites for these organizations can be found at the end of this report.

While it is generally accepted that molds can be allergenic and can lead to adverse health conditions in susceptible people, unfortunately there are no widely accepted or regulated interpretive standards or numerical guidelines for the interpretation of microbial data. The absence of standards often makes interpretation of microbial data difficult and controversial. This report has been designed to provide some basic interpretive information using certain assumptions and facts that have been extracted from a number of peer reviewed texts, such as the American Conference of Governmental Industrial Hygienists (ACGIH). In the absence of standards, the user must determine the appropriateness and applicability of this report to any given situation. Identification of the presence of a particular fungus in an indoor environment does not necessarily mean that the building occupants are or are not being exposed to antigenic or toxic agents.

None of the information contained herein should be construed as medical advice or a call to action for evacuation or remediation. Only a qualified physician should make any decision relative to medical significance.

EMLab P&K did not conduct the site investigation, provide consulting or collect the samples referenced in this report. EMLab P&K's primary involvement in this project is to provide analytical results for the samples submitted. The data presented in this report are based on the samples and accompanying information provided and represents concentrations at a point in time under the conditions sampled.

EMLab P&K's standard terms and conditions govern all aspects of this report.

#### **Materials**

Please refer to the chain of custody included with this report.

#### Methods

#### 1. Surface Samples – Swab, Dust, Tape and Bulk Samples

Swab, Dust and Tape samples are mounted on a glass slide and observed under a bright field microscope for either Qualitative or Quantitative Examination. A bulk sample is also simultaneously observed under a stereomicroscope to look for signs of any visible discoloration or fungal growth, which is then mounted and observed under a bright field microscope for either Qualitative or Quantitative Examination. The samples are analyzed at a minimum of 200X magnification and up to a 1000X magnification. In the qualitative

examination, the prepared samples are observed for the presence of any structures or skewing of spore distribution that may indicate growth in the sample being analyzed. In the quantitative examination, the mold spores detected in the sample are counted and reported as spores per cm<sup>2</sup>, spores per gram (or 1000mg), or spores per swab/wipe, etc depending on the sample type. These methodologies do not differentiate between viable and non-viable fungal spores.

#### 2. Air Samples-Spore Trap Device

Spore traps are a unique sampling device designed for the rapid collection and analysis of a wide range of airborne particulates, including fungal spores. While analyzing the sample, the analyst takes a number of variables into account to select the proper analytical method to accurately determine the densities of the various spores on the trace. The densities of the debris and the spores on the trace will determine the approach to analyzing the sample. In general, the sample is directly mounted under the microscope and the various airborne particles detected are counted at a minimum of 200X magnification and up to 1000X magnification, with the entire trace (100% of the sample) being analyzed at 200X or 600X. This method does not differentiate between viable and non-viable fungal spores. This technique does not allow for the differentiation between *Aspergillus* and *Penicillium* spores. Additionally, depending on morphology, other non-distinctive spores are reported in categories such as ascospores or basidiospores. All slides are graded with the following debris scale for data qualification.

Debris Rating	Description	Interpretation
None	No particles detected.	No particulates on slide. The absence of particulates could indicate improper sampling as most air samples typically capture some particles.
<1+	Good visibility. A few particles detected.	Deported values are not offected by debuis
1+	Good visibility. No crowding of particles.	Reported values are not affected by debris.
2+	Decent visibility. Particles beginning to crowd.	Non-microbial particulates can mask the presence of fungal spores. As a result, actual values could be higher than the
3+	Decent visibility. Particles beginning to crowd.	numbers reported. Higher debris ratings increase the probability of this bias.
4+	Poor visibility. Particles beginning to overlap.	Excessive debris detected in the sample. Counts reported may vary drastically and actual values could be higher than
>4+	Poor visibility. Particles overlapping.	the numbers reported. The sample should be collected at a shorter time interval, or other measures taken to reduce the collection of non-microbial debris. In addition, a >4+ rating will only allow for a count from the perimeter of the slide.

#### 3. Comments

Comments identify issues or events that are relevant to your analytical results. A comment includes information about any peculiar observation or situation encountered while analyzing the sample. In each case, the comments provide significant information vital to the interpretation of the laboratory data.

#### 4. Data Interpretation

According to ACGIH, "Data from individual sampling episodes is often interpreted with respect to baseline data from other environments or the same environment under anticipated low exposure conditions." In the absence of established acceptable exposure limits, it is often necessary to use a comparison standard when interpreting data. In this instance, it will be necessary to sample the suspect area as well as a non-suspect area.

According to ACGIH, "...active fungal growth in indoor environments is inappropriate and may lead to exposure and adverse health effects."

#### a. Total Fungal Spores

According to ACGIH, ".... differences that can detected with manageable sample sizes are likely to be in 10- fold multiplicative steps (e.g., 100 versus 1000...)". Following this logic, if total fungal spores are ten (10) times greater in the sample from a suspect area than in the negative control sample collected from a non-suspect area, then that sample area may be a fungal amplification site.

#### **b.** Mycelial Fragments

Mycelium is a fungal mass that constitutes the vegetative or living body of a fungus. Following the same logic above, if total mycelial fragments are ten (10) times greater in the suspect sample than in the negative control, then the sample area is considered to be a fungal amplification site. The presence of mycelial fragments provides evidence of microbial growth.

#### c. Mycotoxins

Molds can produce toxic substances called mycotoxins. More than 200 mycotoxins have been identified from common molds, and many more remain to be identified. Some of the molds that are known to produce mycotoxins are commonly found in moisture-damaged buildings. Exposure pathways for mycotoxins can include inhalation, ingestion, or skin contact. Although some mycotoxins are well known to affect humans and have been shown to be responsible for human health effects, for many mycotoxins, little information is available, and in some cases research is ongoing. Some molds can produce several toxins, and some molds produce mycotoxins only under certain environmental conditions. The presence of mold in a building does not necessarily mean that mycotoxins are present or that they are present in large quantities.

#### d. Water Indicator Molds

Certain authorities identify certain molds whose presence indicates excessive moisture. The presence of a few spores of indicator mold should be interpreted with caution. Additionally, it should be recognized that these named molds are not necessarily the only ones of potential significance.

#### e. Mold Glossary

Specific characteristics of the individual molds listed in the report are presented in Table 1.

#### f. Useful Resources

- i. Guidelines on Assessment and Remediation of Fungi in Indoor Environments, New York City Department of Health.
  - www.ci.nyc.ny.us/html/doh/html/epi/moldrpt1.html
- ii. Facts about Mold, New York City Department of Health. www.ci.nyc.ny.us/html/doh/html/epi/epimold.html

- iii. Mold Resources, United States Environmental Protection Agency. http://www.epa.gov/mold/moldresources.html
- iv. Mold in My Home, What do I do? California Department of Health Services. www.asbestos.org/Microbial/index.html

**Table 1: Summary of Specific Mold Characteristics** 

Fungi	Environmental Indicator	Typically Found
Alternaria		Alternaria is one of the more common fungi found in nature. It is found growing indoors on a variety of substrates including wallboards, painted walls, etc.
Arthrinium		Arthrinium is a saprobe and is found on plants. It is rarely found growing indoors.
Ascospores	★ 📑	Ascospores are ubiquitous in nature and are commonly found in the outdoor environment. Some fungi that belong to the ascomycete family include the sexual forms of <i>Penicillium/Aspergillus</i> , <i>Chaetomium</i> , etc that may be frequently found growing on damp substrates.
Aureobasidium		Aureobasidium is commonly found in a variety of soils. Indoors, it is commonly found where moisture accumulates, especially bathrooms, and kitchens, on shower curtains, tile grout, windowsills, textiles, and liquid waste materials.
Basidiospores		Basidiospores are Saprophytes and plant pathogens and are commonly found in gardens, forests, and woodlands. They also include organisms that are the agent of "dry rot," and other fungi that cause white and brown wood rot, which may grow and destroy the structural wood of buildings.
Bipolaris/ Dreschlera		Bipolaris and Dreschlera are usually found associated with plant debris, and soil. They are plant pathogens of numerous plants, particularly grasses. Bipolaris and Dreschlera can grow indoors on a variety of substrates.
Botrytis		Botrytis is commonly found in tropical and temperate climates growing on vegetative matter. They may be found indoors in conjugation with indoor plants, fruits and vegetables.
Chaetomium	★ 📑	Chaetomium is often found on materials containing cellulose such as sheetrock paper, or other wet materials.
Cladosporium		Cladosporium is a common outdoor mold. They are commonly found on dead plants, food, textiles, and a variety of other surfaces. Indoors, they can grow on a variety of substrates including textiles, wood, moist windowsills, etc. It can grow at 0°C and is associated with refrigerated foods.
Curvularia		Curvularia is found on plant materials and is considered a saprobe. Indoors, they can grow on a variety of substrates.
Epicoccum		<i>Epicoccum</i> is a saprophyte and considered a weekly parasitic secondary invader of plants. They tend to colonize continuously damp materials such as damp wallboard and fabrics.
Fusarium	* -	Fusarium requires very wet conditions and is frequently isolated from plants and grains. They colonize continuously damp materials such as damp wallboard and water reservoirs for humidifiers and drip pans.

Memnoniella			Memnoniella can be found growing on a variety of cellulose- containing materials.
Nigrospora			Nigrospora is especially abundant in warm climates and is rarely found growing indoors.
Oidium/ Peronospora			<i>Oidium</i> and <i>Peronospora</i> are plant pathogens and are not found growing indoors.
Penicillium/ Aspergillus	*	-	Penicillium and Aspergillus are ubiquitous in environment. Aspergillus tends to colonize continuously damp materials such as damp wallboard and fabrics. Penicillium is commonly found in house dusts, wallpaper, decaying fabrics, moist clipboards, etc.
Pithomyces/ Ulocladium			Pithomyces is commonly found on grass and decaying plant material and are rarely found growing indoors. Ulocladium has a high water requirement and therefore colonizes continuously damp materials such as damp wallboard and fabrics.
Rusts			Rusts are plant pathogens and only grow on host plants.
Smuts/ Periconia/ Myxomycetes			Smuts and Myxomycetes are parasitic plant pathogens that require a living host. Smuts do not usually grow indoors. <i>Periconia</i> are rarely found growing indoors. Myxomycetes are occasionally found indoors, but rarely growing.
Stachybotrys	*	- <u>\</u>	Stachybotrys are commonly found indoors on wet materials containing cellulose, such as wallboard, jute, wicker, straw baskets, and other paper materials.
Stemphylium			Stemphylium is either parasitic or saprophytic and is rarely found growing indoors.
Torula			Torula can grow indoors on cellulose containing materials such as wallboard, jute, wicker, straw baskets, and other paper materials.
Other brown/ colorless			An uncharacteristic fungal spore that does not lend itself to classification via direct microscopy.



Potential Water Intrusion/Indicator Mold

Potential Water Intrusion/Indicator Mold Capable of Mycotoxin Production

#### **Quality Programs**

The EMLab P&K's laboratory network is staffed with highly trained analysts, the majority of which hold advanced degrees. The reliability of test results depends on many factors such as the personnel performing the tests, environmental conditions, selection and validation of test methods, equipment functioning, as well as the sampling, storage and handling of test items, all of which are a reflection of the overall quality system of the laboratory.

EMLab P&K has modeled its quality system after ISO 17025, General Requirements for the Competence of Testing and Calibration Laboratories, one of the most stringent sets of standards in the industry, to ensure that its customers receive the highest standard of accuracy, reliability, and impartiality that they have come to expect from the leader in the environmental industry. EMLab P&K's laboratories adherence to the standards set forth in ISO 17025 has been validated and formally recognized through accreditations granted by an independent outside agency, American Industrial Hygiene Association (AIHA), on a site by site basis. As an additional measure to demonstrate its competency to perform the analyses it offers to its clients, EMLab P&K laboratories

also participate in a variety of different proficiency testing programs, including the Environmental Microbiology Proficiency Analytical Testing Program (EMPAT) sponsored by the American Industrial Hygiene Association.

As part of our continuous commitment to excellence, EMLab P&K laboratories are also inspected, licensed and/or accredited by a number of governmental agencies and independent associations in addition to those already mentioned above. The scope of services, accreditation certificates, and proficiency results can all be accessed at <a href="www.emlabpk.com">www.emlabpk.com</a>.


#### References

- 1. Bioaerosols: Assessment and Control. Janet Macher, Ed., American Conference of Government Industrial Hygienists, Cincinnati, OH (1999).
- 2. EPA: The Inside Story. A Guide to Indoor Air Quality, United States Environmental Protection Agency and the United States Consumer Product Safety Commission, Washington DC (1995).
- 3. Health Canada: Exposure Guidelines for Residential Indoor Air Quality. Environmental Health Directorate. Health Protection Branch, Health Canada, Ottawa, Ontario (1989).
- 4. IIRC: Standard and Reference Guide for Professional Water Damage Restoration, 2nd Ed. Institute of Inspection, Cleaning and Restoration, Vancouver, WA (1999).
- 5. Field Guide for the Determination of Bio logical Contaminants in Environmental Samples. American Industrial Hygiene Association, Fairfax, VA (1996).
- 6. Standards of Practice for the Assessment of Indoor Environmental Quality, Volume I: Mold Sampling, Assessment of Mold Contamination. Indoor Environmental Standards Organization (2002).

(800) 651-4802 Fax (623) 780-7695 www.emlab.com

04-03-2013: 12-179 EMLab P&K


#### SPORE TRAP REPORT: NON-VIABLE METHODOLOGY



#### **Comments:**

EMLab P&K 1501 West Knudsen Drive, Phoenix, AZ 85027 (800) 651-4802 Fax (623) 780-7695 www.emlab.com

#### SPORE TRAP REPORT: NON-VIABLE METHODOLOGY



#### **Comments:**

Note: Graphical output may understate the importance of certain "marker" genera. Aerotech Laboratories, Inc

•				•	
	: Heavy	Moderate	VE Light	None	The second second second second second clean
	_			×	ē
	<b> </b>			N	5
				ĸ	OHOW
i			×		DISJAN
					Clear
Bulk	opone Swat	. Tape	Non-Culturalitie		
OC THREAD	=		<u>e</u>	<b>7.77.0</b> 00	
		0010457			

		ŀ					į	ļ		-									<u> </u>				İ	.'	O - Other
	4	Ċ					7	6	Č	K	,	_		س	44			q		SO - Soil	B - Bulk	[4.	er Burkard	Jaidilled IN Spenne - even	100 - 001
		}	$\perp$	ĺ	-					-	1	1	Ť					ηĖ	1		7	Zelon, Allergenco.	_	face Air Somo	9A9 - Sm
	]		ļ				ĺ	-				Î	J	- July						W-Water	SW - Swab	ST - Spore Trap;	-13	iersen	A1S - Andersen
13			_	1						ļ			= +	- 1	<u>두</u>	i				D - Dust	T - Tape	CP - Contact Plate	유	assette"	BC - BioCassette
7	DATE & TIME	Į.				*	RECEIVED BY	ŽŲ.	깶					DATE & TIME	DATE	<b>Y</b>	RELINCUISHED BY	RELINO			ES	SAMPLE TYPE CODES	SAMP		
_				-	_	_	-	┞	_			H	F							-					
<u> </u>		<u></u>	1	+	+		_	1	<u> </u>			-	+			ļ	+				أ				
				<del> </del>	-	Ļ	+	┼-	!	}		+	<del>-</del>				<u> </u>				-				
		<u>!</u>	-	۳.	<u> </u>	<b>İ</b>	-	┼	ļ.,			+	<del>                                     </del>												
<u> </u>			<u>.</u>					-	_		<u> </u>	1	1												
				╢				<u> </u>	<u> </u>			+	<u>+</u>				<u> </u>							-	
<u></u>			- 1				╁	<del>   </del>	$\Box$			    	<del>                                     </del>						Ĺ					-	
-			$\exists$		_ļ		-					-	_	i			_			<u> </u>	]				İ
		<u> </u> 					$\dashv$					_	<u> </u>				-							_	
$\dashv$	- 1	 i					Н					-	<u> </u>								-				
	·.			·		'	-÷-			-	<u></u>	^	÷					7057	M	57	10	to llaterence	Outside		
				<u> </u>	Ľ	_	-	_			<u>,                                     </u>	10	<u>                                      </u>	ĺ,	ļ ;	ļ [		1506	M	57		111 37	OHIVE	3	ľ
_		=	_	$\overline{}$	╌	4-		_		ŀ			1				ĿĒ	Tres applicable)		A V		344	1		•
	Asbestos CR (pla	QuantiTr Abbestos	MPN 3e	Total Co Vembra	Legionel		3-Modia Culturab	2-Medie	i-Media	Quantita	Direct M	Spore 19 Spore 19	Fungi - (	RH, elc.)	ES SE	ini Timba or day		00000	(Above)	adyle aldtues		DESCRIPIJON		SAMPLE D	SAI
	s Ana									live S			er.	eeds	ialysis needs	weekend ana	1946 0048		dollday	WH - Weekend/Holiday	W			Den.	PO Number
	lysis			-		_				Spon			<u> </u>	n-advance of		Please alent us	Plea	Rush	iess Dey	SD - Same Business Day Rush	11/24	141-13	Date & Tinje:		Zin Code:
	- PLN									- Cour			<u> </u>	e considered		weekends, will be next	1 790.00 WPMB		ess Day	ND - Next Business Day	<u> </u>	cal Interneliate	Sampling to a	Bis	Project Desc.: Project
	(EPA									ท Dire			<u>. ⊐.;.</u>	after 2pm grø	d after 2	Rushes received	Rushi	ן ד	DEFAUL	STD - Standard (DEFAULT)	(O)		79	D. 12-179	Project ID:
		ome								d Ex		entir1	-00			ES (TAT)	ME CODE	TURN AROUND TIME CODES (TAT)	TURN			A ROBERT SAN CHEMICAL CONTRACTION	CO. UNIVERSITY	NAC SE	
		Fiber (				<u> </u>				em eme		ns	<u></u>		i		ŀ				Dim .	Phone/Email:918-742-1567/jack@libertyohm.com	1567/jack@	mall:918-742-	Phone/E
		Count																	uctions:	obaciat tileadotions:				Contact Jack Kerr	Contact
		(NIO				face I	•						<u> </u>				K 74105	St, Tulsa, O	1 E 39th	Address:1211 E 39th St, Tulsa, OK 74105			5	Company: Liberty OHM	Compan
		SH 740		<del></del>		Bacterie													ESC.	CONTACT INFORMATION	CONT				
FISE	65	45249	001045	8				BioCasss Water, &		Tape Swab Bulk	m (2) -1 =	Spore Swab Trap Bulk	<del>-                                    </del>	*			Moderate Heavy	of EVI	1 12 -6653	(866) 871-1984 * (800) 651-486   66 * (866) 188	I, NJ 08003 * ix, AZ 85027 3runo, CA 940	Cherry Hitt, NJ: 1936 Olney Avanve, Cherry Hill, NJ 08003 * (866) 871-1984 Phoenix, AZ: 1501 West Knudsen Drive, Phoenix, AZ 85027 * (800) 651-4802 San Bruno, CA: 1150 Bayhill Drive, #100, San Bruno, CA 94066 * (866) 888-6653	Olney Avai est Knudse Bayhill Dri	Hill, NJ: 1936 k, AZ: 1501 W uno, CA: 1150	Cherry I Phoenis San Bru
							e system	<b>杂</b> 8	- Page 2000			0.000			× Snow	× ⊗ Rain	WEATHER:	#25450	× ×	EMLab P&K	MEN	YDC :(*)•	Com	CHAIN OF CUSTODY www.EMLabPK.com	CHA

By submitting this Chain of Custody, you agree to be bound by the terms and conditions set forth at www.emlabpk.com/terms.html