



PLACERVILLE UNION SCHOOL DISTRICT

1032 THOMPSON WAY
PLACERVILLE, CALIFORNIA 95667

ERIC BONNIKSEN
Superintendent

BOARD OF EDUCATION
Chris Belmer
Mike Bouchard
Misty diVittorio
Katie Stabler

RFP CALSHAPE VENDOR QUESTION

The thermostat count is quite a bit lower than the unit count based on counts listed for funds approved by the CEC. Every classroom (or “learning space”) needs a CO2 monitoring thermostat as part of this program, either installed as part of the program or installed after August 1, 2020.

Do you know if some of these thermostats were recently replaced with the appropriate thermostat (meeting CalSHAPE guidelines) and perhaps that is why the thermostat count is lower? If so, the district would need to provide documentation of what was installed and when, otherwise the program will not approve the final payment.

ANSWER:

The CO2 monitor count submitted in a CalSHAPE application does not correlate with the number of mechanical units on the site. The number of CO2 monitors included in the application will instead equal the number of classrooms on the school site.

SUPERINTENDENT'S OFFICE
1032 THOMPSON WAY
PLACERVILLE, CA 95667
(530) 622-7216
Fax 622-0336

LOUISIANA SCHNELL SCHOOL
2871 SCHNELL SCHOOL ROAD
PLACERVILLE, CA 95667
(530) 622-6244
Fax 622-2309

SIERRA SCHOOL
1100 THOMPSON WAY
PLACERVILLE, CA 95667
(530) 622-0814
Fax 622-0532

EDWIN MARKHAM SCHOOL
2800 MOULTON DRIVE
PLACERVILLE, CA 95667
(530) 622-0403
Fax 622-5584