

State of Facilities

			Deficiencies		
School/Site	Year	Sq. Ft.	Structural	Mechanical	Electrical
Liberty Elementary	1951	40,459	Main Building needs Painting; Portables need ramps, gutters, and paint	Steam system leaks, exhaust fans on roof have failed	Entire Electrical Upgrade, Upgrade Clock System, Replace Doors and Hardware, Replace Key System, Replace Intercom System
Cascade Elementary	1955	38,923	Paint Doors and Trim; Portables need paint and ramps replaced	Outdated heating system - inadequate and inefficient	Entire Electrical Upgrade, Upgrade Clock System, Replace Doors and Hardware, Replace Key System, Replace Intercom System
Shoultes Elementary	1958	40,050	Broken Concrete, Trim and Doors, Painting; Replace Siding and Ramps on Portables	No isolation valves for heating loop, have to shut down entire system to service	Upgrade Fire Alarm System, Upgrade Intercom System, Replace Key System, Replace Door Hardware
Sunnyside Elementary	1964	39,121	Paint Doors and Trim; Portables need paint and ramps replaced	No Controls over heating system	Upgrade Fire Alarm System, Upgrade Intercom System, Replace Door Hardware, Replace Clock System
Pinewood Elementary	1968	38,949	Replace Main Building Roofing, Doors and Trim need painting; Portables need paint and ramps	No Controls over heating system	Replace Door Hardware, Replace Key System, Upgrade Intercom System
Marshall Elementary	1981	51,943	No Needs	No Needs	Upgrade Fire Alarm System, Upgrade Intercom System, Replace Key System
Kellogg Marsh Elementary	1989	47,816	Interior Hallways need new Vinyl; Portables need paint	No Needs	Upgrade Fire Alarm System, Upgrade Intercom System
Allen Creek Elementary	1993	47,594	Main Building Roof Replacement, Interior Hallways need new Vinyl; Portable Ramps	Water Loop fittings all leak when heating system is turned off	Upgrade Fire Alarm System, Upgrade Intercom System
Quilceda/Tulalip Elementary	1997	45,690	Portables - Replace Siding and Ramps, Painting	No Needs	Upgrade Fire Alarm System, Upgrade Speaker System
Grove Elementary	2008	45,713	No Needs	No Needs	No Needs
Totem Middle	1950	124,822	Partial Roof Replacement, Painting	Steam system leaks, heaters leak	Replace Key System, Replace Door Hardware
Marysville Middle	1960	99,617	Replace Hallway Tiles, Concrete Repair Painting; Portable Ramps and Decks	No Controls over heating system	New Fire Alarm System, Replace Original Electrical System, Replace Key System, Replace Door Hardware, Replace Clock and Intercom Speaker System
Cedarcrest Middle	1991	83,128	Replace Main Building Roofing, Siding, and Gutters; Replace Portables Siding and Ramps	No Needs	Upgrade Fire Alarm System, Replace Key System, Replace Door Hardware, Upgrade Intercom System
Marysville Pilchuck	1970	259,033	Broken Concrete, Partial Roof Replacement, Fascia Siding Replacement - All, Painting	Pool boiler relocation, main boilers can't keep up after years of additions	Upgrade Fire Alarm System, Replace key system on all doors (3 systems currently there)
Marysville Mt. View	1993	18,350	No Needs	No Needs	Upgrade Fire Alarm System, Upgrade Intercom Speaker System, Replace key system
Marysville Tulalip	2007	86,495	No Needs	Replace plastic condensate lines with copper to prevent freezing	Upgrade Intercom Speaker System
Marysville Getchell	2009	182,524	No Needs	No Needs	No Needs
Service Center - Main Building	1961	33,331	Painting Interior and Exterior, Carpet Replacement	Replace Entire Heating System	Lighting System Upgrade, Replace Key System, Upgrade Intercom Speaker System