

Valenzuela/CAHSEE Lawsuit Settlement
Quarterly Report on Williams Uniform Complaints
 [Education Code § 35186(d)]

District Bishop Unified School District _____

Person completing this form: Midge Milici _____ Title: Chief Business Officer

Quarterly Report Submission Date:

- ✓ October 2020
 January 2021
 April 2021
 July 2021

Date for information to be reported publicly at governing board meeting: October 22, 2020

Please check the box that applies:

- No complaints were filed with any school in the district during the quarter indicated above.
- Complaints were filed with schools in the district during the quarter indicated above. The following chart summarizes the nature and resolution of these complaints.

General Subject Area	Total # of Complaints	# Resolved	# Unresolved
Textbooks and Instructional Materials	0		
Teacher Vacancy or Misassignment	0		
Facilities Conditions	0		
CAHSEE Intensive Instruction and Services	0		
TOTALS	0		

Katie Kolker
 Print Name of District Superintendent

Signature of District Superintendent

Date

10/15/20

SCHOOL DISTRICT/COUNTY OFFICE OF EDUCATION		COUNTY
Bishop Unified School District		Inyo
SCHOOL SITE	SCHOOL TYPE (GRADE LEVELS)	
Palisades Glacier High School	Tenth - twelfth	
INSPECTOR'S NAME		NUMBER OF CLASSROOMS ON SITE
Todd Remley		4
INSPECTOR'S TITLE		NAME OF DISTRICT REPRESENTATIVE ACCOMPANYING THE INSPECTOR(S) (IF APPLICABLE)
MOT Director		Patrick Twomey- Principal
TIME OF INSPECTION		
9:30		

PART III: CATEGORY TOTALS AND RANKING (round all calculations to two decimal places)

TOTAL NUMBER OF AREAS EVALUATED	A. SYSTEMS			B. INTERIOR INTERIOR SURFACES	C. CLEANLINESS		D. ELECTRICAL ELECTRICAL	E. RESTROOMS/FOUNTAINS		F. SAFETY		G. STRUCTURAL		H. EXTERNAL	
	GAS LEAKS	MECH/NAC	SEWER		OVERALL CLEANLINESS	PEST/VERMIN INFESTATION		RESTROOMS	SINKS/ FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUND/ SCHOOL GROUNDS	WINDOWS/DOORS/ GATES/FENCES
7	6	7	3	7	7	7	7	1	2	7	7	7	6	7	7
	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0
	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
	1	0	4	0	0	0	0	6	5	0	0	0	0	0	0
Percent of System in Good Repair Number of "v"s divided by (Total Areas - "NA"s)*	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	85.71%	100.00%	100.00%
Total Percent per Category (average of above)*	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	92.86%	100.00%	100.00%
Rank (Circle one) GOOD = 90%-100% FAIR = 75%-89.99% POOR = 0%-74.99%	GOOD			GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD

*Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category and a zero for "Total Percent per Category".

OVERALL RATING: DETERMINE AVERAGE PERCENTAGE OF 8 CATEGORIES ABOVE → 99.11% → SCHOOL RATING** → EXEMPLARY

**For School Rating, apply the Percentage Range below to the average percentage determined above, taking into account the rating Description below.

PERCENTAGE	DESCRIPTION	RATING
99%-100%	The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.	EXEMPLARY
90%-98.99%	The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.	GOOD
75 %-89.99%	The school is not in good repair. Some deficiencies noted are critical and/or widespread. Repairs and/or additional maintenance are necessary in several areas of the school site.	FAIR
0%-74.99%	The school facilities are in poor condition. Deficiencies of various degrees have been noted throughout the site. Major repairs and maintenance are necessary throughout the campus.	POOR

COMMENTS AND RATING EXPLANATION:

Siding to be placed on the five year plan. Due to cost, the project will be completed over 3 years.

CATEGORY	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	
AREA	GAS LEAKS	MECH/HVAC	SEWER	INTERIOR SURFACES	OVERALL CLEANLINESS	PEST/VERMIN INFESTATION	ELECTRICAL	RESTROOM	SINKS/ FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUND/ SCHOOL GROUNDS	WINDOWS/ DOORS/ GATES/FENCES	
Restroom Bldg	NA	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	COMMENTS:															
Office Bldg	✓	✓	NA	✓	✓	✓	✓	NA	✓	✓	✓	D	✓	✓	✓	
	COMMENTS:	South facing exterior walls in need of repair.														
English Bldg	✓	✓	NA	✓	✓	✓	✓	NA	NA	✓	✓	✓	✓	✓	✓	
	COMMENTS:															
Science Bldg	✓	✓	✓	✓	✓	✓	✓	NA	NA	✓	✓	✓	✓	✓	✓	
	COMMENTS:															
Social Sciences Bldg	✓	✓	NA	✓	✓	✓	✓	NA	NA	✓	✓	✓	✓	✓	✓	
	COMMENTS:															
Computer Lab	✓	✓	✓	✓	✓	✓	✓	NA	NA	✓	✓	✓	✓	✓	✓	
	COMMENTS:															
Tool Shed, Pump House, Storage Area	✓	✓	NA	✓	✓	✓	✓	NA	NA	✓	✓	✓	✓	✓	✓	
	COMMENTS:															
	COMMENTS:															
	COMMENTS:															
	COMMENTS:															
	COMMENTS:															
	COMMENTS:															

Marks: ✓ = Good Repair (When filling up the electronic version, please use **ctrl+G**); D = Deficiency; X = Extreme Deficiency; NA = Not Applicable
 Use additional sheets as necessary.

SCHOOL DISTRICT/COUNTY OFFICE OF EDUCATION Bishop Unified School District		COUNTY Inyo
SCHOOL SITE Bishop Elementary	SCHOOL TYPE (GRADE LEVELS) K - 5	NUMBER OF CLASSROOMS ON SITE 50
INSPECTOR'S NAME Todd Remley	NAME OF DISTRICT REPRESENTATIVE ACCOMPANYING THE INSPECTOR(S) (IF APPLICABLE) Gretchen Skrotzki - Principal	
INSPECTOR'S TITLE MOT Director		
TIME OF INSPECTION 7:30	WEATHER CONDITION AT TIME OF INSPECTION Mild	

PART III: CATEGORY TOTALS AND RANKING (round all calculations to two decimal places)

TOTAL NUMBER OF AREAS EVALUATED	A. SYSTEMS			B. INTERIOR INTERIOR SURFACES	C. CLEANLINESS		D. ELECTRICAL ELECTRICAL	E. RESTROOMS/FOUNTAINS		F. SAFETY		G. STRUCTURAL		H. EXTERNAL	
	GAS LEAKS	MECH/HVAC	SEWER		OVERALL CLEANLINESS	PEST/VERMIN INFESTATION		RESTROOMS	SINKS/FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUND/ SCHOOL GROUNDS	WINDOWS/DOORS/ GATES/FENCES
8	8	8	8	8	8	8	8	8	8	8	8	8	8	8	8
Number of "v"s:	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Number of "D"s:	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Number of "X"s:	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Number of N/A's:	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Percent of System in Good Repair (Total Areas - "NA"s)*	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%
Total Percent per Category (average of above)*	100.00%			100.00%	100.00%	93.75%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%
Rank (Circle one) GOOD = 90%-100% FAIR = 75%-89.99% POOR = 0%-74.99%	GOOD			GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD

*Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category and a zero for "Total Percent per Category".

OVERALL RATING: DETERMINE AVERAGE PERCENTAGE OF 8 CATEGORIES ABOVE → 99.22% → SCHOOL RATING** → EXEMPLARY

**For School Rating, apply the Percentage Range below to the average percentage determined above, taking into account the rating Description below.

PERCENTAGE	DESCRIPTION	RATING
99%-100%	The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.	EXEMPLARY
90%-98.99%	The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.	GOOD
75 %-89.99%	The school is not in good repair. Some deficiencies noted are critical and/or widespread. Repairs and/or additional maintenance are necessary in several areas of the school site.	FAIR
0%-74.99%	The school facilities are in poor condition. Deficiencies of various degrees have been noted throughout the site. Major repairs and maintenance are necessary throughout the campus.	POOR

COMMENTS AND RATING EXPLANATION:

--

PART II: EVALUATION DETAIL Date of Inspection: 09/30/20 School Name: Bishop Elementary

CATEGORY	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	
AREA	GAS LEAKS	MECH/HVAC	SEWER	INTERIOR SURFACES	OVERALL CLEANLINESS	PEST/MERMIN INFESTATION	ELECTRICAL	RESTROOM	SINKS/ FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUND/ SCHOOL GROUNDS	WINDOWS/ DOORS/ GATES/FENCES	
Kindergarten	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	COMMENTS:															
First Grade	✓	✓	✓	✓	✓	✓	✓	D	✓	✓	✓	✓	✓	✓	✓	
	COMMENTS:	Restrooms need tile repairs and paint.														
Second Grade	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	COMMENTS:															
Office Buildings	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	COMMENTS:															
Third/Fourth Grade	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	COMMENTS:															
Bungalos	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	COMMENTS:															
Fifth Grade	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	COMMENTS:															
BAC	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	COMMENTS:															
	COMMENTS:															
	COMMENTS:															
	COMMENTS:															
	COMMENTS:															

Marks: ✓ = Good Repair (When filling up the electronic version, please use **ctrl+G**); D = Deficiency; X = Extreme Deficiency; NA = Not Applicable
 Use additional sheets as necessary.

SCHOOL DISTRICT/COUNTY OFFICE OF EDUCATION		COUNTY
Bishop Unified School District		Inyo
SCHOOL SITE	SCHOOL TYPE (GRADE LEVELS)	NUMBER OF CLASSROOMS ON SITE
Bishop Union High School	Nine - Twelve	38
INSPECTOR'S NAME	NAME OF DISTRICT REPRESENTATIVE ACCOMPANYING THE INSPECTOR(S) (IF APPLICABLE)	
Todd Remley	David Kalk, Principal	
TIME OF INSPECTION	WEATHER CONDITION AT TIME OF INSPECTION	
8:30	Mild	

PART III: CATEGORY TOTALS AND RANKING (round all calculations to two decimal places)

TOTAL NUMBER OF AREAS EVALUATED	CATEGORY TOTALS	A. SYSTEMS			B. INTERIOR INTERIOR SURFACES	C. CLEANLINESS		D. ELECTRICAL ELECTRICAL	E. RESTROOMS/FOUNTAINS		F. SAFETY		G. STRUCTURAL		H. EXTERNAL			
		GAS LEAKS	MECH/HVAC	SEWER		OVERALL CLEANLINESS	PEST/VERMIN INFESTATION		RESTROOMS	SINKS/ FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUND/ SCHOOL GROUNDS	WINDOWS/DOORS/ GATES/FENCES		
8	Number of "v"s: Number of "D"s: Number of "X"s: Number of "N/A"s:	8 0 0 0	8 0 0 0	7 1 0 0	8 0 0 0	8 0 0 0	8 0 0 0	8 0 0 0	8 0 0 0	8 0 0 0	8 0 0 0	8 0 0 0	7 1 0 0	6 2 0 0	6 0 0 0	8 0 0 0		
Percent of System in Good Repair Number of "v"s divided by (Total Areas - "NA"s)*		100.00%	100.00%	87.50%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	87.50%	100.00%	100.00%	
Total Percent per Category (average of above)		95.83%			87.50%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	93.75%	75.00%	87.50%	100.00%	87.50%	
Rank (Circle one) GOOD = 90%-100% FAIR = 75%-89.99% POOR = 0%-74.99%		GOOD			FAIR	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	FAIR	FAIR

*Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category and a zero for "Total Percent per Category".

OVERALL RATING: DETERMINE AVERAGE PERCENTAGE OF 8 CATEGORIES ABOVE → 95.57% → SCHOOL RATING** → GOOD

**For School Rating, apply the Percentage Range below to the average percentage determined above, taking into account the rating Description below.

PERCENTAGE	DESCRIPTION	RATING
99%-100%	The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.	EXEMPLARY
90%-98.99%	The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.	GOOD
75 %-89.99%	The school is not in good repair. Some deficiencies noted are critical and/or widespread. Repairs and/or additional maintenance are necessary in several areas of the school site.	FAIR
0%-74.99%	The school facilities are in poor condition. Deficiencies of various degrees have been noted throughout the site. Major repairs and maintenance are necessary throughout the campus.	POOR

COMMENTS AND RATING EXPLANATION:

PART II: EVALUATION DETAIL Date of Inspection: 09/30/20 School Name: Bishop Union High School

AREA	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
CATEGORY	GAS LEAKS	MECH/HVAC	SEWER	INTERIOR SURFACES	OVERALL CLEANLINESS	PEST/VERMIN INFESTATION	ELECTRICAL	RESTROOM	SINKS/ FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUND/ SCHOOL GROUNDS	WINDOWS/ DOORS/ GATES/FENCES
Bldg 100	✓	✓	✓	D	✓	✓	✓	✓	✓	✓	✓	✓	✓	D	✓
COMMENTS:	Multiple damaged flooring areas.														
Bldg 200	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	D	✓
COMMENTS:	Tree roots have lifted asphalt - trip hazard, mall area.														
Bldg 300	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
COMMENTS:															
Group 400	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
COMMENTS:															
Group 500	✓	✓	D	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	D	✓
COMMENTS:	Tree roots have lifted asphalt - trip hazard, mall area. Leaking roof.														
Bldg 600	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
COMMENTS:															
Bldg 700	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
COMMENTS:															
Bldg 800	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
COMMENTS:															
COMMENTS:															
COMMENTS:															
COMMENTS:															
COMMENTS:															
COMMENTS:															

Marks: ✓ = Good Repair (When filling up the electronic version, please use **ctrl+G**); D = Deficiency, X = Extreme Deficiency, NA = Not Applicable
 Use additional sheets as necessary.

SCHOOL DISTRICT/COUNTY/OFFICE OF EDUCATION Bishop Unified School District		COUNTY Inyo
SCHOOL SITE Home Street Middle School	SCHOOL TYPE (GRADE LEVELS) Six - Eight	NUMBER OF CLASSROOMS ON SITE 25
INSPECTOR'S NAME Todd Remley	INSPECTOR'S TITLE MOT Director	NAME OF DISTRICT REPRESENTATIVE ACCOMPANYING THE INSPECTOR(S) (IF APPLICABLE) Derek Moisant- Principal
TIME OF INSPECTION 8:00	WEATHER CONDITION AT TIME OF INSPECTION Mild	

PART III: CATEGORY TOTALS AND RANKING (round all calculations to two decimal places)

TOTAL NUMBER OF AREAS EVALUATED	CATEGORY TOTALS	A. SYSTEMS		B. INTERIOR	C. CLEANLINESS		D. ELECTRICAL	E. RESTROOMS/FOUNTAINS		F. SAFETY		G. STRUCTURAL		H. EXTERNAL	
		GAS LEAKS	MECH/RVAC		SEWER	INTERIOR SURFACES		OVERALL CLEANLINESS	PEST/VERMIN INFESTATION	ELECTRICAL	RESTROOMS	SINKS/ FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE
6	Number of "v"s:	6	0	0	6	6	6	6	6	6	6	6	6	5	6
	Number of "D"s:	0	0	0	0	0	0	0	0	0	0	0	0	1	0
	Number of "X"s:	0	0	0	0	0	0	0	0	0	0	0	0	0	0
	Number of "N/A"s:	0	0	0	0	0	0	0	0	0	0	0	0	0	0
	Percent of System in Good Repair (Total Areas - "NA"s) *	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	83.33%	100.00%
	Total Percent per Category (average of above) *	100.00%		100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	91.67%	
	Rank (Circle one) GOOD = 90%-100% FAIR = 75%-89.99% POOR = 0%-74.99%	GOOD		GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	

*Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category and a zero for "Total Percent per Category".

OVERALL RATING: DETERMINE AVERAGE PERCENTAGE OF 8 CATEGORIES ABOVE → 98.96% → SCHOOL RATING** → GOOD

**For School Rating, apply the Percentage Range below to the average percentage determined above, taking into account the rating Description below.

PERCENTAGE	DESCRIPTION	RATING
99%-100%	The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.	EXEMPLARY
90%-98.99%	The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.	GOOD
75 %-89.99%	The school is not in good repair. Some deficiencies noted are critical and/or widespread. Repairs and/or additional maintenance are necessary in several areas of the school site.	FAIR
0%-74.99%	The school facilities are in poor condition. Deficiencies of various degrees have been noted throughout the site. Major repairs and maintenance are necessary throughout the campus.	POOR

COMMENTS AND RATING EXPLANATION:

--

PART II: EVALUATION DETAIL Date of Inspection: 09/30/20 School Name: Home Street Middle School

CATEGORY	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
AREA	GAS LEAKS	MECH/PVAC	SEWER	INTERIOR SURFACES	OVERALL CLEANLINESS	PEST/VERMIN INFESTATION	ELECTRICAL	RESTROOM	SINKS/ FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUND/ SCHOOL GROUNDS	WINDOWS/ DOORS/ GATES/FENCES
6th Wing	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:	Restroom needs patch and paint.													
7th Wing	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:	Restroom needs patch and paint.													
8th Wing	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:														
Main Hall	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	D	✓
	COMMENTS:	Curb by handicap ramp uneven													
Science/Music	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:														
MP Room	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:	Restroom needs patch and paint.													
	COMMENTS:														
	COMMENTS:														
	COMMENTS:														
	COMMENTS:														
	COMMENTS:														

Marks: ✓ = Good Repair (When filling up the electronic version, please use **ctrl+G**); D = Deficiency; X = Extreme Deficiency; NA = Not Applicable
 Use additional sheets as necessary.