

**Valenzuela/CAHSEE Lawsuit Settlement**  
**Quarterly Report on Williams Uniform Complaints**  
 [Education Code §35186(d)]

District: Bishop Unified School District      Date: 12/30/2020

Person completing this form: Midge Milici      Title: CBO

Quarterly Report Submission Date:       October 2020 (Jul – Sep)  
 (check one)       January 2021 (Oct – Dec)  
                                                                   April 2021 (Jan – Mar)  
                                                                   July 2021 (Apr – Jun)


Date for information to be reported publicly at governing board meeting: January 21, 2021

Please check the box that applies:

- No complaints were filed with any school in the district during the quarter indicated above.
- Complaints were filed with schools in the district during the quarter indicated above. The following chart summarizes the nature and resolution of these complaints.

General Subject Area	Total # of Complaints	# Resolved	# Unresolved
Textbooks and Instructional Materials	0	0	0
Teacher Vacancy or Misassignment	0	0	0
Facilities Conditions	0	0	0
CAHSEE Intensive Instruction and Services	0	0	0
<b>TOTALS</b>	0	0	0

Katherine Kolker  
 Print Name of District Superintendent

  
 Signature of District Superintendent

12/30/2020  
 Date

STATE OF CALIFORNIA  
FACILITY INSPECTION TOOL(FIT)  
SCHOOL FACILITY CONDITIONS EVALUATION  
(REV 05/09)

SCHOOL DISTRICT/COUNTY OFFICE OF EDUCATION Bishop Unified School District		COUNTY Inyo	SCHOOL TYPE (GRADE LEVELS) K - 5	NUMBER OF CLASSROOMS ON SITE 50
SCHOOL SITE Bishop Elementary		INSPECTOR'S TITLE MOT Director		
INSPECTOR'S NAME Todd Remley		NAME OF DISTRICT REPRESENTATIVE ACCOMPANYING THE INSPECTOR(S) (IF APPLICABLE) Gretchen Skrotzki - Principal		
TIME OF INSPECTION 7:30		WEATHER CONDITION AT TIME OF INSPECTION Snow		

**PART III: CATEGORY TOTALS AND RANKING (round all calculations to two decimal places)**

TOTAL NUMBER OF AREAS EVALUATED	A. SYSTEMS				B. INTERIOR	C. CLEANLINESS	D. ELECTRICAL	E. RESTROOMS/FOUNTAINS		F. SAFETY		G. STRUCTURAL		H. EXTERNAL		
	GAS LEAKS	MECH/HVAC	SEWER	INTERIOR SURFACES				OVERALL CLEANLINESS	PEST/VERMIN INFESTATION	ELECTRICAL	RESTROOMS	SINKS/FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS
8	8	8	8	8	8	8	8	7	8	8	8	8	8	8	8	8
	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0
	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	87.50%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%
	100.00%		100.00%		100.00%		93.75%		100.00%		100.00%		100.00%		100.00%	
	100.00%				100.00%		100.00%		100.00%		100.00%		100.00%		100.00%	
	GOOD				GOOD		GOOD		GOOD		GOOD		GOOD		GOOD	
	Percent of System in Good Repair Number of "v"s divided by (Total Areas - "NA"s)*															
	Total Percent per Category (average of above)															
	Rank (Circle one) GOOD = 90%-100% FAIR = 75%-89.99% POOR = 0%-74.99%															

\*Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category and a zero for "Total Percent per Category".

DETERMINE AVERAGE PERCENTAGE OF 8 CATEGORIES ABOVE → 99.22% SCHOOL RATING → EXEMPLARY

\*\*For School Rating, apply the Percentage Range below to the average percentage determined above, taking into account the rating Description below.

PERCENTAGE	DESCRIPTION	RATING
99%-100%	The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.	EXEMPLARY
90%-98.99%	The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.	GOOD
75 %-89.99%	The school is not in good repair. Some deficiencies noted are critical and/or widespread. Repairs and/or additional maintenance are necessary in several areas of the school site.	FAIR
0%-74.99%	The school facilities are in poor condition. Deficiencies of various degrees have been noted throughout the site. Major repairs and maintenance are necessary throughout the campus.	POOR

**COMMENTS AND RATING EXPLANATION:**

---



---



---



SCHOOL DISTRICT/COUNTY OFFICE OF EDUCATION		COUNTY
Bishop Unified School District		Inyo
SCHOOL SITE	SCHOOL TYPE (GRADE LEVELS)	NUMBER OF CLASSROOMS ON SITE
Palisades Glacier High School	Tenth - twelfth	4
INSPECTOR'S NAME	NAME OF DISTRICT REPRESENTATIVE ACCOMPANYING THE INSPECTOR(S) (IF APPLICABLE)	
Todd Remley	Patrick Twomey- Principal	
INSPECTOR'S TITLE		
MOT Director		
TIME OF INSPECTION		
9:30	Snow	

**PART III: CATEGORY TOTALS AND RANKING (round all calculations to two decimal places)**

TOTAL NUMBER OF AREAS EVALUATED	CATEGORY TOTALS	A. SYSTEMS			B. INTERIOR	C. CLEANLINESS		D. ELECTRICAL		E. RESTROOMS/FOUNTAINS		F. SAFETY		G. STRUCTURAL		H. EXTERNAL	
		GAS LEAKS	MECH/RVAC	SEWER		INTERIOR SURFACES	OVERALL CLEANLINESS	PEST/VERMIN INFESTATION	ELECTRICAL	RESTROOMS	SINKS/FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUND/ SCHOOL GROUNDS	WINDOWS/DOORS/ GATEFENCES
7	Number of "u"/s: 6 Number of "D"/s: 0 Number of "X"/s: 0 Number of N/A's: 1	7	0	3	7	7	7	7	1	2	7	7	7	6	7	7	7
	Percent of System in Good Repair Number of "u"/s divided by (Total Areas - "NA"s)*	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	85.71%	100.00%	100.00%	100.00%
	Total Percent per Category (average of above)	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	92.86%	100.00%	100.00%	100.00%	100.00%
	Rank (Circle one) GOOD = 90%-100% FAIR = 75%-89.99% POOR = 0%-74.99%	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD

\*Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category and a zero for "Total Percent per Category".

OVERALL RATING: DETERMINE AVERAGE PERCENTAGE OF 8 CATEGORIES ABOVE → 99.11% → SCHOOL RATING\*\* → EXEMPLARY

\*\*For School Rating, apply the Percentage Range below to the average percentage determined above, taking into account the rating Description below.

PERCENTAGE	DESCRIPTION	RATING
99%-100%	The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.	EXEMPLARY
90%-98.99%	The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.	GOOD
75 %-89.99%	The school is not in good repair. Some deficiencies noted are critical and/or widespread. Repairs and/or additional maintenance are necessary in several areas of the school site.	FAIR
0%-74.99%	The school facilities are in poor condition. Deficiencies of various degrees have been noted throughout the site. Major repairs and maintenance are necessary throughout the campus.	POOR

**COMMENTS AND RATING EXPLANATION:**

Siding to be placed on the five year plan. Due to cost, the project will be completed over 3 years.

PART II: EVALUATION DETAIL Date of Inspection: 12/28/20 School Name: Palisades Glacier High School

AREA	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	
CATEGORY	GAS LEAKS	MECH/RVAC	SEWER	INTERIOR SURFACES	OVERALL CLEANLINESS	PEST/VERMIN INFESTATION	ELECTRICAL	RESTROOM	SINKS/ FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUND/ SCHOOL GROUNDS	WINDOWS/ DOORS/ GATES/FENCES	
<b>Restroom Bldg</b>	NA	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	COMMENTS:															
<b>Office Bldg</b>	✓	✓	NA	✓	✓	✓	✓	NA	✓	✓	✓	D	✓	✓	✓	
	COMMENTS:	South facing exterior walls in need of repair.														
<b>English Bldg</b>	✓	✓	NA	✓	✓	✓	✓	NA	NA	✓	✓	✓	✓	✓	✓	
	COMMENTS:															
<b>Science Bldg</b>	✓	✓	✓	✓	✓	✓	✓	NA	NA	✓	✓	✓	✓	✓	✓	
	COMMENTS:															
<b>Social Sciences Bldg</b>	✓	✓	NA	✓	✓	✓	✓	NA	NA	✓	✓	✓	✓	✓	✓	
	COMMENTS:															
<b>Computer Lab</b>	✓	✓	✓	✓	✓	✓	✓	NA	NA	✓	✓	✓	✓	✓	✓	
	COMMENTS:															
<b>Tool Shed, Pump House, Storage Area</b>	✓	✓	NA	✓	✓	✓	✓	NA	NA	✓	✓	✓	✓	✓	✓	
	COMMENTS:															
	COMMENTS:															
	COMMENTS:															
	COMMENTS:															
	COMMENTS:															
	COMMENTS:															

Marks: ✓ = Good Repair (When filling up the electronic version, please use ctrl+G); D = Deficiency; X = Extreme Deficiency; NA = Not Applicable  
Use additional sheets as necessary.

SCHOOL DISTRICT/COUNTY OFFICE OF EDUCATION		COUNTY
Bishop Unified School District		Inyo
SCHOOL SITE	SCHOOL TYPE (GRADE LEVELS)	NUMBER OF CLASSROOMS ON SITE
Home Street Middle School	Six - Eight	25
INSPECTOR'S NAME	NAME OF DISTRICT REPRESENTATIVE ACCOMPANYING THE INSPECTOR(S) (IF APPLICABLE)	
Todd Remley	Derek Moisant- Principal	
INSPECTOR'S TITLE	WEATHER CONDITION AT TIME OF INSPECTION	
MOT Director	Snow	
TIME OF INSPECTION		
8:00		

**PART III: CATEGORY TOTALS AND RANKING (round all calculations to two decimal places)**

TOTAL NUMBER OF AREAS EVALUATED	A. SYSTEMS			B. INTERIOR		C. CLEANLINESS		D. ELECTRICAL		E. RESTROOMS/FOUNTAINS		F. SAFETY		G. STRUCTURAL		H. EXTERNAL	
	GAS LEAKS	MECH/RVAC	SEWER	INTERIOR SURFACES	OVERALL CLEANLINESS	PEST/VERMIN INFESTATION	ELECTRICAL	RESTROOMS	SINKS/FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUND/ SCHOOL GROUNDS	WINDOWS/DOORS/ GATES/FENCES		
6	6	6	6	6	6	6	6	6	6	6	6	6	6	5	5	6	
	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	
	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
Percent of System in Good Repair Number of "v"s divided by (Total Areas - "NA"s)	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	
Total Percent per Category (average of above)	100.00%			100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	83.33%	91.67%	100.00%	
Rank (Circle one) GOOD = 90%-100% FAIR = 75%-89.99% POOR = 0%-74.99%	GOOD			GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	

\*Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category and a zero for "Total Percent per Category".

OVERALL RATING: DETERMINE AVERAGE PERCENTAGE OF 8 CATEGORIES ABOVE → 98.96% → SCHOOL RATING\*\* → GOOD

\*\*For School Rating, apply the Percentage Range below to the average percentage determined above, taking into account the rating Description below.

PERCENTAGE	DESCRIPTION	RATING
99%-100%	The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.	EXEMPLARY
90%-98.99%	The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.	GOOD
75 %-89.99%	The school is not in good repair. Some deficiencies noted are critical and/or widespread. Repairs and/or additional maintenance are necessary in several areas of the school site.	FAIR
0%-74.99%	The school facilities are in poor condition. Deficiencies of various degrees have been noted throughout the site. Major repairs and maintenance are necessary throughout the campus.	POOR

**COMMENTS AND RATING EXPLANATION:**

---



---



---



---

STATE OF CALIFORNIA  
FACILITY INSPECTION TOOL  
SCHOOL FACILITY CONDITIONS EVALUATION  
(REV 05/09)

PART II: EVALUATION DETAIL Date of Inspection: 12/28/20 School Name: Home Street Middle School

CATEGORY AREA	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
	GAS LEAKS	MECH/HVAC	SEWER	INTERIOR SURFACES	OVERALL CLEANLINESS	PEST/VERMIN INFESTATION	ELECTRICAL	RESTROOM	SINKS/FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUND/ SCHOOL GROUNDS	WINDOWS/ DOORS/ GATES/FENCES
6th Wing	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:	Restroom needs patch and paint.													
7th Wing	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:	Restroom needs patch and paint.													
8th Wing	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:														
Main Hall	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	D	✓
	COMMENTS:	Curb by handicap ramp uneven													
Science/Music	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:														
MP Room	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:	Restroom needs patch and paint.													
	COMMENTS:														
	COMMENTS:														
	COMMENTS:														
	COMMENTS:														
	COMMENTS:														

Marks: ✓ = Good Repair (When filling up the electronic version, please use **ctrl+G**); D = Deficiency; X = Extreme Deficiency; NA = Not Applicable  
Use additional sheets as necessary.

SCHOOL DISTRICT/COUNTY OFFICE OF EDUCATION		COUNTY
Bishop Unified School District		Inyo
SCHOOL SITE	SCHOOL TYPE (GRADE LEVELS)	
Bishop Union High School	Nine - Twelve	
INSPECTOR'S NAME		NUMBER OF CLASSROOMS ON SITE
Todd Remley		38
INSPECTOR'S TITLE		NAME OF DISTRICT REPRESENTATIVE ACCOMPANYING THE INSPECTOR(S) (IF APPLICABLE)
MOT Director		David Kalk, Principal
WEATHER CONDITION AT TIME OF INSPECTION		
Snow		
TIME OF INSPECTION		
8:30		

**PART III: CATEGORY TOTALS AND RANKING (round all calculations to two decimal places)**

TOTAL NUMBER OF AREAS EVALUATED	CATEGORY TOTALS	A. SYSTEMS			B. INTERIOR SURFACES	C. CLEANLINESS OVERALL CLEANLINESS	D. ELECTRICAL ELECTRICAL	E. RESTROOMS/FOUNTAINS		F. SAFETY		G. STRUCTURAL		H. EXTERNAL	
		GAS LEAKS	MECH/HVAC	SEWER				INTERIOR SURFACES	RESTROOMS	SINKS/ FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUND/ SCHOOL GROUNDS
8	Number of "✓"'s:	8	7	7	8	8	8	8	8	8	8	8	8	6	8
	Number of "D"'s:	0	0	1	0	0	0	0	0	0	0	0	0	2	0
	Number of "X"'s:	0	0	0	0	0	0	0	0	0	0	0	0	0	0
	Number of N/A's:	0	0	0	0	0	0	0	0	0	0	0	0	0	0
	Percent of System in Good Repair	100.00%	100.00%	87.50%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	75.00%	100.00%
	Number of "✓"'s divided by (Total Areas - "NA"'s)														
	Total Percent per Category (average of above)*	95.83%		87.50%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	87.50%	
	Rank (Circle one)	GOOD		FAIR	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	FAIR	
	GOOD = 90%-100%														
	FAIR = 75%-89.99%														
	POOR = 0%-74.99%														

\*Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category and a zero for "Total Percent per Category".

**OVERALL RATING:** DETERMINE AVERAGE PERCENTAGE OF 8 CATEGORIES ABOVE → 96.35% → SCHOOL RATING\*\* → GOOD

\*\*For School Rating, apply the Percentage Range below to the average percentage determined above, taking into account the rating Description below.

PERCENTAGE	DESCRIPTION	RATING
99%-100%	The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.	EXEMPLARY
90%-98.99%	The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.	GOOD
75 %-89.99%	The school is not in good repair. Some deficiencies noted are critical and/or widespread. Repairs and/or additional maintenance are necessary in several areas of the school site.	FAIR
0%-74.99%	The school facilities are in poor condition. Deficiencies of various degrees have been noted throughout the site. Major repairs and maintenance are necessary throughout the campus.	POOR

**COMMENTS AND RATING EXPLANATION:**

