

Valenzuela/CAHSEE Lawsuit Settlement
Quarterly Report on Williams Uniform Complaints
[Education Code §35186(d)]

District: Bishop Unified Date: 06/30/2021

Person completing this form: Midge Milici Title: Chief Business Officer

Quarterly Report Submission Date: October 2020 (Jul – Sep)
(check one) January 2021 (Oct – Dec)
 April 2021 (Jan – Mar)
 X July 2021 (Apr – Jun)

Date for information to be reported publicly at governing board meeting: 08/09/2021

Please check the box that applies:

- No complaints were filed with any school in the district during the quarter indicated above.

- Complaints were filed with schools in the district during the quarter indicated above. The following chart summarizes the nature and resolution of these complaints.

General Subject Area	Total # of Complaints	# Resolved	# Unresolved
Textbooks and Instructional Materials	0		
Teacher Vacancy or Misassignment	0		
Facilities Conditions	0		
CAHSEE Intensive Instruction and Services	0		
TOTALS	0		

Katie Kolker
Print Name of District Superintendent

Signature of District Superintendent Date 08/05/2021

STATE OF CALIFORNIA
FACILITY INSPECTION TOOL(FIT)
SCHOOL FACILITY CONDITIONS EVALUATION
 (REV 05/09)

SCHOOL DISTRICT/COUNTY OFFICE OF EDUCATION		COUNTY
Bishop Unified School District		Inyo
SCHOOL SITE	Bishop Elementary	SCHOOL TYPE (GRADE LEVELS)
INSPECTOR'S NAME	Todd Renley	K - 5
INSPECTOR'S TITLE	MOT Director	NAME OF DISTRICT REPRESENTATIVE ACCOMPANYING THE INSPECTOR(S) (IF APPLICABLE)
INSPECTOR'S TITLE	MOT Director	Gretchen Skrotzki - Principal
TIME OF INSPECTION	7:30	WEATHER CONDITION AT TIME OF INSPECTION
TIME OF INSPECTION	7:30	Hot

PART III: CATEGORY TOTALS AND RANKING (round all calculations to two decimal places)

TOTAL NUMBER OF AREAS EVALUATED	CATEGORY TOTALS	A. SYSTEMS			B. INTERIOR		C. CLEANLINESS		D. ELECTRICAL	E. RESTROOMS/FOUNTAINS		F. SAFETY		G. STRUCTURAL		H. EXTERNAL	
		GAS LEAKS	MECH/HVAC	SEWER	INTERIOR SURFACES	OVERALL CLEANLINESS	PEST/VERMIN INFESTATION	ELECTRICAL	RESTROOMS	SINKS/FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUND/SCHOOL GROUNDS	WINDOWS/DOORS/GATES/FENCES	
8	Number of "✓"'s:	8	8	8	8	8	8	7	8	8	8	8	8	8	8	8	
	Number of "D"'s:	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	
	Number of "X"'s:	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
Percent of System in Good Repair (Total Areas - "N/A"'s) [*]		100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	87.50%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	
Total Percent per Category (average of above) [*]		100.00%		100.00%	100.00%	100.00%	100.00%	93.75%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%		
Rank (Circle one) GOOD = 90%-100% FAIR = 75%-89.99% POOR = 0%-74.99%		GOOD		GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD		

*Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category and a zero for "Total Percent per Category".

OVERALL RATING:

DETERMINE AVERAGE PERCENTAGE OF 8 CATEGORIES ABOVE **99.22%** **SCHOOL RATING**** **EXEMPLARY**

**For School Rating, apply the Percentage Range below to the average percentage determined above, taking into account the rating Description below.

PERCENTAGE	DESCRIPTION	RATING
99%-100%	The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.	EXEMPLARY
90%-98.99%	The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.	GOOD
75%-89.99%	The school is not in good repair. Some deficiencies noted are critical and/or widespread. Repairs and/or additional maintenance are necessary in several areas of the school site.	FAIR
0%-74.99%	The school facilities are in poor condition. Deficiencies of various degrees have been noted throughout the site. Major repairs and maintenance are necessary throughout the campus.	POOR

COMMENTS AND RATING EXPLANATION:

AREA	CATEGORY	Date of Inspection: 06/29/21														
		1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
		GAS LEAKS	MECH/HVAC	SEWER	INTERIOR SURFACES	OVERALL CLEANLINESS	PEST/VERMIN INFESTATION	ELECTRICAL	RESTROOM	SINKS/ FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUNDS/ SCHOOL GROUNDS	WINDOWS/ DOORS/ GATES/FENCES
Kindergarten	COMMENTS:	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	✓	✓	✓	✓	✓	✓	✓	✓	D	✓	✓	✓	✓	✓	✓	✓
First Grade	COMMENTS:	Restrooms need tile repairs and paint.														
	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
Second Grade	COMMENTS:															
	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
Office Buildings	COMMENTS:															
	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
Third/Fourth Grade	COMMENTS:															
	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
Bungalows	COMMENTS:															
	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
Fifth Grade	COMMENTS:															
	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
BAC	COMMENTS:															
	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:															
	COMMENTS:															
	COMMENTS:															
	COMMENTS:															

Marks: ✓ = Good Repair (When filling up the electronic version, please use ctrl+G); D = Deficiency; X = Extreme Deficiency; NA = Not Applicable
 Use additional sheets as necessary.

STATE OF CALIFORNIA
FACILITY INSPECTION TOOL (FIT)
SCHOOL FACILITY CONDITIONS EVALUATION
 (REV 05/09)

SCHOOL DISTRICT/COUNTY OFFICE OF EDUCATION		COUNTY	Inyo
Bishop Unified School District		SCHOOL TYPE (GRADE LEVELS)	Nine - Twelve
SCHOOL SITE	Bishop Union High School	NUMBER OF CLASSROOMS ON SITE	38
INSPECTOR'S NAME	Todd Renley	INSPECTOR'S TITLE	MOT Director
TIME OF INSPECTION	8:30	WEATHER CONDITION AT TIME OF INSPECTION	Cool
		NAME OF DISTRICT REPRESENTATIVE ACCOMPANYING THE INSPECTOR(S) (IF APPLICABLE)	David Kalk, Principal

PART III: CATEGORY TOTALS AND RANKING (round all calculations to two decimal places)

TOTAL NUMBER OF AREAS EVALUATED	CATEGORY TOTALS	A. SYSTEMS			B. INTERIOR		C. CLEANLINESS		D. ELECTRICAL		E. RESTROOMS/FOUNTAINS		F. SAFETY		G. STRUCTURAL		H. EXTERNAL		
		GAS LEAKS	MECHANICAL	SEWER	INTERIOR SURFACES	OVERALL CLEANLINESS	PEST/TERMIN INFESTATION	ELECTRICAL	RESTROOMS	SINKS/FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUND/SCHOOL GROUNDS	WINDOWS/DOORS/GATEPENCES			
8	Number of "✓'s":	8	8	7	7	8	8	8	8	8	8	8	8	8	6	8			
	Number of "D's":	0	0	1	1	0	0	0	0	0	0	0	0	0	2	0			
	Number of "X's":	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0			
Number of N/A's:		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0			
Percent of System in Good Repair: Number of "✓'s" divided by (Total Areas - "NA's")		100.00%	100.00%	87.50%	87.50%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	75.00%	100.00%				
Total Percent per Category (Average of Above)*		95.83%			87.50%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	87.50%					
Rank (Circle one)		GOOD			FAIR	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	FAIR					
GOOD = 90%-100% FAIR = 75%-89.99% POOR = 0%-74.99%																			

*Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category and a zero for "Total Percent per Category".

OVERALL RATING:

DETERMINE AVERAGE PERCENTAGE OF 8 CATEGORIES ABOVE

96.35%

SCHOOL RATING**

GOOD

**For School Rating, apply the Percentage Range below to the average percentage determined above, taking into account the rating Description below.

PERCENTAGE	DESCRIPTION	RATING
99%-100%	The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.	EXEMPLARY
90%-98.99%	The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.	GOOD
75%-89.99%	The school is not in good repair. Some deficiencies noted are critical and/or widespread. Repairs and/or additional maintenance are necessary in several areas of the school site.	FAIR
0%-74.99%	The school facilities are in poor condition. Deficiencies of various degrees have been noted throughout the site. Major repairs and maintenance are necessary throughout the campus.	POOR

COMMENTS AND RATING EXPLANATION:

PART II: EVALUATION DETAIL Date of Inspection: **06/29/21**

School Name: **Bishop Union High School**

CATEGORY	Date of Inspection: 06/29/21														
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
AREA	GAS LEAKS	MECH/HVAC	SEWER	INTERIOR SURFACES	OVERALL CLEANLINESS	PEST/TERMIN INFESTATION	ELECTRICAL	RESTROOM	SINKS/ FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUND/S CHOL. GROUNDS	WINDOWS/ DOORS/ GATES/FENCES
Bldg 100	✓	✓	✓	D	✓	✓	✓	✓	✓	✓	✓	✓	✓	D	✓
	COMMENTS: Multiple damaged flooring areas.														
Bldg 200	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS: Tree roots have lifted asphalt - trip hazard, mall area.														
Bldg 300	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:														
Group 400	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:														
Group 500	✓	✓	D	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS: Tree roots have lifted asphalt - trip hazard, mall area.														
Bldg 600	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:														
Bldg 700	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:														
Bldg 800	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:														
	COMMENTS:														
	COMMENTS:														
	COMMENTS:														
	COMMENTS:														

Marks: ✓ = Good Repair (When filling up the electronic version, please use **ctH+G**); D = Deficiency; X = Extreme Deficiency; NA = Not Applicable
 Use additional sheets as necessary.

STATE OF CALIFORNIA
FACILITY INSPECTION TOOL(FIT)
SCHOOL FACILITY CONDITIONS EVALUATION
 (REV 05/09)

STATE ALLOCATION BOARD
 OFFICE OF PUBLIC SCHOOL CONSTRUCTION

SCHOOL DISTRICT/COUNTY OFFICE OF EDUCATION		COUNTY	Inyo
School Site		SCHOOL TYPE (GRADE LEVELS)	Tenth - twelfth
Bishop Unified School District		NUMBER OF CLASSROOMS ON SITE	4
Pallisades Glacier High School		INSPECTOR'S TITLE	MOT Director
INSPECTOR'S NAME		NAME OF DISTRICT REPRESENTATIVE ACCOMPANYING THE INSPECTOR(S) (IF APPLICABLE)	Patrick Twomey-Principal
Todd Remley		TIME OF INSPECTION	9:30
9:30		Hot	

PART III: CATEGORY TOTALS AND RANKING (round all calculations to two decimal places)

TOTAL NUMBER OF AREAS EVALUATED	CATEGORY TOTALS	A. SYSTEMS			B. INTERIOR	C. CLEANLINESS		D. ELECTRICAL	E. RESTROOMS/FOUNTAINS		F. SAFETY		G. STRUCTURAL		H. EXTERNAL	
		GAS LEAKS	MECHANICAL	SEWER	INTERIOR SURFACES	OVERALL CLEANLINESS	PEST/VERMIN INFESTATION	ELECTRICAL	RESTROOMS	SINKS/ FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUND/ SCHOOL GROUNDS	WINDOWS/DOORS/ GATES/FENCES
7	Number of "A"s:	6	7	3	7	7	7	7	1	2	7	6	7	7	7	7
	Number of "D"s:	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0
	Number of "X"s:	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
	Number of N/A's:	1	0	4	0	0	0	0	6	5	0	0	0	0	0	0
Percent of System in Good Repair Number of "A"s divided by (Total Areas - "N/A"s) [*]		100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	85.71%	100.00%	100.00%	100.00%	100.00%
Total Percent per Category (average of above) [*]		100.00%			100.00%	100.00%		100.00%	100.00%		100.00%	92.86%		100.00%		100.00%
Rank (Circle one) GOOD = 90%-100% FAIR = 75%-89.99% POOR = 0%-74.99%		GOOD			GOOD	GOOD		GOOD	GOOD		GOOD	GOOD		GOOD		GOOD

*Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category and a zero for "Total Percent per Category".

OVERALL RATING:

DETERMINE AVERAGE PERCENTAGE OF 8 CATEGORIES ABOVE	99.11%	SCHOOL RATING**	EXEMPLARY
---	---------------	------------------------	------------------

**For School Rating, apply the Percentage Range below to the average percentage determined above, taking into account the rating Description below.

PERCENTAGE	DESCRIPTION	RATING
99%-100%	The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.	EXEMPLARY
90%-98.99%	The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated and/or resulting from minor wear and tear and/or in the process of being mitigated.	GOOD
75 %-89.99%	The school is not in good repair. Some deficiencies noted are critical and/or widespread. Repairs and/or additional maintenance are necessary in several areas of the school site.	FAIR
0%-74.99%	The school facilities are in poor condition. Deficiencies of various degrees have been noted throughout the site. Major repairs and maintenance are necessary throughout the campus.	POOR

COMMENTS AND RATING EXPLANATION:

Siding to be placed on the five year plan. Due to cost, the project will be completed over 3 years.

PART II: EVALUATION DETAIL Date of Inspection: **06/29/21**

School Name: Palisades Glacier High School

CATEGORY	Date of Inspection: 06/29/21															
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	
AREA	GAS LEAKS	MECH/PVAC	SEWER	INTERIOR SURFACES	OVERALL CLEANLINESS	PEST/VERMIN INFESTATION	ELECTRICAL	RESTROOM	SINKS/ FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUND/S CHOL. GROUNDS	WINDOW/ DOOR/ GATES/FENCES	
Restroom Bldg	NA	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	COMMENTS:															
Office Bldg	✓	✓	NA	✓	✓	✓	✓	NA	✓	✓	✓	D	✓	✓	✓	
	COMMENTS:	South facing exterior walls in need of repair.														
English Bldg	✓	✓	NA	✓	✓	✓	✓	NA	NA	✓	✓	✓	✓	✓	✓	
	COMMENTS:															
Science Bldg	✓	✓	✓	✓	✓	✓	✓	NA	NA	✓	✓	✓	✓	✓	✓	
	COMMENTS:															
Social Sciences Bldg	✓	✓	NA	✓	✓	✓	✓	NA	NA	✓	✓	✓	✓	✓	✓	
	COMMENTS:															
Computer Lab	✓	✓	✓	✓	✓	✓	✓	NA	NA	✓	✓	✓	✓	✓	✓	
	COMMENTS:															
Tool Shed, Pump House, Storage Area	✓	✓	NA	✓	✓	✓	✓	NA	NA	✓	✓	✓	✓	✓	✓	
	COMMENTS:															
	COMMENTS:															
	COMMENTS:															
	COMMENTS:															
	COMMENTS:															
	COMMENTS:															
	COMMENTS:															

Marks: ✓ = Good Repair (When filling up the electronic version, please use **ctH+G**); D = Deficiency; X = Extreme Deficiency; NA = Not Applicable
 Use additional sheets as necessary.

PART II: EVALUATION DETAIL		Date of Inspection: 06/29/21		School Name: Home Street Middle School													
AREA	CATEGORY	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	
		GAS LEAKS	MECH/HVAC	SEWER	INTERIOR SURFACES	OVERALL CLEANLINESS	PEST/VERMIN INSPECTION	ELECTRICAL	RESTROOM	SINKS/ FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUNDS/ CHOCOL GROUNDS	WINDOWS/ DOORS/ GATES/FENCES	
6th Wing	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	COMMENTS:	Restroom needs patch and paint.															
	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
7th Wing	COMMENTS:	Restroom needs patch and paint.															
	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	COMMENTS:																
8th Wing	COMMENTS:																
	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	COMMENTS:																
Main Hall	COMMENTS:	Curb by handicap ramp uneven															
	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	D	✓
	COMMENTS:																
Science/Music	COMMENTS:																
	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	COMMENTS:																
MP Room	COMMENTS:	Restroom needs patch and paint.															
	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	COMMENTS:																
	COMMENTS:																
	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	COMMENTS:																
	COMMENTS:																
	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	COMMENTS:																
	COMMENTS:																
	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	COMMENTS:																
	COMMENTS:																
	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	COMMENTS:																

Marks: ✓ = Good Repair (When filling up the electronic version, please use **ctH+G**); D = Deficiency; X = Extreme Deficiency; NA = Not Applicable
 Use additional sheets as necessary.

STATE OF CALIFORNIA
FACILITY INSPECTION TOOL(FIT)
SCHOOL FACILITY CONDITIONS EVALUATION
 (REV 09/09)

STATE ALLOCATION BOARD
 OFFICE OF PUBLIC SCHOOL CONSTRUCTION

SCHOOL DISTRICT/COUNTY OFFICE OF EDUCATION		COUNTY	Inyo
Bishop Unified School District		SCHOOL TYPE (GRADE LEVELS)	Six - Eight
SCHOOL SITE		HOME STREET MIDDLE SCHOOL	NUMBER OF CLASSROOMS ON SITE
INSPECTOR'S NAME		Todd Renley	MOT Director
INSPECTOR'S TITLE		MOT Director	Derek Moisant- Principal
TIME OF INSPECTION		8:00	Hot
WEATHER CONDITION AT TIME OF INSPECTION		Hot	

PART III: CATEGORY TOTALS AND RANKING (round all calculations to two decimal places)

TOTAL NUMBER OF AREAS EVALUATED	CATEGORY TOTALS	A. SYSTEMS			B. INTERIOR		C. CLEANLINESS		D. ELECTRICAL	E. RESTROOMS/FOUNTAINS		F. SAFETY		G. STRUCTURAL		H. EXTERNAL	
		GAS LEAKS	MECH/HVAC	SEWER	INTERIOR SURFACES	OVERALL CLEANLINESS	PEST/VERMIN INFESTATION	ELECTRICAL	RESTROOMS	SINKS/ FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUND/ SCHOOL GROUNDS	WINDOWS/DOORS/ GATES/FENCES	
6	Number of "✓"'s:	6	6	6	6	6	6	6	6	6	6	6	6	5	6		
	Number of "D"'s:	0	0	0	0	0	0	0	0	0	0	0	0	1	0		
	Number of "X"'s:	0	0	0	0	0	0	0	0	0	0	0	0	0	0		
Number of N/A's:		0	0	0	0	0	0	0	0	0	0	0	0	0	0		
Percent of System in Good Repair Number of "✓"'s divided by (Total Areas - "NA"'s)*		100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	83.33%	100.00%		
Total Percent per Category (average of above)*		100.00%			100.00%		100.00%		100.00%	100.00%		100.00%		91.67%			
Rank (Circle one) GOOD = 90%-100% FAIR = 75%-89.99% POOR = 0%-74.99%		GOOD			GOOD		GOOD		GOOD	GOOD		GOOD		GOOD			

*Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category and a zero for "Total Percent per Category".

OVERALL RATING: **DETERMINE AVERAGE PERCENTAGE OF 8 CATEGORIES ABOVE** **98.96%** **SCHOOL RATING**** **GOOD**

**For School Rating, apply the Percentage Range below to the average percentage determined above, taking into account the rating Description below.

PERCENTAGE	DESCRIPTION	RATING
93%-100%	The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.	EXEMPLARY
90%-98.99%	The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.	GOOD
75 %-89.99%	The school is not in good repair. Some deficiencies noted are critical and/or widespread. Repairs and/or additional maintenance are necessary in several areas of the school site.	FAIR
0%-74.99%	The school facilities are in poor condition. Deficiencies of various degrees have been noted throughout the site. Major repairs and maintenance are necessary throughout the campus.	POOR

COMMENTS AND RATING EXPLANATION:
