

Valenzuela/CAHSEE Lawsuit Settlement
Quarterly Report on Williams Uniform Complaints
 [Education Code §35186(d)]

District: BUSD Date: 6/30/2022

Person completing this form: Stephanie Fritz Title: Chief Business Officer

Quarterly Report Submission Date: October 2021 (Jul – Sep)
 (check one) January 2022 (Oct – Dec)
 April 2022 (Jan – Mar)
 July 2022 (Apr – Jun)

Date for information to be reported publicly at governing board meeting: 7/28/2022

Please check the box that applies:

- No complaints were filed with any school in the district during the quarter indicated above.
- Complaints were filed with schools in the district during the quarter indicated above. The following chart summarizes the nature and resolution of these complaints.

General Subject Area	Total # of Complaints	# Resolved	# Unresolved
Textbooks and Instructional Materials			
Teacher Vacancy or Misassignment			
Facilities Conditions			
CAHSEE Intensive Instruction and Services			
TOTALS	0		

Katie Kolker
 Print Name of District Superintendent

 Signature of District Superintendent 7/28/2022
 Date

PART II: EVALUATION DETAIL		Date of Inspection: 05/21/22 School Name: Palisades Glacier High School														
CATEGORY	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	
AREA	GV'S LEAKS	MECHANICAL	SEWER	INTERIOR SURFACES	OVERALL CONDITION	RESTROOM/INVESTIGATION	ELECTRICAL	RESTROOM	SINKS/FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUNDS/SCHOOL GROUNDS	WINDOWS/DOORS/GATES/FENCES	
Restroom Bldg	NA	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
COMMENTS:																
Office Bldg	✓	✓	NA	✓	✓	✓	✓	NA	✓	✓	✓	D	✓	✓	✓	
COMMENTS:	South facing exterior walls in need of repair.															
English Bldg	✓	✓	NA	✓	✓	✓	✓	NA	NA	✓	✓	✓	✓	✓	✓	
COMMENTS:																
Science Bldg	✓	✓	✓	✓	✓	✓	✓	NA	NA	✓	✓	✓	✓	✓	✓	
COMMENTS:																
Social Sciences Bldg	✓	✓	NA	✓	✓	✓	✓	NA	NA	✓	✓	✓	✓	✓	✓	
COMMENTS:																
Computer Lab	✓	✓	✓	✓	✓	✓	✓	NA	NA	✓	✓	✓	✓	✓	✓	
COMMENTS:																
Tool Shed, Pump House, Storage Area	✓	✓	NA	✓	✓	✓	✓	NA	NA	✓	✓	✓	✓	✓	✓	
COMMENTS:																
COMMENTS:																
COMMENTS:																
COMMENTS:																
COMMENTS:																
COMMENTS:																

Marks: ✓ = Good Repair (When filling up the electronic version, please use ctrl+G); D = Deficiency; X = Extreme Deficiency; NA = Not Applicable
 Use additional sheets as necessary.

SCHOOL DISTRICT/COUNTY OFFICE OF EDUCATION Bishop Unified School District		COUNTY Inyo
SCHOOL SITE Palisades Glacier High School		SCHOOL TYPE (GRADE LEVELS) Tenth - twelfth
INSPECTOR'S NAME Todd Remley		NUMBER OF CLASSROOMS ON SITE 4
INSPECTOR'S TITLE MOT Director		NAME OF DISTRICT REPRESENTATIVE ACCOMPANYING THE INSPECTOR(S) (IF APPLICABLE) Patrick Twomey- Principal
TIME OF INSPECTION 10:30		
		Hot/ sunny

PART III: CATEGORY TOTALS AND RANKING (round all calculations to two decimal places)

TOTAL NUMBER OF AREAS EVALUATED	CATEGORY TOTALS	A. SYSTEMS			B. INTERIOR INTERIOR SURFACES	C. CLEANLINESS		D. ELECTRICAL ELECTRICAL	E. RESTROOMS/FOUNTAINS		F. SAFETY		G. STRUCTURAL		H. EXTERNAL	
		PLUMBING	MCHANICAL	SEWER		OVERALL CLEANLINESS	PEST/VERMIN INFESTATION		RESTROOMS	SINK/J FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUND/ SCHOOL GROUNDS	WINDOWS/DOORS/ GATES/FENCES
7		6	7	3	7	7	7	7	1	2	7	7	6	7	7	7
		0	0	0	0	0	0	0	0	0	0	0	1	0	0	0
		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
		1	0	4	0	0	0	0	6	5	0	0	0	0	0	0
	Percent of System in Good Repair Number of "Y's" divided by (Total Areas - "NA's")	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	85.71%	100.00%	100.00%	100.00%
	Total Percent per Category (Average of above)*	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	92.86%	100.00%	100.00%	100.00%
	Rank (Circle one) GOOD = 90%-100% FAIR = 75%-89.99% POOR = 0%-74.99%	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD

*Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category and a zero for "Total Percent per Category".

OVERALL RATING:	DETERMINE AVERAGE PERCENTAGE OF 8 CATEGORIES ABOVE	SCHOOL RATING**
	99.11%	EXEMPLARY

**For School Rating, apply the Percentage Range below to the average percentage determined above, taking into account the rating Description below.

PERCENTAGE	DESCRIPTION	RATING
99%-100%	The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.	EXEMPLARY
90%-98.99%	The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.	GOOD
75 %-89.99%	The school is not in good repair. Some deficiencies noted are critical and/or widespread. Repairs and/or additional maintenance are necessary in several areas of the school site.	FAIR
0%-74.99%	The school facilities are in poor condition. Deficiencies of various degrees have been noted throughout the site. Major repairs and maintenance are necessary throughout the campus.	POOR

COMMENTS AND RATING EXPLANATION:

Siding to be placed on the five year plan. Due to cost, the project will be completed over 3 years.

PART II: EVALUATION DETAIL		Date of Inspection: 03/29/22 School Name: Home Street Middle School															
AREA	CATEGORY	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	
		GAS LEAKS	MECH/HVAC	SEWER	INTERIOR SURFACES	OVERALL CLEANLINESS	PEST/VERMIN INFESTATION	ELECTRICAL	RESTROOM	SINKS/ FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUNDS SCHOOL GROUNDS	WINDOWS/ DOORS/ GATES/FENCES	
6th Wing		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	COMMENTS:	Restroom needs patch and paint.															
7th Wing		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	COMMENTS:	Restroom needs patch and paint.															
8th Wing		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	COMMENTS:																
Main Hall		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	D	✓
	COMMENTS:	Curb by handicap ramp uneven															
Science/Music		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:																
MP Room		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	D	✓	✓	✓
	COMMENTS:	Roof leaks in several places.															
	COMMENTS:																
	COMMENTS:																
	COMMENTS:																
	COMMENTS:																
	COMMENTS:																

Marks: ✓ = Good Repair (When filling up the electronic version, please use ctrl+G); D = Deficiency; X = Extreme Deficiency; NA = Not Applicable
 Use additional sheets as necessary.

SCHOOL DISTRICT/COUNTY OFFICE OF EDUCATION Bishop Unified School District		COUNTY Inyo
SCHOOL SITE Home Street Middle School	SCHOOL TYPE (GRADE LEVELS) Six - Eight	NUMBER OF CLASSROOMS ON SITE 25
INSPECTOR'S NAME Todd Remley	NAME OF DISTRICT REPRESENTATIVE ACCOMPANYING THE INSPECTOR(S) (IF APPLICABLE) Derek Moisant-Principal	
INSPECTOR'S TITLE MOT Director	INSPECTOR'S TITLE	
TIME OF INSPECTION 9:00	WEATHER CONDITION AT TIME OF INSPECTION Hot/ sunny	

PART III: CATEGORY TOTALS AND RANKING (round all calculations to two decimal places)

TOTAL NUMBER OF AREAS EVALUATED	CATEGORY TOTALS	A. SYSTEMS			B. INTERIOR		C. CLEANLINESS		D. ELECTRICAL		E. RESTROOMS/FOUNTAINS		F. SAFETY		G. STRUCTURAL		H. EXTERNAL	
		PLUMBING	Mechanical	SEWER	Interior Surfaces	Overall Cleanliness	Pest/Vermin Infestation	Electrical	Restrooms	Sinks/Fountains	Fire Safety	Hazardous Materials	Structural Damage	Roofs	Playground/School Grounds	Windows/Doors/Gateways		
6	Number of 'Y's: Number of 'O's: Number of 'X's: Number of N/A's:	6	0	0	6	6	6	6	6	6	6	6	6	5	6	5	1	0
6	Percent of System in Good Repair Number of 'Y's divided by (Total Areas - 'N/A's')	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	83.33%	100.00%	100.00%
Total Percent per Category (average of above)*		100.00%		100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	91.67%	91.67%	83.33%	100.00%	100.00%
Rank (Circle one) GOOD = 90%-100% FAIR = 75%-89.99% POOR = 0%-74.99%		GOOD		GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD

*Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category and a zero for "Total Percent per Category".

OVERALL RATING:	DETERMINE AVERAGE PERCENTAGE OF 8 CATEGORIES ABOVE	SCHOOL RATING**
	97.92%	GOOD

**For School Rating, apply the Percentage Range below to the average percentage determined above, taking into account the rating Description below.

PERCENTAGE	DESCRIPTION	RATING
99%-100%	The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.	EXEMPLARY
90%-99.99%	The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.	GOOD
75 %-89.99%	The school is not in good repair. Some deficiencies noted are critical and/or widespread. Repairs and/or additional maintenance are necessary in several areas of the school site.	FAIR
0%-74.99%	The school facilities are in poor condition. Deficiencies of various degrees have been noted throughout the site. Major repairs and maintenance are necessary throughout the campus.	POOR

COMMENTS AND RATING EXPLANATION:

PART II: EVALUATION DETAIL		Date of Inspection: <u>06/21/22</u> School Name: <u>Bishop Elementary</u>														
AREA	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	
CATEGORY	GAS LEAKS	MECH/HVAC	SEWER	INTERIOR SURFACES	OVERALL CLEANLINESS	PEST/TERMIN INFESTATION	ELECTRICAL	RESTROOM	SINKS/FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUNDS/SCHOOL GROUNDS	WINDMYS/DOORS/GATES/FENCES	
Kindergarten	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
COMMENTS:																
First Grade	✓	✓	✓	✓	✓	✓	✓	D	✓	✓	✓	✓	✓	✓	✓	
COMMENTS: Restrooms need tile repairs and paint.																
Second Grade	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
COMMENTS:																
Office Buildings	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
COMMENTS:																
Third/Fourth Grade	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
COMMENTS:																
Bungalows	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
COMMENTS:																
Fifth Grade	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
COMMENTS:																
BAC	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
COMMENTS:																
COMMENTS:																
COMMENTS:																
COMMENTS:																
COMMENTS:																

Marks: ✓ = Good Repair (When filling up the electronic version, please use ctrl+G) ; D = Deficiency; X = Extreme Deficiency; NA = Not Applicable
 Use additional sheets as necessary.

SCHOOL DISTRICT/COUNTY OFFICE OF EDUCATION Bishop Unified School District		COUNTY Inyo	NUMBER OF CLASSROOMS ON SITE 50
SCHOOL SITE Bishop Elementary		SCHOOL TYPE (GRADE LEVELS) K - 5	
INSPECTOR'S NAME Todd Remley		NAME OF DISTRICT REPRESENTATIVE ACCOMPANYING THE INSPECTOR(S) (IF APPLICABLE) Gretchen Skrotzki - Principal	
INSPECTOR'S TITLE MOT Director			
TIME OF INSPECTION 8:30		WEATHER CONDITION AT TIME OF INSPECTION Hot/ sunny	

PART III: CATEGORY TOTALS AND RANKING (round all calculations to two decimal places)

TOTAL NUMBER OF AREAS EVALUATED	CATEGORY TOTALS	A. SYSTEMS			B. INTERIOR SURFACES	C. CLEANLINESS		D. ELECTRICAL	E. RESTROOMS/FOUNTAINS		F. SAFETY		G. STRUCTURAL		H. EXTERNAL			
		GAS LEAKS	MECH/HVAC	SEWER		OVERALL CLEANLINESS	RESTROOM INFESTATION		ELECTRICAL	RESTROOMS	SINKS/FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUND/SCHOOL SUROUNDS	WINDOWS/DOORS/GATES/FENCES	
8	Number of "1"s: Number of "0"s: Number of "X"s: Number of N/A's:	8 0 0 0	8 0 0 0	8 0 0 0	8 0 0 0	8 0 0 0	8 0 0 0	8 0 0 0	7 1 0 0	8 0 0 0	8 0 0 0	8 0 0 0	8 0 0 0	8 0 0 0	8 0 0 0	8 0 0 0		
	Percent of System in Good Repair Number of "1"s divided by (Total Areas - "N/A's")	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	87.50%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	
	Total Percent per Category (average of above)	100.00%			100.00%	100.00%	100.00%	93.75%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	
	Rank (Circle one) GOOD = 99%-100% FAIR = 75%-99.99% POOR = 0%-74.99%	GOOD			GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD

*Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category and a zero for "Total Percent per Category".

OVERALL RATING:	DETERMINE AVERAGE PERCENTAGE OF 8 CATEGORIES ABOVE	SCHOOL RATING**
	99.22%	EXEMPLARY

**For School Rating, apply the Percentage Range below to the average percentage determined above, taking into account the rating Description below.

PERCENTAGE	DESCRIPTION	RATING
99%-100%	The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.	EXEMPLARY
90%-99.99%	The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.	GOOD
75 %-89.99%	The school is not in good repair. Some deficiencies noted are critical and/or widespread. Repairs and/or additional maintenance are necessary in several areas of the school site.	FAIR
0%-74.99%	The school facilities are in poor condition. Deficiencies of various degrees have been noted throughout the site. Major repairs and maintenance are necessary throughout the campus.	POOR

COMMENTS AND RATING EXPLANATION:

STATE OF CALIFORNIA
FACILITY INSPECTION TOOL
 SCHOOL FACILITY CONDITIONS EVALUATION
 (REV 05/09)

PART II: EVALUATION DETAIL		Date of Inspection: <u>06/27/22</u>		School Name: <u>Bishop Union High School</u>												
AREA	CATEGORY	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
		GAS LEAKS	MECHRVAC	SEWER	INTERIOR SURFACES	OVERALL CLEANLINESS	PEST/VERMIN INFESTATION	ELECTRICAL	RESTROOM	SINKS/ FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUND/SCHOOL GROUNDS	WINDOWS/ DOORS/ GATES/FENCES
Bldg 100		✓	✓	✓	D	✓	✓	✓	✓	✓	✓	✓	✓	✓	D	✓
	COMMENTS:	Multiple damaged flooring areas.														
Bldg 200		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	D	✓
	COMMENTS:	Tree roots have lifted asphalt - trip hazard, mall area.														
Bldg 300		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:															
Group 400		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:															
Group 500		✓	✓	D	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:	Tree roots have lifted asphalt - trip hazard, mall area.														
Bldg 600		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	D	✓
	COMMENTS:															
Bldg 700		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:															
Bldg 800		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:															
	COMMENTS:															
	COMMENTS:															
	COMMENTS:															
	COMMENTS:															
	COMMENTS:															

Marks: ✓ = Good Repair (When filling up the electronic version, please use ctrl+G); D = Deficiency; X = Extreme Deficiency; NA = Not Applicable

SCHOOL DISTRICT/COUNTY OFFICE OF EDUCATION		COUNTY	
Bishop Unified School District		Inyo	
SCHOOL SITE		SCHOOL TYPE (GRADE LEVELS)	NUMBER OF CLASSROOMS ON SITE
Bishop Union High School		Nine - Twelve	38
INSPECTOR'S NAME		NAME OF DISTRICT REPRESENTATIVE ACCOMPANYING THE INSPECTOR(S) (IF APPLICABLE)	
Todd Remley		David Kalk, Principal	
INSPECTOR'S TITLE			
MOT Director			
TIME OF INSPECTION		WEATHER CONDITION AT TIME OF INSPECTION	
9:30		Hot/ sunny	

PART III: CATEGORY TOTALS AND RANKING (round all calculations to two decimal places)

TOTAL NUMBER OF AREAS EVALUATED	CATEGORY TOTALS	A. SYSTEMS			B. INTERIOR SUPPLY	C. CLEANLINESS	D. ELECTRICAL	E. RESTROOMS/PLUMBING		F. SAFETY	G. STRUCTURAL		H. EXTERNAL	
		GAS LINES	MECHANICAL	SEWER				RESTROOMS	SINKS/ FOUNTAINS		FIRE SAFETY	HAZARDOUS MATERIALS		STRUCTURAL DAMAGE
8	Number of 'Y's'	8	7	7	8	8	8	8	8	8	8	7	6	8
	Number of 'Z's'	0	1	1	0	0	0	0	0	0	0	1	2	0
	Number of 'X's'	0	0	0	0	0	0	0	0	0	0	0	0	0
	Number of 'N/A's'	0	0	0	0	0	0	0	0	0	0	0	0	0
	Percent of System in Good Repair	100.00%	100.00%	87.50%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	87.50%	75.00%	100.00%
	Number of 'Y's' divided by (Total Areas - 'N/A's')	95.83%		87.50%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	93.75%	87.50%	87.50%	
	Total Percent per Category (average of above)	GOOD		FAIR	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	GOOD	FAIR
	Rank (Given one)	GOOD = 95.83%		FAIR = 87.50%	GOOD = 100.00%	GOOD = 100.00%	GOOD = 100.00%	GOOD = 100.00%	GOOD = 100.00%	GOOD = 100.00%	GOOD = 93.75%	GOOD = 87.50%	GOOD = 87.50%	
	GOOD = 95.83%	GOOD = 95.83%		FAIR = 87.50%	GOOD = 100.00%	GOOD = 100.00%	GOOD = 100.00%	GOOD = 100.00%	GOOD = 100.00%	GOOD = 100.00%	GOOD = 93.75%	GOOD = 87.50%	GOOD = 87.50%	
	FAIR = 87.50%	GOOD = 95.83%		FAIR = 87.50%	GOOD = 100.00%	GOOD = 100.00%	GOOD = 100.00%	GOOD = 100.00%	GOOD = 100.00%	GOOD = 100.00%	GOOD = 93.75%	GOOD = 87.50%	GOOD = 87.50%	
	POOR = 0%	GOOD = 95.83%		FAIR = 87.50%	GOOD = 100.00%	GOOD = 100.00%	GOOD = 100.00%	GOOD = 100.00%	GOOD = 100.00%	GOOD = 100.00%	GOOD = 93.75%	GOOD = 87.50%	GOOD = 87.50%	

*Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category and a zero for "Total Percent per Category".

OVERALL RATING:	DETERMINE AVERAGE PERCENTAGE OF 8 CATEGORIES ABOVE	SCHOOL RATING**
	95.57%	GOOD

**For School Rating, apply the Percentage Range below to the average percentage determined above, taking into account the rating Description below.

PERCENTAGE	DESCRIPTION	RATING
99%-100%	The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.	EXEMPLARY
90%-99.99%	The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.	GOOD
75 %-89.99%	The school is not in good repair. Some deficiencies noted are critical and/or widespread. Repairs and/or additional maintenance are necessary in several areas of the school site.	FAIR
0%-74.99%	The school facilities are in poor condition. Deficiencies of various degrees have been noted throughout the site. Major repairs and maintenance are necessary throughout the campus.	POOR

COMMENTS AND RATING EXPLANATION:

--