

Bid Pack #5 - Construction Progress Update 5/31/22

Apollo Early Childhood Center






Canopy Roof prepped and ready for Tectum Deck.

EPDM roofing installed on secured entry addition.




Bid Pack #5 - Construction Progress Update 5/31/22

Apollo Early Childhood Center



Installation of damp proofing prepped for spray foam insulation.



Interior metal studs and Hollow metal door frames installed



Bid Pack #5 - Construction Progress Update 5/31/22

Apollo Early Childhood Center





HVAC duct work being installed

Toilet room concrete poured back and ready for CMU walls



Bid Pack #5 - Construction Progress Update 5/31/22

Country Oaks Elementary School



Roof sumps and piping being installed




Spray foam insulation is completed in preparation for face brick at exterior walls and densglass installed.



Bid Pack #5 - Construction Progress Update 5/31/22

Country Oaks Elementary School



Interior toilet room new sink carrier and rough plumbing installed



Bid Pack #5 - Construction Progress Update 5/31/22

Heritage Elementary School





Face brick laid at new addition and Densglass Sheathing put in place on exterior walls.


Wood blocking and sheathing installed in prep for metal panels.



Bid Pack #5 - Construction Progress Update 5/31/22

Heritage Elementary School






Spray foam insulation is completed in preparation for face brick at exterior walls

HVAC duct work being installed



Bid Pack #5 - Construction Progress Update 5/31/22

Kurtz Elementary School






Curb for new RTU is Set and concrete in corridor poured

Face Brick laid at new addition



Bid Pack #5 - Construction Progress Update 5/31/22

Kurtz Elementary School



Vapor barrier and reinforcing steel are in place ahead of concrete floor slab pour




Concrete floor slab being poured and leveled in the Secured Entry Addition




Bid Pack #5 - Construction Progress Update 5/31/22

Kurtz Elementary School



Slab on grade poured at secured entry addition




Roof sumps and piping being installed



Bid Pack #5 - Construction Progress Update 5/31/22

Spring Mills Elementary School



Structural Steel being set in place over the gymnasium.



Structural Steel detailing throughout the addition



Bid Pack #5 - Construction Progress Update 5/31/22

Spring Mills Elementary School





New equipment pad for new chiller poured




Bid Pack #5 - Construction Progress Update 5/31/22

Spring Mills Elementary School







Above ceiling electrical rough in is on-going.