



# HURON VALLEY SCHOOLS 2020 Bond Program

Bid Pack #5 - Construction Progress Update

6/27/22

## Apollo Early Childhood Center



Drywall prep for paint on going at secured entry office area



Drywall prep for paint on going at secured entry reception area.




# HURON VALLEY SCHOOLS 2020 Bond Program

## Bid Pack #5 - Construction Progress Update

6/27/22

### Apollo Early Childhood Center



Multi-purpose room being laid out for zig-zag wall.



New sign foundation poured






# HURON VALLEY SCHOOLS 2020 Bond Program

Bid Pack #5 - Construction Progress Update

6/27/22

## Apollo Early Childhood Center



Wall tile in the new bathrooms



**HURON VALLEY SCHOOLS 2020 Bond Program**  
Bid Pack #5 - Construction Progress Update  
6/27/22

**Apollo Early Childhood Center**



Secured entry sidewalks being formed.



New sidewalks poured at secured entry





**HURON VALLEY SCHOOLS 2020 Bond Program**  
Bid Pack #5 - Construction Progress Update  
6/27/22

**Apollo Early Childhood Center**



New sidewalks poured at secured entry




**HURON VALLEY SCHOOLS 2020 Bond Program**  
Bid Pack #5 - Construction Progress Update  
6/27/22

**Country Oaks Elementary School**



Drywall installation on going.




Old floor being removed in the multi-purpose room






**HURON VALLEY SCHOOLS 2020 Bond Program**  
Bid Pack #5 - Construction Progress Update  
6/27/22

**Country Oaks Elementary School**



Ceilings and floors removed in corridors



Parents drop off and pick up asphalt removed and prepped for new base layer of asphalt.



# HURON VALLEY SCHOOLS 2020 Bond Program

Bid Pack #5 - Construction Progress Update

6/27/22

## Country Oaks Elementary



Parents drop off and pick up asphalt base layer completed.






**HURON VALLEY SCHOOLS 2020 Bond Program**  
Bid Pack #5 - Construction Progress Update  
6/27/22

**Heritage Elementary School**



Drywall being hung in the new secured entry addition reception area.



Drywall hung in new office area of secured entry addition




**HURON VALLEY SCHOOLS 2020 Bond Program**  
Bid Pack #5 - Construction Progress Update  
6/27/22

**Heritage Elementary School**



New opening in the masonry wall



Classroom flooring and ceilings removed and ready for grinding.






# HURON VALLEY SCHOOLS 2020 Bond Program

Bid Pack #5 - Construction Progress Update

6/27/22

## Heritage Elementary



Floor protection installed throughout school



New roof on the secured entry



**HURON VALLEY SCHOOLS 2020 Bond Program**  
Bid Pack #5 - Construction Progress Update  
6/27/22

**Kurtz Elementary School**



Drywall being hung in the new secured entry addition reception area.



Drywall hung in new office area of secured entry addition





**HURON VALLEY SCHOOLS 2020 Bond Program**  
Bid Pack #5 - Construction Progress Update  
6/27/22

**Kurtz Elementary School**



Old floors removed in the multipurpose room



Flooring and ceilings removed in corridors



**HURON VALLEY SCHOOLS 2020 Bond Program**  
Bid Pack #5 - Construction Progress Update  
6/27/22

**Kurtz Elementary**



Existing asphalt removed and prepped for new base course.






**HURON VALLEY SCHOOLS 2020 Bond Program**  
Bid Pack #5 - Construction Progress Update  
6/27/22

**Spring Mills Elementary School**



Spray foam completed on classrooms and brick starter courses being laid.



Masonry brick work on going for gym addition



# HURON VALLEY SCHOOLS 2020 Bond Program

Bid Pack #5 - Construction Progress Update

6/27/22

## Spring Mills Elementary School



Gym addition masonry progressing and z-girts being installed.



Demo on going in new secured entry area.





**HURON VALLEY SCHOOLS 2020 Bond Program**  
Bid Pack #5 - Construction Progress Update  
6/27/22

**Spring Mills Elementary School**



Old chiller dismantled and removed.



Old entry removed and prepping for new secured entry.