


Bid Pack #5 - Construction Progress Update 6/13/22

Apollo Early Childhood Center







South Elevation of Secured Entry Addition - Brick, Spray Foam and Z-Girts for Metal Panel are being installed



Bid Pack #5 - Construction Progress Update 6/13/22

Apollo Early Childhood Center



Drywall Finishing is progressing in the Secured Entry Addition Reception Room




Demolition is progressing in the Old Multi-Purpose Room - Zone A



Bid Pack #5 - Construction Progress Update 6/13/22



Storage Trailers have been Mobilized for Move-out of Furniture & Furnishings



One of the 13 New Toilet Rooms are being prepared for Hard Tile Installation




Bid Pack #5 - Construction Progress Update 6/13/22

Country Oaks Elementary School



Temporary Enclosure is in Place for Secured Entry Addition to allow interior finish trade work to continue





Metal Stud Partitions are built in the Secured Entry Addition



Bid Pack #5 - Construction Progress Update 6/13/22

Country Oaks Elementary School







Z-Girts for Metal Panels are being installed.
Temporary Enclosure of Storefront Window Openings has been installed to allow interior finish work to continue.



Bid Pack #5 - Construction Progress Update 6/13/22

Heritage Elementary School





West Elevation of Secured Entry Addition - Brick, Spray Foam, Z-Girts for Metal Panel and Temporary Enclosure are in place West Elevation of Secured Entry Addition - Canopy Wood Blocking & Temporary Enclosure are in place



Bid Pack #5 - Construction Progress Update 6/13/22

Heritage Elementary School



Overhead Piping, Ductwork and Metal Stud Walls are being installed in the Secured Entry Addition



Metal Stud Walls are being built at Tie-in with the Secured Entry Addition



Bid Pack #5 - Construction Progress Update 6/13/22

Kurtz Elementary School



Hollow Metal Door Frames with Sidelights have been set for Offices in the Secured Entrance Addition




Hollow Metal Door Frames with Sidelights have been set for Offices in the Secured Entrance Addition




Bid Pack #5 - Construction Progress Update 6/13/22

Kurtz Elementary School



Overhead plumbing, sheet metal duck work and in-wall electrical rough-in are underway in the Secured Entry Addition



Face brick at the new main entrance is being installed



Bid Pack #5 - Construction Progress Update 6/13/22

Kurtz Elementary School






Cold Formed Metal Framing for Canopy Eyebrow is being installed

Temporary enclosure of the storefront window openings has been installed to allow finish trade work to continue in the Secured Entry Addition



Bid Pack #5 - Construction Progress Update 6/13/22

Spring Mills Elementary School



North & West Elevations of Gymnasium with Damproofing, Brick and Through-Wall Flashing being installed



North Elevation of Gymnasium with Damproofing, Brick and Through-Wall Flashing at Ramp being installed



Bid Pack #5 - Construction Progress Update 6/13/22

Spring Mills Elementary School





North Elevation of Gymnasium with Damproofing, Brick and Through-Wall Flashing at Ramp being installed East Elevation of Classrooms - Damproofing, Brick and Wood Blocking at the Parapet Cap is being installed




Bid Pack #5 - Construction Progress Update 6/13/22

Spring Mills Elementary School



South Elevation of Classrooms - Damproofing, Brick and Wood Blocking at the Parapet Cap is being installed



Interior Overhead Storm Piping, Electrical & Water Piping in Corridor Outside the New Classrooms in being installed