


Bid Pack #5 - Construction Progress Update 9/30/22

#### **Apollo Early Childhood Center**









Beveled Metal Soffit Panels at the Entrance Canopy are complete



Bid Pack #5 - Construction Progress Update 9/30/22

#### **Apollo Early Childhood Center**







Typical toilet room finishes in (12) added toilet rooms



Bid Pack #5 - Construction Progress Update 9/30/22

### **Apollo Early Childhood Center**






Typical added toilet rooms at each of the Centrums

Completed Media Center



Bid Pack #5 - Construction Progress Update 9/30/22

#### **Country Oaks Elementary School**





Storefront aluminum windows and entrance vestibule doors are installed

Storefront aluminum windows and wood door from Reception out to Corridor are installed



Bid Pack #5 - Construction Progress Update 9/30/22

#### **Country Oaks Elementary School**



Runtal Perimeter Heating Elements are installed in the Secured Entry Addition




Runtal Perimeter Heating Elements installed in the Secure Entry Addition



Bid Pack #5 - Construction Progress Update 9/30/22

### **Country Oaks Elementary School**





**Exterior Aluminum Entrance Doors are installed** 

FRP Egress Door and Sidelight at Classroom K-04 is installed



Bid Pack #5 - Construction Progress Update 9/30/22

#### **Heritage Elementary School**



Secured Entry Addition enclosure is complete except for metal panels and metal copings




Interior Aluminum Window Framing is being installed at the Secured Entrance Addition



Bid Pack #5 - Construction Progress Update 9/30/22

#### **Heritage Elementary School**



Interior Aluminum Window Framing is being installed at the Secured Entrance Addition





Exterior Aluminum Doors are installed at the Secured
Entrance Addition



Bid Pack #5 - Construction Progress Update 9/30/22

#### **Heritage Elementary School**





Millwork bench across from business offices is installed

FRP Egress Door and Sidelight at Classroom D-8 is being installed



Bid Pack #5 - Construction Progress Update 9/30/22

#### **Kurtz Elementary School**



Secured Entry Addition Exterior is complete except for metal panels and metal copings



New Flagpole and finished landscaping near the Secured Entrance Addition



Bid Pack #5 - Construction Progress Update 9/30/22

#### **Kurtz Elementary School**



Monument sign and paving is complete at the Secured Entrance Addition



Asphalt pathways have been seal coated




Bid Pack #5 - Construction Progress Update 9/30/22

### **Kurtz Elementary School**



Cafeteria renovation is complete



Typical corridor finishes



Bid Pack #5 - Construction Progress Update 9/30/22

#### **Spring Mills Elementary School**



Storefront Aluminum Windows and Entrance Doors are installed



Aluminum Windows and FRP Doors are installed at new the Gymnasium and Classroom Addition



Bid Pack #5 - Construction Progress Update 9/30/22

#### **Spring Mills Elementary School**



Metal panels and windows are installed at the New Classroom Addition



FRP Entrance Doors into Gymnasium and Classroom Addition are installed



Bid Pack #5 - Construction Progress Update 9/30/22

### **Spring Mills Elementary School**



Manufactured Casework in the New Art

Classroom is installed




Light fixtures are being installed in the new Gymnasium



Bid Pack #5 - Construction Progress Update 9/30/22

### **Spring Mills Elementary School**



Light fixtures are being installed in the new Gymnasium