

PART 3: SAMPLING & ANALYSIS WORKSHEET

Cayuga Heights Elementary School
1780 Como Park Blvd.
Depew, New York 14043
UNYSE Project: 16-0917JGD

Sample #	Room Name	Wall ID	Outlet #	Outlet Type	Lab ID	Result (mg/L)	Result (ppb)	Exceeds Limit
D1	Rm. 278	B	D1	S	001	ND	ND	NO
D2	Rm. 278	B	D2	DF	002	0.00101	1.01	NO
D3	Rm. 277	B	D3	S	003	0.00100	1.00	NO
D4	Rm. 277	B	D4	DF	004	0.00159	1.59	NO
D5	Rm. 178	D	D5	DF	005	0.01180	11.80	NO
D6	Rm. 178	D	D6	S	006	0.00565	5.65	NO
D7	Rm. 177	B	D7	DF	007	0.00309	3.09	NO
D8	Rm. 177	B	D8	S	008	0.00261	2.61	NO
D9	Rm. 176	D	D9	S	009	0.00297	2.97	NO
D10	Rm. 176	D	D10	DF	010	0.00274	2.74	NO
D11	Rm. 179	B	D11	S	011	0.12700	127.00	YES
D12	Rm. 179	B	D12	DF	012	0.00398	3.98	NO
D13	Rm. 180	D	D13	DF	013	0.00681	6.81	NO
D14	Rm. 180	D	D14	S	014	0.00552	5.52	NO
D15	Rm. 175	B	D15	S	015	0.00451	4.51	NO
D16	Rm. 175	B	D16	DF	016	0.00662	6.62	NO
D17	Rm. 174	D	D17	S	017	0.00412	4.12	NO
D18	Rm. 174	D	D18	DF	018	0.00204	2.04	NO
D19	Rm. 181	B	D19	S	019	0.00526	5.26	NO
D20	Rm. 181	B	D20	DF	020	0.00352	3.52	NO
D21	Hallway 188 at Rm. 182	C1	D21	DF	021	0.00210	2.10	NO
D22	Hallway 188 at Rm. 182	C2	D22	DF	022	0.00390	3.90	NO
D23	Rm. 182	D	D23	DF	023	0.00440	4.40	NO
D24	Rm. 182	D	D24	S	024	0.00204	2.04	NO
D25	Rm. 173	B	D25	DF	025	0.00544	5.44	NO
D26	Rm. 173	B	D26	S	026	0.00248	2.48	NO
D27	Rm. 172	D	D27	S	027	0.00427	4.27	NO
D28	Rm. 183	B	D28	S	028	0.00293	2.93	NO
D29	Rm. 183	B	D29	DF	029	0.00292	2.92	NO
D30	Rm. 171	D	D30	S	030	0.00505	5.05	NO

ASBESTOS | LEAD | MOLD | HAZMAT

ENVIRONMENTAL CONSULTANTS

877 466 4429

346 AUSTIN STREET **BUFFALO** NEW YORK 14207 | 716 833 2929 FAX 716 833 9292

4 COMMERCIAL STREET, LL **ROCHESTER** NEW YORK 14614 | 585 783 1465 FAX 585 783 1466

Sample #	Room Name	Wall ID	Outlet #	Outlet Type	Lab ID	Result (mg/L)	Result (ppb)	Exceeds Limit
D31	Rm. 171	D	D31	DF	031	0.00440	4.40	NO
D32	Rm. 184	D	D32	DF	032	0.00221	2.21	NO
D33	Rm. 184	D	D33	S	033	0.00175	1.75	NO
D34	Rm. 100 Nurses Office Exam Rm.	B	D34	S	034	0.00288	2.88	NO
D35	Rm. 100 Nurses Office Lavatory	B	D35	S	035	0.02730	27.30	YES
D36	Hallway 191 at Rm. 168	A1	D36	DF	036	0.00157	1.57	NO
D37	Hallway 191 at Rm. 168	A2	D37	DF	037	0.00142	1.42	NO
D38	Rm. 191 E Womans Lavatory	D1	D38	S	038	0.00827	8.27	NO
D39	Rm. 191 E Womans Lavatory	D2	D39	S	039	0.00615	6.15	NO
D40	Rm. 191 D Mens Lavatory	B1	D40	S	040	0.00395	3.95	NO
D41	Rm. 191 D Mens Lavatory	B2	D41	S	041	0.01660	16.60	YES
D42	185F Faculty Lavatory	B	D42	S	042	0.01860	18.60	YES
D43	Outside 185F	C	D43	DF	043	ND	ND	NO
D44	Rm. 114 Boys Lavatory	B2	D44	S	044	0.00341	3.41	NO
D45	Rm. 114 Boys Lavatory	B4	D45	S	045	0.00859	8.59	NO
D46	Rm. 115 Girls Lavatory	B1	D46	S	046	0.00560	5.60	NO
D47	Rm. 115 Girls Lavatory	B2	D47	S	047	0.00464	4.64	NO
D48	Rm. 115 Girls Lavatory	B3	D48	S	048	0.00393	3.93	NO
D49	Rm. 115 Girls Lavatory	B4	D49	S	049	0.00395	3.95	NO
D50	Rm. 160 Girls Lavatory	A1	D50	S	050	0.00761	7.61	NO
D51	Rm. 160 Girls Lavatory	A2	D51	S	051	0.00771	7.71	NO
D52	Rm. 160 Girls Lavatory	A3	D52	S	052	0.00293	2.93	NO

ASBESTOS | LEAD | MOLD | HAZMAT

ENVIRONMENTAL CONSULTANTS

877 466 4429

346 AUSTIN STREET **BUFFALO** NEW YORK 14207 | 716 833 2929 FAX 716 833 9292

4 COMMERCIAL STREET, LL **ROCHESTER** NEW YORK 14614 | 585 783 1465 FAX 585 783 1466

Sample #	Room Name	Wall ID	Outlet #	Outlet Type	Lab ID	Result (mg/L)	Result (ppb)	Exceeds Limit
D53	Rm. 160 Girls Lavatory	A4	D53	S	053	0.00666	6.66	NO
D54	Hallway 192 at Rm. 159	A5	D54	S	054	0.00107	1.07	NO
D55	Hallway 192 at Rm. 159	D1	D55	DF	055	0.00112	1.12	NO
D56	Rm. 159 Boys Lavatory	C1	D56	S	056	0.00950	9.50	NO
D57	Rm. 159 Boys Lavatory	C2	D57	S	057	0.00639	6.39	NO
D58	Rm. 159 Boys Lavatory	C3	D58	S	058	0.00863	8.63	NO
D59	Hallway 192 at Rm. 121	D1	D59	DF	059	ND	ND	NO
D60	Hallway 192 at Rm. 121	D2	D60	DF	060	ND	ND	NO
D61	Rm. 122	C	D61	S	061	0.01660	16.60	YES
D62	Rm. 122	A	D62	S	062	0.01120	11.20	NO
D63	Rm. 141A Girls Lavatory	B1	D63	S	063	0.00500	5.00	NO
D64	Rm. 141A Girls Lavatory	B2	D64	S	064	0.00212	2.12	NO
D65	Rm. 141A Girls Lavatory	B3	D65	S	065	0.00289	2.89	NO
D66	Rm. 141A Girls Lavatory	B4	D66	S	066	0.00480	4.80	NO
D67	Rm. 141B Boys Lavatory	D1	D67	S	067	0.00616	6.16	NO
D68	Rm. 141B Boys Lavatory	D2	D68	S	068	0.00495	4.95	NO
D69	Rm. 141B Boys Lavatory	D3	D69	S	069	0.00810	8.10	NO
D70	Hallway 192 at Rm. 140	A	D70	DF	070	0.00100	1.00	NO
D71	Rm. 140	A	D71	S	071	0.03900	39.00	YES
D72	Rm. 129	A	D72	S	072	0.02600	26.00	YES
D73	Rm. 239 Boys Lavatory	C1	D73	S	073	0.00182	1.82	NO
D74	Rm. 239 Boys Lavatory	C2	D74	S	074	ND	ND	ND
D75	Rm. 239 Boys Lavatory	C3	D75	S	075	ND	ND	NO
D76	Rm. 240 Girls Lavatory	C1	D76	S	076	ND	ND	NO
D77	Rm. 240 Girls Lavatory	C2	D77	S	077	ND	ND	NO

ASBESTOS | LEAD | MOLD | HAZMAT

ENVIRONMENTAL CONSULTANTS

877 466 4429

346 AUSTIN STREET **BUFFALO** NEW YORK 14207 | 716 833 2929 FAX 716 833 9292

4 COMMERCIAL STREET, LL **ROCHESTER** NEW YORK 14614 | 585 783 1465 FAX 585 783 1466

Sample #	Room Name	Wall ID	Outlet #	Outlet Type	Lab ID	Result (mg/L)	Result (ppb)	Exceeds Limit
D78	Rm. 240 Girls Lavatory	C3	D78	S	078	ND	ND	NO
D79	Rm. 241A Faculty Lavatory	B	D79	S	079	0.00245	2.45	NO
D80	Rm. 128 Faculty Room	C	D80	S	080	0.00208	2.08	NO
D81	Rm. 111	A	D81	S	081	0.00762	7.62	NO
D82	Rm. 112	C lower	D82	S	082	0.01210	12.10	NO
D83	Rm. 112	C upper	D83	S	083	0.01310	13.10	NO
D84	Rm. 103 Cafeteria	C	D84	DF	084	ND	ND	NO
D85	Rm. 104 Kitchen	B	D85	Sprayer	085	0.00174	1.74	NO
D86	Rm. 104 Kitchen	B	D86	Hose	086	0.00230	2.30	NO
D87	Rm. 104 Kitchen	B	D87	Dish Sink	087	0.00482	4.82	NO
D88	Rm. 104 Kitchen	C	D88	Pot Filler	088	0.02570	25.70	YES
D89	Rm. 104 Kitchen	C	D89	Hose	089	0.00440	4.40	NO
D90	Rm. 104 Kitchen	C	D90	Steamers	090	0.04380	43.80	YES
D91	Rm. 104 Kitchen	C	D91	Prep Sink	091	0.00861	8.61	NO
D92	Rm. 104 Kitchen	C	D92	Prep Sink	092	0.00236	2.36	NO
D93	Rm. 103D Kitchen Staff Lavatory	B	D93	S	093	0.01960	19.60	YES
D94	Girls Phys Ed. Office Lavatory	C	D94	S	094	0.04020	40.20	YES
D95	Girls Locker Rm. (old)	C	D95	DF	095	ND	ND	NO
D96	Girls Locker Rm. (old)	C	D96	T	096	0.00581	5.81	NO
D97	Boys Phys Ed. Office Lavatory	C	D97	S	097	0.00888	8.88	NO
D98	Boys Locker Room (old)	C	D98	DF	098	ND	ND	NO
D99	Boys Locker Room (old)	A	D99	T	099	ND	ND	NO

Sample #	Room Name	Wall ID	Outlet #	Outlet Type	Lab ID	Result (mg/L)	Result (ppb)	Exceeds Limit
D100	Rm. 309 Concession Stand	C	D100	S	100	ND	ND	NO
D101	Rm. 308 Ladies Lavatory	A1	D101	S	101	ND	ND	NO
D102	Rm. 308 Ladies Lavatory	A2	D102	S	102	ND	ND	NO
D103	Rm. 308 Ladies Lavatory	A3	D103	S	103	ND	ND	NO
D104	Rm. 308 Ladies Lavatory	A4	D104	S	104	ND	ND	NO
D105	Rm. 307 Mens Lavatory	C1	D105	S	105	0.00427	4.27	NO
D106	Rm. 307 Mens Lavatory	C2	D106	S	106	0.00557	5.57	NO
D107	Rm. 307 Mens Lavatory	C3	D107	S	107	0.00470	4.70	NO
D108	Rm. 307 Mens Lavatory	C4	D108	S	108	ND	ND	NO
D109	Track Spigot	n/a	D109	n/a	109	0.00264	2.64	NO

Key:

Sample #: Sample ID

Wall ID: Unique wall location utilizing HUD identification protocol A, B, C or D

Outlet #: same as sample ID

Outlet Type: S-Sink, DF-Drinking Fountain, T-Trough Sink